

Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377









Friday, December 26, 2008
Inspector
Tony Marino
727-433-2613
tony@npimarino.com
ASHI Certified

" Independently Owned and Operated "

Inspection Date : Inspector: Tony Marino 12/26/2008 Inspector Phone:

727-433-2613

Email or Web Site: tony@npimarino.com

ASHI Certified

©1996-2008 Page 1 of 35



## Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377

**INVOICE #: TEMPLATE** 

Inspection Date: 12/26/2008 10:00 AM

National Property Inspections of Southern Pinellas County

Payment Method: Personal Check

dba National Property Inspections

Clearwater FL

Paid

Client Name : Ronald Bullard
Property Location : 1300 S. 6th. St. N.

St. Petersburg FL 33377

Billing Address:

1877 Pirate Cove Lane

St. Petersburg FL 33777

Client Phone:

(555)555-5555

Client Email:

TYPE OF INSPECTIONS PERFORMED

| Home Inspection | \$275.00 | | Infrared scan | \$50.00 | | Subtotal | \$325.00 |

Total \$325.00

Grand Total (Due Upon Receipt) \$325.00

**Listing Agent Information** 

Agent: Andrew Duncan Agency: Keller Williams Realty

Email: Address:

Work #: (813) 739-5948 Cell #: (727) 742-2875

Fax #:

FL

Pager #:

" Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino Email or Web Site: tony@npimarino.com

12/26/2008 Inspector Phone: ASHI Certified 727-433-2613

©1996-2008 Page 2 of 35



### Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377

\*The summary is not the entire report. The complete report may include additional information of concern to the buyer. Any/all photos included are considered to be part of the summary/report. Cosmetic issues are not part of the general home inspection. Trees are not part of the general home inspection unless these are likely to adversely affect the building. Some/all electrical outlets, HVAC vents, and windows may not be tested due to access being denied by furniture or personal belongings of the current home owner in all rooms. Stored items restrict viewing of all closet interior and sink areas.

\*All recommendations and/or referrals within this Inspection Report for repair, replacement, and/or evaluation stated in the specific sections of this report are recommended to be completed by specifically licensed contractors with respect to the individual component being addressed for repair, replacement or evaluation prior to the close of escrow.

" Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino

12/26/2008 Inspector Phone:

Email or Web Site: tony@npimarino.com

**ASHI** Certified

727-433-2613

©1996-2008 Page 3 of 35



Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377

GEN	ERAL INF	ORN	ΛAΊ	IION						
GEN	ERAL CON	DITI	ONS	S AT TIM	1E OF I	NSPECTION	:			
Estimate Type of	y Occupied : ed Age Of Property Property : Construction :	No : 10 ☑ Si		□ Multi ☑ Block	□ Brick	Property Faces :   Weather :   Soil Conditions :   Persons Present :	Sunny ☑ Dry	□ Damp	Temperatu	□ Frozen
☑ Othe	r: Stucco/vinyl sid	ling								
	INITIONS:  are listed the defini	itions us	sed thr	oughout the	report to d	escribe each feature	of the pro	operty.		
ACC	(ACCEPTABLE	Ε)	The it	tem/system wa	s performing	its intended function at	the time of	of the inspe	ction.	
MAR	(MARGINAL)		inspec			acceptable. (It perforn and/or deterioration, it				
NI	(NOT INSPECT	TED)	The it	*		ed due to safety concern	inacces	sibility and	or concealn	nent or
NP	(NOT PRESEN	T)	The it	tem/system do	es not exist o	r was visually concealed	d at the tin	ne of the ins	spection.	
DEF	(DEFECTIVE)			tem/system fai s hazardous at		e/perform its intended fune inspection.	unction, w	as structura	lly deficient	, was unsafe
National such as, is sugged The follocarefully Propert Scope	unclogging drains sted that you budg owing report is base y. The following iter y was not occupi	tions wis s, servic get for r ed on visu ms may l ed at tir does no	shes to ing of regular ual insp be of sp me of i	o remind you furnaces, air maintenance pection only or pecial interest.	conditione e/repairs. f the accessi	perty requires a certairs, water heaters, etc ble areas of this proper rity, cable TV or tele	c. This p	roperty w	ill be no ex	ception. It

#### " Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino Email or Web Site: tony@npimarino.com

Inspector Phone: 12/26/2008 **ASHI** Certified 727-433-2613

\*Client opted to have a limited infrared thermal scan performed.

Page 4 of 35 ©1996-2008



	Ronald	d Bu	llard, 1300 S. 6th.	St.	N., St. P	Petersburg, FL, 33	377				
G	RADING / DRAINAG	E				Monitor Condition	ACC	MAR	NI	NP	DEF
						<b>Recommend Repairs</b>	$\square$				
	Near Level	V	Positive Slope		Negative S	lope $\square$	Pond	ing			•
Co	mments :										
DI	RIVEWAY						ACC	MAR	NI	NP	DEF
						Recommend Repairs	Ø				
✓	Concrete		Asphalt		Brick		Grave	el			
	General Deterioration		Cracks		Settlement						
Co	mments :										
W	ALKS / STEPS					Monitor Condition	ACC	MAR	NI	NP	DEF
						<b>Recommend Repairs</b>	Ø				
V	Concrete   Flagstone		Brick	1							,
	General Deterioration Poor Earth / Wood Clearance		Handrail Loose / Missing		Cracks / Se	ettlement	Tripp	ing Haz	ard		
	mments :										
_ P(	ORCHES / STOOPS					Monitor Condition	ACC	MAR	NI	NP	DEF
						<b>Recommend Repairs</b>	$\square$				
	Enclosed	V	Open								•
	General Deterioration		Settlement		Poor Earth	/ Wood Clearance	Hand	rail Loo	se / N	Aissii	1g
Co	mments :										
PA	ATIO				☑	Monitor Condition	ACC	MAR	NI	NP	DEF
						Recommend Repairs		V			
	Concrete		Flagstone		Brick						
	General Deterioration		Cracks		Settlement		Slope	s Towa	rd Ho	use	
Co	mments: Ceiling fan opera	ationa	al at time of inspection								
	view of the deck Screen enclosur	shov e ap	ved it to be in good cor	nditio	on, though.	ected due to not inspe ough one panel at west				t	
			" Independently	Own	ed and Ope	rated "					
	pection Date : Inspector: T 26/2008 Inspector Ph		<b>I</b> arino			or Web Site: tony@npimar	rino.co	m			
12/	26/2008 Inspector Ph		727-433-2613		ASHI	Certified					

©1996-2008 Page 5 of 35



## Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377



ROOTING						ACC	MAR	NI	NP	DEF
				☐ Recommend Repair	rs		Ø			
: 10 Ye	ear(s) De	sign Life : <b>17-20</b>	Year(s)	Layers: 1		10	<b>)0</b> % Vi	sible		
Visual From Gro						☐ Snow Covered				
Asphalt / Compos	sition $\square$	□ Wood Shake □ Wood Shingle □								
Tar and Gravel		☐ Metal ☐ Rolled Composition ☐			Slate					
Membrane										
Suspected Leak(s	s) 🗹	Missing Shingle(s)		Cupping/Curling/Lifting/Brittle		Previo	us Rep	airs N	loted	
□ Excessive Granular Loss □ Bubbling □ Trim Trees / Branches			Trim Trees / Branches		Improj	per Inst	allati	on		
	Visual From Gro Asphalt / Compos Tar and Gravel Membrane Suspected Leak(s	Tar and Gravel  Membrane  Suspected Leak(s)  De  Year(s)  De  Means and Ground  Membrane  De  De  Membrane  De  De  De  De  De  De  De  De  De	Visual From Ground	Tar and Gravel  Membrane  Suspected Leak(s)  Design Life: 17-20 Year(s)  Walked On  Wood Shake  Metal  Metal  Missing Shingle(s)  □  Missing Shingle(s)	Recommend Repair  10 Year(s) Design Life: 17-20 Year(s) Layers: 1  Visual From Ground	Recommend Repairs  10 Year(s) Design Life: 17-20 Year(s) Layers: 1  Visual From Ground	Recommend Repairs  10 Year(s) Design Life: 17-20 Year(s) Layers: 1  Visual From Ground	Recommend Repairs   □   ⊠	Recommend Repairs   □ □ □ □ □	Recommend Repairs

Comments: Leaks not always detectable.

Dimensional asphalt shingle roof, roof materials show to be properly secured. All roof penetrations appear in good condition and properly sealed.

The roof was in generally good condition with the following issues noted:

There are 2 areas at the n/w corner that show wear. Most likely caused by the palm tree branches that over hang this section of roof. The limbs have already been trimmed and are not an issue. Would recommend having these small areas of shingles replaced to avoid water intrusion.

Recommend further evaluation and repairs by a licensed roofing contractor.

" Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino Email or Web Site: tony@npimarino.com

12/26/2008 Inspector Phone: ASHI Certified 727-433-2613

©1996-2008 Page 6 of 35



## Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377





							1 7		1	Y	1	
FLA	ASHING/VALLEYS	5				Monitor (	Condition	ACC	MAR	NI	NP	DEF
						Recomme	nd Repairs	Ø				
Ø N	Metal		Composition / Membrane	;								
] (	General Deterioration		Rust		Improper Ir	nstallation		Suspe	cted Le	ak(s)		
□ F	Exposed Nails		Previous Repairs Noted		Filled with	Debris						
Comr	nents: Metal flashing a viewable.	around	I perimeter of eaves pr	rope	rly installed	l. Flashinç	g in valleys is	covere	ed and	d not	İ	
SKY	YLIGHTS				✓	Monitor	Condition	ACC	MAR	NI	NP	DEF
						Recomm	end Repairs		V			
<b></b> Fi	ixed / Stationary		Operable									
⊐ Sι	uspected Leak(s)		Caulking Needed		Fogged		Cracked					
Comr	Skylight is fogg at bathroom ce		t appears in good cond	ditior	and prope	erly sealed	d. No water st	ains n	oted I	belov	V,	

fogged skylight

727-433-2613

#### " Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino

12/26/2008 Inspector Phone:

Email or Web Site: tony@npimarino.com

ASHI Certified

©1996-2008 Page 7 of 35



	Ronal	d Bu	ıllard, 1300 S. 6th	. St.	N., St. P	etersburg	, FL, 33	377				
Gl	UTTERS/DOWN SPO	UTS	5			Monitor Con	dition	ACC	MAR	NI	NP	DEF
						Recommend :	Repairs				Ø	
	Aluminum		Copper		Steel	□ Vinyl						
$\checkmark$	Missing		Rust / Corroded		Leaking	☐ Loos	se					
	Filled with Debris		Misaligned		Missing Ext	tension / Splash	Block					
Coı	mments: Recommend ad	ding	gutters to home to kee	ep wa	ater away fr	om the found	dation.					
EX	XTERIOR SURFACE				[	✓ Monitor C	ondition <b>E</b>	Reco	ommen	d Re	pairs	
								ACC	MAR	NI	NP	DEF
SID	DING/TRIM								Ø			
EX	TERIOR FAUCETS							Ø				
EX	TERIOR ELECTRICAL OUTI	LETS	□ NO GFCI					Ø				
EX	TERIOR LIGHTING							Ø				
$\checkmark$	Wood	$\checkmark$	Metal	$\checkmark$	Vinyl		Stucco					
	Synthetic Stucco		Composite		Veneer		Brick					
	General Deterioration		Needs Paint		Missing / Lo	oose 🗹	Cracked					
V	Needs Caulk / Seal		Poor Earth / Siding Clea	rance								
Coi			rds are in good condit s and outlets are oper		al.							

Body of home is stucco over cement block with wood fascia and soffit boards. Vinyl siding at rear gable.

Stucco siding is in generally good condition but has minor hairline cracks at most walls. Also, at the s/e corner at grade, there is a small damaged area and metal corner bead is exposed. Recommend having professionally sealed/repaired and monitoring over time.

Outlet at rear wall is missing its protective cover. Recommend replacing with pool nearby.

" Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino Email or Web Site: tony@npimarino.com

12/26/2008 Inspector Phone: ASHI Certified


727-433-2613

©1996-2008

Page 8 of 35



## Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377









WINDOWS		☐ Monitor Condition	ACC	MAR	NI	NP	DEF
		☐ Recommend Repairs	Ø				
□ Wood	Vinyl	Metal					
☐ Insulated Panes	Single Pane	Window Wells					
☐ General Deterioration	Needs Caulk / Seal	Defective / Damaged Storm Windows					
□ Needs Paint / Finish	Fogged	Painted Shut					
	I windows present a	•					

All locks operational.

#### " Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino Email or Web Site: tony@npimarino.com

Inspector Phone: 12/26/2008 ASHI Certified 727-433-2613

Page 9 of 35 ©1996-2008



## National Property Inspections of Southern Pinellas County

Į		<b>L</b>	db	a National	Pro	perty	Inspection	IS					
		Ronal	d Bu	ıllard, 1300 S.	6th. S	. N., S	t. Petersburg, F	L, 33	377				
EX	KTERI	OR DOORS					☑ Monitor Condition		ACC	MAR	NI	NP	DEI
_							☑ Recommend Rep	airs		Ø			
	Wood	☑ Metal		Vinyl	Fibergl		☑ Glass		S 1 11		,.		
$\square$		Deterioration  Storm Door Damage	.d 🗆	Delaminated / Dama Evidence of Leak(s)	-		g / Damaged Hardware Replace Weather-Strip		Doorbell Needs C	-			
		both-sides" type	have lock of fro	for safety. Int entry door frame			owever recommend repairs by a license				keye	ed-	

FC	OUNDATION				☐ Monitor Condition	n	A	CC	MAR	NI	NP	DEF
					☐ Recommend Rep	airs				Ø		
	Concrete Block	$\overline{\checkmark}$	Concrete	$\checkmark$	Slab		Post	/ Pi	er			
	Brick		Stone		Wood		Sub-	-Gra	de Entry	yway		
	General Deterioration		Horizontal Cracks		Step Cracks		Vert	ical	Cracks			
V	Limited Observation		Needs Caulk / Seal		Trim Vegetation							
Cor	nments: No visibility due to	de	sign or landscaping.									

" Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino Email or Web Site: tony@npimarino.com

Inspector Phone: 12/26/2008 **ASHI** Certified 727-433-2613

Page 10 of 35 ©1996-2008



Ronald	Bullard, 1300 S. 6th	. St. N., St. Petersburg, FL, 33	377			
GARAGE/CARPORT		☐ Monitor Condition	□ R	ecomm	end Re	pairs
✓ Attached □ Detached	□ Carport					
☐ One Car ☑ Two Cars	☐ Three or More Cars		ACC	MAR	NI N	P DEF
FLOOR/WALLS/CEILING/ELECTI	RICAL		$\square$			]
ROOF						<b>Z</b>
SIDING/TRIM						<b>Z</b> 🗆
☐ General Deterioration	☐ Settlement / Movement	☐ Obscured / Limited View		Cracked		
☐ Outlets NOT GFCI Protected	☐ Electrical Deficiencies					
Comments: Garage is in gene	rally good condition.					
OVERHEAD GARAGE I	DOORS	☐ Monitor Condition	ACC	MAR	NI N	P DEF
# of Openers: 1	DOORS	☑ Recommend Repairs				
□ Wood	☑ Metal	☐ Fiberglass				
☐ General Deterioration	☐ Loose Track	✓ Repair / Replace Weather-Stripping				
_	☐ Damaged / Inoperative	☐ Repair / Adjust Automatic Reverse				
Wall opener does Weather stripping Recommend repa						

Attic / Roof

Method of Inspection

Physical Entry

☐ Visual from Access

☑ No Access / Limited View

50 % Visible

" Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino Email or Web Site: tony@npimarino.com

12/26/2008 Inspector Phone: ASHI Certified

727-433-2613

Page 11 of 35



# National Property Inspections of Southern Pinellas County

	1 <sub>®</sub>	dba	<b>National</b>	Prop	perty Inspections		
	Rona	ld Bull	ard, 1300 S. 6	th. St.	N., St. Petersburg, FL,	333′	77
ATTIC /	ROOF FRAN	/ING/S	HEATHING		<ul><li>☐ Monitor Condition</li><li>☐ Recommend Repairs</li></ul>	A	ACC MAR NI NP DEF
<ul><li>✓ Trusses</li><li>□ Broken</li></ul>	s Rafters / Trusses		Cafters Deflection		Plywood / Panel Board / Boards Water Stains / Suspected Leak(s)		Delaminated
	Only one acce	50% of a ss openir thing is C	attic area was ablung and limited according and limited according particle board metal roof straps	cess du			

#### ☐ Monitor Condition ATTIC / ROOF VENTILATION ACC MAR NI NP DEF ☐ Recommend Repairs $\overline{\mathbf{V}}$ Gable □ Ridge $\overline{\mathbf{Q}}$ Soffit ☐ Static Vent ☐ Turbine Powered Vent Attic Fan Whole House Fan □ No Venting ☐ Additional Vents Needed ☐ Obstructed Air Flow ☐ Clothes Dryer / Exhaust Fans Vented Into Attic

Comments: Roof vents also installed.



Independently Owned and Operated '

Inspection Date: Inspector: Tony Marino Email or Web Site: tony@npimarino.com

Inspector Phone: 12/26/2008 **ASHI** Certified

727-433-2613

Page 12 of 35



	Ronald	Bullard, 13	00 S. 6	oth. St.	N., St. P	etersburg	g, FL, 33	377				
ATTIC / F	ROOF INSULA	TION				Monitor Con	dition	ACC	MAR	NI	NP	DEF
						Recommend	Repairs	Ø				
☑ Loose Fil	1	□ Blanket			Missing		□ Uneve	n Distri	bution			
ATTIC E	Blown fiberglass	nsulation prese	ent; app	ears in g		Monitor Cond Recommend F		ACC	MAR	NI	NP □	DEF
☐ Open Spl	ices / Junction Boxes											
Comments : Foundat	Limited visibility due Limited view of at order.							appear	ed in (	3000	t	
F ounaai Foundatio		□ Basement		Crawl Sp	pace 5	Z Slab On G	rade					
FOUNDA	TION FRAMI	NG SUPPOR	T					ACC	MAR	NI	NP	DEF
	Deterioration Observation No visibility of frai	☐ Horizontal (☐ Leaning / Bo	owing	□ □ nished wa	Step Cracks Inadequate		□ Vertic	al Craclescence				
		" In	depende	ently Owne	ed and Ope	rated "						
Inspection Dat 12/26/2008	te: Inspector: To Inspector Pho	ny Marino	-		Email	or Web Site: t Certified	ony@npimar	rino.con	n			

©1996-2008 Page 13 of 35



Ro	nald Bu	ullard, 1	300 S. 6th	. St	. N., St. P	etersburg, I	FL, 33	377				
FOUNDATION FLO	OR/SL	AB				Monitor Condit		ACC	MAR	NI	NP	DEF
						Recommend Re	pairs					
☑ Concrete		Wood										
□ Settlement		Cracks			Differential		Ø O	bscure	d / Cov	ered		
Comments: Limited/no v	isibility o	f concrete	slab due to f	loor	covering.							
ELECTRICAL						☐ Monitor Cor	dition	☑ Re	comme	nd R	epair	rs
SERVICE SIZE (Main Pa	nel)											
□ 110 Volt (Nominal)		110 / 220	Volt (Nominal)	$\overline{\checkmark}$	120 / 240 V	olt (Nominal)	60 Am	р		100	Amp	p
□ 125 Amp		150 Amp	( ,		200 Amp		Undete	-	d			
		•			•							
SERVICE SIZE (Sub Pa	nel)											
☑ 40 Amp		60 Amp			100 Amp		Undet	ermine	d			
SERVICE		Overhead	✓ Undergro	ound				ACC	MAR	NI	NP	DEF
ENTRANCE CABLE	<u> </u>	Aluminum	Copper									
PANEL	<u> </u>	Breaker(s)	Fuse(s)		Combinat	ion						<u> </u>
SUB-PANEL	<u> </u>	Breaker(s)	Fuse(s)		Combinat	ion						
BRANCH CIRCUITS		Solid Aluminum	☑ Copper									
BONDING/GROUNDING												
GFCI(IN PANEL)*  ARC FAULT											<u>a</u>	
SMOKE DETECTORS*												<u> </u>
Overfused		Double Tap	ninα		Rust / Corrosi	ion			ficient A			IV.
☐ Looses Connections		No Main Di				ers Incorrectly Size			heating			n or
☐ Improper Splices		Open Knocl				Not Jumpered	.u		oper Gr		TCIIII	1g
*Smoke Detection Main electrical No defects  Smoke detection	cal service noted in rectors are nastwer	I's checked vee panel is main service	vith test button located ce panel or s	only. ub p	Monthly Testoral	ed with canned nily room was i		; oper	ated			
Inspection Date : Inspec	or: Tony l		ndependently	Owr		rated "						

©1996-2008 Page 14 of 35

**ASHI** Certified

Inspector Phone:

727-433-2613

12/26/2008



## Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377





PLUMBING	☐ Monitor Condition ☐ Recommend Repairs
Water Service : ☑ Water Public □ Water Private □ Water Off	Water Shut Off Location: West wall
<b>Sewage Service :</b> ☑ Sewage Public □ Sewage Private □ Fuel Off	
	ACC MAR NI NP DEF
SUPPLY	
DRAINS   ☑ PVC  ☐ Cast Iron  ☐ Copper  ☐ ABS	
EJECTOR PUMP	
VENTS	
☐ General Deterioration ☐ Improper Connections ☐ Low Flo	w
☐ Missing / Improper Cleanouts ☐ Suspected Leak(s) ☐ Improper	r Venting

Comments: Main utility line, septic systems and gray water systems are excluded from this Inspection.

Main water shut-off is located at the west wall.



#### " Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino Email or Web Site: tony@npimarino.com

12/26/2008 Inspector Phone: ASHI Certified

727-433-2613

©1996-2008 Page 15 of 35



## Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377

	□ Recommend Repairs □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □						
	Size: 55 Gallons						
Ass. 12 No. (c) Design Life : 10.15							
Age: 12 Year(s) Design Life: 10-15	Year(s)						
☐ Gas ☑ Electric ☐ Oil ☐ Solar ☐ Integra	ral with Boiler						
$\square$ Leaks $\square$ Rust / Corrosion $\square$ Improp	pper Elevation   Insulation Blanket Obstructs View						
$\square$ Gas Leak $\square$ Faulty Flue Connection $\square$ At or N	Near Design Life ☐ Beyond Design Life						
☐ Missing / Improper Pressure Relief Valve / Extension ☐ Seismically Strapped							

Water heater located in the GARAGE.

Electric & gas water heater design lives are 10-15 years, depending on quality of water.

Water heater operational at time of inspection.



" Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino Email or Web Site: tony@npimarino.com

Inspector Phone: 12/26/2008 **ASHI** Certified

727-433-2613

Page 16 of 35 ©1996-2008



## Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377

LAUNDRY FACILITIES   Monitor Condition  Recommend Repairs							
Location: Utility room		ACC	MAR	NI	NP	DEF	
UTILITY HOOKUPS ☐ Gas (Dryer) ☑ Electric (Dryer)			Ø				
DRYER VENTS						Ø	
LAUNDRY TUB		Ø					
DRAIN		$\square$					

Comments: Electrical connections wired properly.

Washer & dryer were operational at time of inspection but are rated marginal due to age. Monitor condition.

Dryer missing control knobs.

Recommend repairs as needed.

Dryer vent can only be inspected from unit to wall; hose in good condition but is slightly detached at roof sheathing. Lint is being distributed into attic area. Recommend having line professionally cleaned for safety purposes.

Recommend changing black rubber hoses on washer to 1-piece braided hoses, which are burst proof.





" Independently Owned and Operated "

Inspection Date : Inspector: Tony Marino Email or Web Site: tony@npimarino.com

12/26/2008 Inspector Phone: ASHI Certified 727-433-2613

©1996-2008 Page 17 of 35



Ronald Bullard,	1300 S.	6th. St.	N., St.	Petersburg,	FL, 33377

HE	ATING				☐ Monitor Condition	□ Rec	comme	nd Re	epair	s
Brai	nd: Nordyne		Model: B3BV036KBB		BTUs:					
A	ge: 5 Year(s)	Desig	gn Life: 15 Yo	ear(s)		ACC	MAR	NI	NP	DEF
OPE	RATION					V				
ABO	VE GROUND STORAGE TA	NKS								
HUN	IIDIFIER								Ø	
<b>7</b>	Forced Air	$\overline{\checkmark}$	Heat Pump		Boiler / Hot Water	□ Stea	ım			
	Baseboard / Radiant		Gravity							
	Gas	$\checkmark$	Electric		Oil	□ Proj	pane			
	Air Source		Water Source							
	Rusted Heat Exchanger		Unusual Flame Pattern		Too Warm to Test	□ Shu	t Down	For S	Seaso	n
	Corroded / Leaking		At or Near Design Life		Beyond Design Life					
	Improper Temperature Rise		Needs Normal Maintenan	ice / C	Cleaning					
	Missing / Improper Pressure I	Relief	Valve Leaks		Underground Storage Tank Not Part of	f Inspec	tion			
Com	ments: Heat Exchanger - U	Inable	to detect cracks/holes with	out di	smantling unit.					

\*A "split-system" air conditioner is actually a single unit split into two sections, an air handler indoors and a condensing unit outdoors. These units act as one, so therefore, if one of the units is not maintained properly or is in disrepair, it may damage the other unit.



<b>DRAFT CON</b>	TROL/VENT			☐ Monitor Condition	ACC	MAR	NI	NP	DEF
				☐ Recommend Repairs				Ø	
☐ Metal Pipe		PVC							
☐ Negative Slope		Improper Size		Inadequate Flue Clearance					
☐ Obstruction		Loose Connection		Inadequate / Marginal Combustion Air					
□ Leaks		Improper Connection		Excessive Corrosion / Perforation					
Comments:									
		" Independer	ntly Ow	ned and Operated "					
Inspection Date:	Inspector: Tony	Marino		Email or Web Site: tony@npima	rino.co	m			
12/26/2008	Inspector Phone:	727-433-2613		ASHI Certified					

©1996-2008 Page 18 of 35



### Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377

H	EATING DISTRIBU	TION				☑ Monitor Condit	ion 🗆	Rec	ommer	ıd Re	epairs	S
								ACC	MAR	NI	NP	DEF
DIS	STRIBUTION								Ø			
BL	OWER						Ø					
CONTROLS/THERMOSTAT (CALIBRATIONS/TIMED FUNC					NS NO	T CHECKED.)		V				
CII	RCULATOR PUMP										Ø	
$\overline{\checkmark}$	Ductwork		Radiators		Bas	eboard						
	Rusted			Cru	shed / Disconnected Ducts		Noi	sy Blov	ver			
	☐ Air Leaks Noted at Plenum / Duct Joints					Circulator Pump Leaking / Noisy / Inoperable						

#### Comments:

Dirty filter(s) present which are a source of increased operating costs and poor cooling system operation. Missing/dirty air filters can:

- Reduce air flow to the building [dirty filters].
- Cause excessive dirt build-up inside the air handler cabinet & on motor and fan blades, and inside the duct system, leading to mold or allergen problems in a building and to the need for more costly duct cleaning or replacement.
- Recommend replacing as soon as possible.



#### " Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino Email or Web Site: tony@npimarino.com

12/26/2008 Inspector Phone: ASHI Certified

727-433-2613

Page 19 of 35



	Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377													
AI	R CONDITIONER				☐ Monitor Condition	A	.CC	MAR	NI	NP	DEF			
					☐ Recommend Repairs		Ø							
Bı	and: Nordyne		Model: JT5BD036K		Size: 3 TONS	,								
	Age: 1	Desi	gn Life: <b>10-12</b>											
	OPERATION													
$\checkmark$	Electric		Gas											
$\checkmark$	Central		Wall		Evaporative Cooler									
	Noisy Fan / Compressor		Outside Unit Not Level		Outside Temp Too Cold to Test		Dirt	y/Dam	aged	Cond	lenser			
	No Pad Under Unit		No Outside Disconnect		Remove Obstructions / Vegetation		Rus	t / Corr	osior	1				
	At or Near Design Life		Beyond Design Life		Missing/Improper Condensate Line									
	Window Units Not Inspected		Damaged Suction Line		Suspected Leak(s) / Clogged Conde	ensate								
	Temperature Differential Not	Withi	n Industry Standards		Needs Normal Maintenance / Cleani	ing								

Comments:

\*Cooling system inspection limitations: We check for normal temperature differential between input and output air, unusual operating noises, visible damage or defects, and a variety of other possible defects. This inspection is not technically exhaustive. A more thorough inspection, can be performed by a qualified HVAC service professional, and is recommended when any defects or malfunctions are suspected.

\*Heat pump should not be tested in the cool mode with the exterior temperature below 65 degrees; tested in heat mode.

\*System is operational; temperature differential is within industry standards.



#### " Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino Email or Web Site: tony@npimarino.com

12/26/2008 Inspector Phone: ASHI Certified

727-433-2613

Page 20 of 35



### Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377

KITCHEN	S/TRIM						ıd Re	d Repairs		
					ACC	MAR	NI	NP	DEF	
CEILINGS	☐ Typical Ci	rack(s)			Ø					
WALL(S)	☐ Typical Cı	rack(s)			Ø					
WINDOWS/TRIM	☐ Evidence	of Leak(s)	,	☐ Fogged	V					
WINDOW SCREENS	☐ Missing	☐ Damaged			Ø					
FLOOR/FINISH					V					
INTERIOR DOORS/HARDWARE					Ø					
ELECTRICAL (RANDOM SAMPLING OF OUTL	ETS, SWITCI	HES, FIXTURES.)			Ø					
GFCI PROTECTION (CHECKED WITH TEST B	UTTON ONL	Y. MONTHLY TES	T RE	COMMENDED.)	$\square$					
HEAT/AIR DISTRIBUTION					Ø					
COUNTERTOPS/CABINETS						Ø				
SINK/FAUCET					Ø					
EXHAUST FAN						V				
STOVE TOP/OVEN	☐ Gas	✓ Electric			$\square$					
STOVE ANTI-TIP BRACKET					$\square$					
WATER PRESSURE/FLOW/DRAINAGE					$\square$					
DISHWASHER/CROSS FLOW PROTECTION	☐ Leaking S	eal Clogged Di	rain		$\square$					
REFRIGERATOR					Ø					
MICROWAVE					Ø					
GARBAGE DISPOSAL	☐ Seized	☐ Noisy		☐ Improper Elec. Connectio	n 🗹					

Comments:

Also includes the dinette.

FYI-exhaust fan does not vent to the outdoors.

Appliances show age but were operational. Refrigerator setting in freezer was off at start of inspection. Turned on and appeared to operate properly.

Water stains under sink did not show moisture when tested with a moisture meter. Appears a bottle of liquid has spilled. Monitor over time.

Recommend sealing countertop/backsplash connection behind faucet to avoid water intrusion.





#### " Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino

12/26/2008 Inspector Phone:

727-433-2613

Email or Web Site: tony@npimarino.com

**ASHI** Certified

Page 21 of 35



## Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377

FAMILY ROOM			V	<b>Monitor Condition</b>	□ Re	comm	end F	Repai	rs
					ACC	MAR	NI	NP	DEF
CEILINGS	Typical Crack(s)	Stain(s)				Ø			
WALL(S)	Typical Crack(s)	Stain(s)			Ø				
WINDOWS/TRIM	Evidence of Leak(s)	Inoperative		Fogged	Ø				
WINDOW SCREENS	Missing	Damaged			Ø				
FLOOR/FINISH						Ø			
INTERIOR DOORS/HARDWARE					V				
ELECTRICAL (RANDOM						Ø			
CLOSET/STORAGE								Ø	
HEAT/AIR DISTRIBUTION					V				
BUILT IN SHELVING					V				
WET BAR	No GFCI Protection							Ø	
MISCELLANEOUS								Ø	

Comments: Ceiling fan[s] operational at time of inspection.

Electrical outlet on floor is missing its protective cover. Recommend having added for safety purposes.

Carpeting shows its age; stains present.

Stains on ceiling at ac duct.





" Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino Email or Web Site: tony@npimarino.com

12/26/2008 Inspector Phone: ASHI Certified 727-433-2613

©1996-2008 Page 22 of 35



## Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377

MAIN BATHROOM			☑ Monitor Condition	□ Re	comm	end I	Repai	rs
				ACC	MAR	NI	NP	DEF
CEILINGS	Typical Crack(s)	Stain(s)		Ø				
WALL(S)	☐ Typical Crack(s)	Stain(s)		Ø				
WINDOWS/TRIM	Evidence of Leak(s)	☐ Inoperative	☐ Fogged	Ø				
WINDOW SCREENS	☐ Missing	☐ Damaged		V				
FLOOR/FINISH				Ø				
INTERIOR DOORS/HARDWARE				Ø				
ELECTRICAL (RANDOM SAMPLI	NG OF OUTLETS, SWITC	HES, FIXTURES.)		Ø				
GFCI PROTECTION (CHECKED V	VITH TEST BUTTON ONL	Y. MONTHLY TE	ST RECOMMENDED.)	V				
HEAT/AIR DISTRIBUTION				Ø				
COUNTERTOPS/CABINETS				Ø				
SINK/FAUCET	Leaking	☐ Cracked / Dama	nged		Ø			
TOILET	Loose at Base	Runs Continuou	ısly	Ø				
TUB/SHOWER				Ø				
JETTED TUB	☐ No Service Access	☐ No GFCI					Ø	
TILE WORK/ENCLOSURE				Ø				
EXHAUST FAN				V				
WATER PRESSURE/FLOW/DRAIN	IAGE			Ø				

Comments:

No bathtub/shower access panel present. No moisture detected at enclosure when read with a moisture meter.

GFCI outlets reset in garage.

Sink stopper is broken; no plug. Recommend repairs.



#### " Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino Email or Web Site: tony@npimarino.com

12/26/2008 Inspector Phone: ASHI Certified

727-433-2613

Page 23 of 35



## Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377

MASTER BEDROOM			☑ Monitor Condition	□ Re	comm	end F	Repai	rs
				ACC	MAR	NI	NP	DEF
CEILINGS	Typical Crack(s)	Stain(s)		Ø				
WALL(S)	☐ Typical Crack(s)	Stain(s)		Ø				
WINDOWS/TRIM	☐ Evidence of Leak(s)	☐ Inoperative	Fogged	Ø				
WINDOW SCREENS	Missing	☐ Damaged		Ø				
FLOOR/FINISH				Ø				
INTERIOR DOORS/HARDWARE				Ø				
ELECTRICAL (RANDOM SAMPLI	ING OF OUTLETS, SWITC	HES, FIXTURES.)		Ø				
GFCI PROTECTION (CHECKED V	VITH TEST BUTTON ONL	Y. MONTHLY TEST	Γ RECOMMENDED.)	Ø				
HEAT/AIR DISTRIBUTION				Ø				
COUNTERTOPS/CABINETS				Ø				
SINK/FAUCET	Leaking	☐ Cracked / Damage	ed	Ø				
TOILET	☐ Loose at Base	Runs Continuously	у	Ø				
TUB/SHOWER				Ø				
JETTED TUB	☐ No Service Access	☐ No GFCI					Ø	
TILE WORK/ENCLOSURE					Ø			
EXHAUST FAN				Ø				
WATER PRESSURE/FLOW/DRAIN	NAGE			V				

Comments:

Ceiling fan operational at time of inspection.

There are small cracks present in the grout near base of enclosure. A slightly elevated moisture content reading was found when read with a moisture meter. Recommend having grout repaired to avoid further water intrusion issues.



#### " Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino

12/26/2008 Inspector Phone:

727-433-2613

Email or Web Site: tony@npimarino.com

**ASHI** Certified

Page 24 of 35



## Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377

COMMON AREA AT ENTRY						☐ Recommend Repairs					
				ACC	MAR	NI	NP	DEF			
CEILINGS	Typical Crack(s)	✓ Stain(s)			Ø						
WALLS	Typical Crack(s)	☐ Stain(s)		Ø							
WINDOWS/TRIM	Evidence of Leak(s)	☐ Inoperative	☐ Fogged	Ø							
WINDOW SCREENS	Missing	☐ Damaged		Ø							
FLOOR/FINISH					Ø						
INTERIOR DOORS/HARDWARE				Ø							
CLOSET							Ø				
ELECTRICAL (RANDOM SAMPI	LING OF OUTLETS, SWITC	CHES, FIXTURES.)		Ø							
HEAT/AIR DISTRIBUTION				Ø							
FRONT BEDROOMS			☐ Monitor Condition	□ Re	comme	nd R	epair	rs			
				ACC	MAD	N.T.T	NID	DEF			
CEILINGS					MAR	NI	NP				
CEILINGS	Typical Crack(s)	Stain(s)		<b>✓</b>	MAK	NI 🗆					
WALLS	Typical Crack(s) Typical Crack(s)	Stain(s)  Stain(s)									
			☐ Fogged	Ø							
WALLS	Typical Crack(s)	☐ Stain(s)	☐ Fogged	<b>Ø</b>							
WALLS WINDOWS/TRIM	Typical Crack(s)  Evidence of Leak(s)	Stain(s)  Inoperative	☐ Fogged	<u> </u>							
WALLS WINDOWS/TRIM WINDOW SCREENS	Typical Crack(s)  Evidence of Leak(s)	Stain(s)  Inoperative	☐ Fogged	\[ \sqrt{1} \]							
WALLS WINDOWS/TRIM WINDOW SCREENS FLOOR/FINISH	Typical Crack(s)  Evidence of Leak(s)	Stain(s)  Inoperative	☐ Fogged	\[ \sqrt{2} \]							
WALLS WINDOWS/TRIM WINDOW SCREENS FLOOR/FINISH INTERIOR DOORS/HARDWARE	Typical Crack(s)  Evidence of Leak(s)  Missing	Stain(s) Inoperative Damaged	☐ Fogged	\ \forall \forall \forall \ \forall \foral							
WALLS WINDOWS/TRIM WINDOW SCREENS FLOOR/FINISH INTERIOR DOORS/HARDWARE CLOSET	Typical Crack(s)  Evidence of Leak(s)  Missing	Stain(s) Inoperative Damaged	☐ Fogged	\ \forall \for							
WALLS WINDOWS/TRIM WINDOW SCREENS FLOOR/FINISH INTERIOR DOORS/HARDWARE CLOSET ELECTRICAL (RANDOM SAMPI	Typical Crack(s)  Evidence of Leak(s)  Missing	Stain(s) Inoperative Damaged	☐ Fogged								
WALLS WINDOWS/TRIM WINDOW SCREENS FLOOR/FINISH INTERIOR DOORS/HARDWARE CLOSET ELECTRICAL (RANDOM SAMPI HEAT/AIR DISTRIBUTION	Typical Crack(s)  Evidence of Leak(s)  Missing	Stain(s) Inoperative Damaged	☐ Fogged								

" Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino Email or Web Site: tony@npimarino.com

12/26/2008 Inspector Phone: ASHI Certified

727-433-2613

Page 25 of 35



Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 333//														
MASTER BEDROOM   Monitor Condition  Recommend Repairs											·s			
							ACC	MAR	NI	NP	DEI			
CEILINGS			Typical Crack(s)	$\overline{\mathbf{A}}$	Stain(s)			Ø						
WALLS			Typical Crack(s)		Stain(s)		Ø							
WINDOWS/TR	RIM		Evidence of Leak(s)		Inoperative	ogged	Ø							
WINDOW SCR	REENS		Missing		Damaged		Ø							
FLOOR/FINIS	H						Ø							
INTERIOR DO	ORS/HARDWARE						Ø							
CLOSET						<u> </u>	Ø							
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)														
HEAT/AIR DIS	STRIBUTION						Ø							
	Carpeting shows it Stains on ceiling a		•											
LAWN SP	RINKLER				☐ Monitor Co		ACC	MAR	NI	NP	DEF			
# of Zones: 3					□ Recommen	d Repairs	Ø							
☑ Manual		□ Au	itomatic		Shut Down for Season					n Heads				
☐ General D	eterioration	□ Co	orrosion		l Leaks (Above Ground)    Apparent Unprof. Workman									
☐ Missing A	nti-Siphon Valve	□ Po	or Water Pressure/Flow		Defective / Missing Cross Connect Prevention									
;		erate			ode. May require sligh el in garage.	t adjustents	-							

No sprinklers in rear of home.



#### " Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino Email or Web Site: tony@npimarino.com

Inspector Phone: 12/26/2008 ASHI Certified

727-433-2613

Page 26 of 35



Comments:

## National Property Inspections of Southern Pinellas County dba National Property Inspections

## Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377

<b>SWIMMING POOL</b>	☑ Monitor Condition □ Recommend Repairs										
✓ In Ground		Above Ground		Winterized		Covered At Time Of In	nspection				
☑ Concrete		Plaster / Shotcrete		Vinyl		Fiberglass					
							ACC	MAR	NI	NP	DEF
SHELL/LINER/HARDCOAT									Ø		
HEATER		☐ Gas		☐ Electric		☑ Solar		Ø			
FILTER		☐ Cartridge		Diatomaceo	us Ear	rth 🔲 Sand			Ø		
PUMP(S)		☐ Leak(s)		☐ Noisy		☐ Inoperative			Ø		
ELECTRICAL		☐ Missing/Loose Bond	d	☐ Deteriorated	i				Ø		
LIGHTS		☐ Inoperative		☐ Loose Hous	ing				Ø		
GFCI (CHECKED W/TEST BUT	TON	ONLY).   Inoperative		Missing			☑				
CHILD SAFETY FENCE		☐ Incorrect Height								Ø	
CHILD SAFETY GATE		☐ Not Self Latching/Lo	ock							Ø	
DECK/APRON		☐ Settlement/Heaving	)	☐ Cracking		☐ Common Crack(s)			Ø		
□ Poor Control Access □ Broken/Missing Handrail □ Defective / Missing Ladder □ Defective/Missing Drain Cover(s)											

Pool has not been cleaned and was very dirty. Did not operate for fear of damaging the


components. The power to units was on and started during the inspection but was cut off as soon as it was noticed.

NOTE: Pool Bodies, Diving Boards, Slides, Self-Cleaning & Chlorinating Devices are beyond the scope of this inspection.

The solar panels on roof appear in good condition but one panel is "buckled" which will probably be damaged in high winds.

Recommend further evaluation and cleaning of all components by a qualified pool technician.





\*Lawn Sprinklers, Pools, Hot Tubs, and Spas are all high maintenance items requiring ongoing care. This inspection is a visual only of exposed/accessible areas and is intended to comment on the overall condition of system(s) at the time of the inspection. It should not be construed as any type of insurance policy, warranty, or guarantee.

" Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino Email or Web Site: tony@npimarino.com

12/26/2008 Inspector Phone: ASHI Certified 727-433-2613

©1996-2008 Page 27 of 35



Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377

## **Summary**

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

### **OVERHEAD GARAGE DOORS**

Garage door is operational. Electric eye for reverse function is operational.

Wall opener does not operate properly. May have an electrical short.

Weather stripping missing on one end of door.

Recommend repairs by a qualified overhead door specialist.





#### **EXTERIOR SURFACE**

Siding/Trim

Body of home is stucco over cement block with wood fascia and soffit boards. Vinyl siding at rear gable.

Stucco siding is in generally good condition but has minor hairline cracks at most walls. Also, at the s/e corner at grade, there is a small damaged area and metal corner bead is exposed. Recommend having professionally sealed/repaired and monitoring over time.

Outlet at rear wall is missing its protective cover. Recommend replacing with pool nearby.

727-433-2613

" Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino

12/26/2008 Inspector Phone:

Email or Web Site: tony@npimarino.com

ASHI Certified

©1996-2008 Page 28 of 35



## Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377









#### **EXTERIOR DOORS**

Exterior door[s] have sections of glass. Not a defect, however recommend changing lock to "keyed-both-sides" type lock for safety.

\*Decay at base of front entry door frame. Recommend repairs by a licensed contractor.



" Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino

12/26/2008 Inspector Phone:

Email or Web Site: tony@npimarino.com

**ASHI** Certified

727-433-2613

©1996-2008 Page 29 of 35



### Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377

#### **PATIO**

Patio directly surrounding the pool was not thoroughly inspected due to not inspection pool. The view of the deck showed it to be in good condition, though.

Screen enclosure appeared in generally good condition though one panel at west wall was torn at bottom. Recommend repairs as needed.



### **ROOFING**

The roof was in generally good condition with the following issues noted:

There are 2 areas at the n/w corner that show wear. Most likely caused by the palm tree branches that over hang this section of roof. The limbs have already been trimmed and are not an issue. Would recommend having these small areas of shingles replaced to avoid water intrusion. Recommend further evaluation and repairs by a licensed roofing contractor.





" Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino

12/26/2008 Inspector Phone:

Email or Web Site: tony@npimarino.com

**ASHI** Certified

727-433-2613

©1996-2008 Page 30 of 35



Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377

### **SKYLIGHTS**

Skylight is fogged but appears in good condition and properly sealed. No water stains noted below, at bathroom ceiling.



### **ELECTRICAL**

Smoke Detectors\*

Smoke detectors are not hardwired to home and were tested with canned smoke; operated properly in mastwer bedroom and front hall. Detector in family room was inoperable; recommend replacement..



" Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino

12/26/2008 Inspector Phone:

Email or Web Site: tony@npimarino.com

**ASHI** Certified

727-433-2613

©1996-2008 Page 31 of 35



Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377

#### **LAUNDRY FACILITIES**

Dryer Vents

Utility Hookups

Washer & dryer were operational at time of inspection but are rated marginal due to age. Monitor condition.

Dryer missing control knobs.

Recommend repairs as needed.

Dryer vent can only be inspected from unit to wall; hose in good condition but is slightly detached at roof sheathing. Lint is being distributed into attic area. Recommend having line professionally cleaned for safety purposes.

Recommend changing black rubber hoses on washer to 1-piece braided hoses, which are burst proof.





### **HEATING DISTRIBUTION**

Distribution

Dirty filter(s) present which are a source of increased operating costs and poor cooling system operation. Missing/dirty air filters can:

- Reduce air flow to the building [dirty filters].
- Cause excessive dirt build-up inside the air handler cabinet & on motor and fan blades, and inside the duct system, leading to mold or allergen problems in a building and to the need for more costly duct cleaning or replacement.
- · Recommend replacing as soon as possible.

" Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino Email or Web Site: tony@npimarino.com

12/26/2008 Inspector Phone: ASHI Certified 727-433-2613

©1996-2008 Page 32 of 35



### Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377



### **KITCHEN**

Countertops/Cabinets

Exhaust Fan

FYI-exhaust fan does not vent to the outdoors.

Appliances show age but were operational. Refrigerator setting in freezer was off at start of inspection. Turned on and appeared to operate properly.

Water stains under sink did not show moisture when tested with a moisture meter. Appears a bottle of liquid has spilled. Monitor over time.

Recommend sealing countertop/backsplash connection behind faucet to avoid water intrusion.





### **FAMILY ROOM**

Ceilings

Floor/Finish

Electrical (Random sampling of outlets, switches, fixtures.)

" Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino Email or Web Site: tony@npimarino.com

12/26/2008 Inspector Phone: ASHI Certified


727-433-2613

©1996-2008 Page 33 of 35



## Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377

Electrical outlet on floor is missing its protective cover. Recommend having added for safety purposes. Carpeting shows its age; stains present. Stains on ceiling at ac duct.





#### **MAIN BATHROOM**

Sink/Faucet

Sink stopper is broken; no plug. Recommend repairs.

#### **MASTER BEDROOM**

Tile Work/Enclosure

There are small cracks present in the grout near base of enclosure. A slightly elevated moisture content reading was found when read with a moisture meter. Recommend having grout repaired to avoid further water intrusion issues.



" Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino

12/26/2008 Inspector Phone: 727-433-2613

Email or Web Site: tony@npimarino.com

**ASHI** Certified

©1996-2008 Page 34 of 35



Ronald Bullard, 1300 S. 6th. St. N., St. Petersburg, FL, 33377

### **COMMON AREA AT ENTRY**

Ceilings

Floor/Finish

Carpeting shows its age; stains present.

Ceiling shows stains at ac ducts.

#### **MASTER BEDROOM**

Ceilings

Carpeting shows its age; stains present.

Stains on ceiling at ac duct.

### **SWIMMING POOL**


Heater

Pool has not been cleaned and was very dirty. Did not operate for fear of damaging the components. The power to units was on and started during the inspection but was cut off as soon as it was noticed. The solar panels on roof appear in good condition but one panel is "buckled" which will probably be

damaged in high winds.

Recommend further evaluation and cleaning of all components by a qualified pool technician.





MAR (MARGINAL)

The item/system was marginally acceptable. (It performed its designed function as of the time of the inspection. However, due to age and/or deterioration, it will likely require early repair or replacement.)

**DEF** (DEFECTIVE)

The item/system failed to operate/perform its intended function, was structurally deficient, was unsafe or was hazardous at the time of the inspection.

" Independently Owned and Operated "

Inspection Date: Inspector: Tony Marino

12/26/2008 Inspector Phone:

Email or Web Site: tony@npimarino.com

ASHI Certified

727-433-2613

©1996-2008 Page 35 of 35