# NPI.

# JDeeEn Inc. DBA

# **National Property Inspections**

Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999









Monday, January 1, 2001 Inspector J. William Naish 858.888.0848 j@npi-sd.com

**FOLK INN** 

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

## JDeeEn Inc. DBA

# **National Property Inspections**

Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

#### **GENERAL INFORMATION**

#### GENERAL CONDITIONS AT TIME OF INSPECTION:

Property Occupied: Yes  Estimated Age Of Property: 26 Year(s)  Property Faces: □ North □ South □ East ☑ West	Weather: ☑ Sunny	
Type of Property:  ☑ Commercial ☑ Hospitality/Hotel	Soil Conditions :  ☑ Dry  Persons Present :	
Primary Construction:  ☑ Wood	☑ Buyer's Agent	☑ Onsite Property Manager & Maintenance Person

#### **DEFINITIONS:**

Below are listed the definitions used throughout the report to describe each feature of the property.

Average to above-average condition for the building system evaluated, taking into consideration factors of age and design. Generally, other than normal maintenance, no repair is recommended or required.

F (FAIR)

Average condition for the building system evaluated, taking into consideration factors of age and design. Some short term or immediate maintenance or repairs are recommended to return the system to a good condition.

P (POOR)

Below-average condition for the building system evaluated, taking into consideration factors of age and design. Immediate repair, significant work or replacement is anticipated to return the building system to a good or fair condition.

NI (NOT INSPECTED)

The item/system was not inspected due to safety concerns, inaccessibility and/or concealment or seasonal conditions and no representations of whether or not it was functioning as intended were made.

NA (NOT APPLICABLE)

This item is not applicable or not present

#### **SCOPE OF THE INSPECTION:**

Building plans, maintenance records, building permits, drawings or site plan/map not available for review limiting full property condition assessment.

Property manager knowledge of physical structure and general operation of facility plant limited and access to system facilities limited. Maintenance staff consisted of one person working only on weekends until 3 pm, thus limiting ability to discuss maintenance issues or gain access to certain building systems.

Inspection Date: Inspector: J. William Naish Email: j@npi-sd.com

01/01/2001 Inspector Phone: 858.888.0848



# **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

Unable to gain access to, thus limiting inspection of:

- Areas containing hot water boiler/water heater used to heat water for all guest rooms. (During random visual inspection of guest rooms, all had ample hot water present.)
- Main electric service room. Reviewed some sub panels throughout the complex.
- Attic space between roof and guest rooms. Property manager stated that there was no attic.
- Space inside mansard roof. Minimal access available where air ventilation register had been removed from roof parapet.

The Inspection only includes those systems and components expressly and specifically identified in the Inspection Report. The Inspection limitations, exceptions and exclusions in the Standards of Practice are incorporated herein. In addition, any area which is not exposed to view, is concealed, is inaccessible because of soil, walls, floors, carpets, ceilings, furnishings or any other fashion. The Inspection does not include any destructive testing or dismantling. Based on the nature of the findings, every effort has been made to provide a comprehensive overview relative to this structure. The following systems and components and areas are among those NOT included in the Inspection or Inspection Report:

- Latent or concealed defects, compliance with code or zoning ordinances or permit research or system or component recalls.
- Structural, geological, soil, survey, engineering analysis or testing.
- Pool/spa inspected for general, overall condition and general compliance with codes and regulations. Recommend full review of licensing and testing records. Recommend licensed qualified pool/spa professional review all safety and heath records and conditions.
- Elevator operation or service records , with the exception of license verification and general operation.
- Termites or other wood destroying insects or organisms, rodents or other pests, dry rot or fungus, or damage from or relating to the preceding.
- Asbestos, radon gas, lead paint, urea formaldehyde, mold or mildew, odors or noise, or flammable chemicals, water or air quality, PCB's or other toxins, electro-magnetic fields, underground storage tanks, proximity to toxic waste sites or other environmental or health hazards.
- Private water, sewage, water softeners or purifiers, or solar systems.
- Steam baths, fountains or other types of or related systems and components.
- Building value appraisal.
- Thermostatic or time clock controls, radio controlled devices, automatic gates or elevators, lifts, dumbwaiters.

Inspection Date: Inspector: J. William Naish 01/01/2001 Inspector Phone: 858.888.0848



# **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

- Freestanding appliances and gas appliances such as fire pits, barbecues, heaters and lamps. Main gas shut off valve. Any gas leaks, furnace heat exchangers.
- Seismic safety, closed circuit TV, security, fire safety or solar (hot water or electric) systems or security bars and/or safety equipment. Recommend licensed qualified company be retained for further evaluation.
- Any adverse condition that may affect the desirability of the property but not limited to proximity to railroad tracks or airplane routes, boundaries, easements or rights of way, adjoining properties or neighborhood.
- Unique/technically complex systems or components, life expectancy or adequacy or efficiency of any system or component.
- Solar panels not in scope of this inspection. Units not inspected.
- Minor details and/or cosmetic items are not, for the most part, incorporated in this report.
- Security alarm system is not in the scope of this inspection, and therefore not inspected, recommend contracting a license qualified company for further evaluation.

Inspection Date: Inspector: J. William Naish

01/01/2001 Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

# **National Property Inspections**

Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

# **Summary**

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

#### 1 MAIN FLAT ROLLED ROOFING

**POOR** 

This roof has passed its useful life and should be replaced. Active leaks and many recent repairs observed. Large areas of granular loss evident. Additional photos are located at end of report. See photos numbered between 14 and 19.

NOTE: Unable to see breath of problem or water intrusion because no one available to indicate location of interstitial space between 2nd floor ceiling and roof. Cost discussion at end of report. See additional photos at end of report.



MAIN FLAT ROLLED ROOFING: Typical wear and slight cracking at coping material run up parapet wall.



MAIN FLAT ROLLED ROOFING: Evidence of recent patch.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

# NPI.

# JDeeEn Inc. DBA

# **National Property Inspections**



MAIN FLAT ROLLED ROOFING: Evidence of continuous roof patching with 5 gallon pail of mastic (one of two found on roof)



MAIN FLAT ROLLED ROOFING: Evidence of another recent roof repair.



MAIN FLAT ROLLED ROOFING: Existing crack and point of water intrusion that needs to be repaired before next rainfall.



MAIN FLAT ROLLED ROOFING: Evidence of ponding and granular loss with it piling up at low spots.



# **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

#### 2 HOTEL LAUNDRY DRYER VENTING

Dryer Vents POOR

Commercial laundry dryer vented directly outside near ground, accumulating and posing a fire hazard. Recommend remediation.



HOTEL LAUNDRY DRYER VENTING: Commercial laundry dryer vented directly outside near ground



HOTEL LAUNDRY DRYER VENTING: Accumulation of dryer lint in planter bed directly outside commercial dryer.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

#### **3 GUEST BATHROOM 229**

Tub/Shower POOR

Shower/tub diverter broken, can't use shower



GUEST BATHROOM 229: Shower/tub diverter broken, can't use shower

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

#### **4 GUEST BATHROOM 241**

Electrical (Random sampling of outlets, switches, fixtures.)

POOR

Bathroom in room 241 has the wires crossed - the hot and neutral have been reversed.



GUEST BATHROOM 241: Bathroom in room 241 has the wires crossed - the hot and neutral have been reversed.



GUEST BATHROOM 241: GFCI installed and operational however the hot and neutral have been reversed.



GUEST BATHROOM 241: Sink drain stopper missing.



GUEST BATHROOM 241: Shower diverter missing - could not turn on shower.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

# 5 MEETING ROOM - CURRENTLY BEING USED AS

Electrical (Random sampling of outlets, switches, fixtures.)

POOR

Burnt power strip still plugged into wall. Recommend removal.



MEETING ROOM - CURRENTLY BEING USED AS BREAKFAST ROOM: Burnt power strip still plugged into wall. Recommend removal.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



# **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

#### 6 GUEST ROOM 104 (HANDICAPPED)

Running Water POOR

Bar sink drains slow. Refrigerator and microwave appear operational. Hot water present Water pressure good. **No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 6 feet of sink.** This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.

#### **7 GUEST ROOM 119**

Running Water POOR

Bar sink slow to drain. No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 6 feet of sink. This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.



GUEST ROOM 119: Sink slow to drain

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



# **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

#### **8 GUEST ROOM 134**

Running Water POOR

No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 6 feet of sink.

This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.

#### 9 GUEST ROOM 209

Running Water POOR

Bar sink slow to drain. **No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 6 feet of sink.** This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.

#### **10 GUEST ROOM 235**

Ceilings

Incomplete patch around ceiling fire sprinkler & masking tape on wallpaper seam.



GUEST ROOM 235: Incomplete patch around ceiling fire sprinkler & masking tape on wallpaper seam.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

#### JDeeEn Inc. DBA

# **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

#### **11 GUEST ROOM 120**

Running Water POOR

Low water pressure. **No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 6 feet of sink.** This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.



GUEST ROOM 120: Low water pressure.
Refrigerator and microwave appear operational. Hot water present. No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 6 feet of sink. This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.

P (POOR)

Below-average condition for the building system evaluated, taking into consideration factors of age and design. Immediate repair, significant work or replacement is anticipated to return the building system to a good or fair condition.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

# **National Property Inspections**

Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

The property is in overall good, sound condition except for those items excluded from this assessment or inaccessible at the time of the inspection. Following is a list of those items observed that will require maintenance within the next 5 years

## **DRIVEWAY & PARKING LOT REPAIR COSTS**

Parking lot patching and seal coating: The asphalt is generally in good condition. The cracks should be filled and a slurry coat applied within the next 5 years. Estimated cost: \$20,000 to \$35,000.

## **ROOF REPLACEMENT COSTS**

Approximate cost to replace the roof on this building (approximately 25,000 sq. ft.) will range between \$100,000 and \$200,000 depending on application style and grade of material. Though it is not unusual to get 20 years out of a roof, for deferred maintenance purposes, one should plan to replace the roof every 10-15 years.

Surface coatings can be applied at regular intervals to extend the life of the roof at a fraction of the cost. However, this should be done at scheduled times as part of a robust maintenance plan. It WILL NOT typically extend the life of the roof if it has already exceeded its usefulness.

CAVEAT: Because the roof has solar, a re-roof project will be more complex. The panels will most likely need to be removed, stored and replaced by a qualified licensed electrical contractor during the re-roofing process. If the solar array is part of a "Purchase Power Agreement" and not outright owned, there may be penalties for disconnecting the units during construction.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

# **National Property Inspections**

Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

### REPLACEMENT OF GUEST ROOM HVAC WALL UNITS

The original HVAC wall units remain in about 20% of the 10% of the vacant guest rooms randomly selected. These units will be 27 years old and will need replacement within the next 5-10 years, or when they break. They have passed their useful life and more energy efficient units are available. Estimated cost \$1,600 each with an unknown number of older units remaining.

## **UPGRADING GUEST ROOM BAR SINK ELECTRICAL OUTLET**

To replace the non-GFCI outlet with a GFCI outlet at each bar sink in 107 rooms would cost between \$100 & \$150/room if a licensed electrician is hired to do the work. Estimated overall cost should range between \$10,000 and \$17,000.

## REPLACEMENT OF ROOFTOP HVAC UNITS

All but one of the several air conditioning units located on the roof are nearing their life expectancy. Recommend professional licensed mechanical contractor be retained to review condition and maintenance records of existing units. Estimate \$5,000 each to replace. Approximate total of 7 units.

# REPLACEMENT OF ABANDONED VENTILATION UNIT ON ROOF

One ventilation unit has been dismantled and abandoned. Estimated replacement \$1,500.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

# NPI.

# JDeeEn Inc. DBA

# **National Property Inspections**

Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

# NPI.

# JDeeEn Inc. DBA

# **National Property Inspections**

Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

	G	F	P	NI	NA
DRIVEWAY	V				

☑ Asphalt ☑ Cracks

#### Comments:

Driveway and parking lot are in good overall condition. Typical cracking occurring with no crack wider than 1/4". Red fire lane curb is pealing in several locations. Recommend filling cracks, sealing asphalt with slurry coat, re-striping parking lot, and re-paint red fire lane curbs within next 5 years.



Driveway: East looking west on south side of building



Driveway: North entrance looking from N. Vineyard.



Driveway: North looking south (towards airport.).



Driveway: West looking east on south side of building.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Driveway: Looking from lobby doorway to the left (south-west)



Driveway: Fire lane curb paint peeling.



Driveway:



Driveway: Typical cracking in a few places with cracks no wider than 1/4".

## ADA/HANDICAPPED PARKING & PATH OF TRAVEL

G	F	P	NI	NA
V				

**☑** Asphalt

#### Comments:

Handicap parking is adjacent to hotel lobby entrance and path of travel is free of obstructions. The required ratio between common parking stalls and handicap spaces is 25 to 1. This property has 4 handicap parking spaces, with at least 1 van accessible space, which would permit up to 200 parking stalls.

NOTE: Because no site maps, plot plans or other drawings were made available at time of inspection it is not possible to determine if there are the appropriate number of handicap parking spaces.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

#### JDeeEn Inc. DBA

# **National Property Inspections**



ADA/Handicapped Parking & Path of Travel: Four handicap spaces located adjacent to the lobby entrance.



ADA/Handicapped Parking & Path of Travel: Handicap parking with required van access.



ADA/Handicapped Parking & Path of Travel: Path of travel between parking area and hotel lobby free of obstructions and tripping hazards.



 $\label{eq:ADA/Handicapped Parking \& Path of Travel: No threshold entrance.} \\ No threshold entrance.$ 



# **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

	G	F	P	NI	NA
PARKING AREA	$\square$				

☑ Asphalt ☑ Cracks

#### Comments:

Driveway and parking lot are in good overall condition. Typical cracking occurring with no crack wider than 1/4". Red fire lane curb is pealing in several locations. Recommend filling cracks, sealing asphalt with slurry coat, re-striping parking lot, and re-paint red fire lane curbs within next 5 years.

NOTE: Because no site maps, plot plans or other drawings were made available at time of inspection, there is no clear identifiers of demarcation between FOLK INN and hotels to the south and west. No representation is given or provided stating perimeter of site and what parking is specific to FOLK INN.



Parking Area: Front parking area directly off N. Vineyard.



Parking Area: Occasional small cracks observed.



Parking Area: Driveway looking from front south-west corner looking east.



Parking Area: Looking from furthest south-west corner of lot.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

## JDeeEn Inc. DBA

# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Parking Area: Looking at back of property.


#### WALKS / STEPS

**☑**Concrete

#### Comments:



Walks / Steps: Sidewalk in front of property.





Walks / Steps: ADA/Handicap access to walkway on north side of building.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

## JDeeEn Inc. DBA

# **National Property Inspections**



Walks / Steps: Access to exterior hallway doors at south side of building.



Walks / Steps: Sidewalk at rear of property.



Walks / Steps: Steps leading from adjacent property to Folk Inn parking lot.



Walks / Steps: Walkway on north side of front of building.

### JDeeEn Inc. DBA

# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Walks / Steps: Stairs leading from Folk Inn to adjacent property at northeast corner of west/front parking area.

## REAR PATIO OFF CONFERENCE ROOM CURRENTLY USED AS B

G	F	P NI		NA
V				

**☑** Concrete

#### Comments:



Rear Patio off conference room currently used as B: Patio area outside of meeting room currently being used as breakfast area. Iron fence shown in photo is safety fence surrounding pool/spa area.



Rear Patio off conference room currently used as B: Patio area outside of meeting room currently being used as breakfast area. Iron fence shown in photo is safety fence surrounding pool/spa area.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



# **National Property Inspections**

# Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

	G	F	P	NI	NA	
NORTH RETAINING WALL	Ø					

☑ Sides ☑ Block ☑ Concrete

#### Comments:



North Retaining Wall: North-west corner of building in front.



North Retaining Wall: North side of the building from about center of retaining wall length..



North Retaining Wall: North side of building on the west end.



North Retaining Wall: Parking lot is another property.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

## JDeeEn Inc. DBA

# **National Property Inspections**

# Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



North Retaining Wall: North side of building from north-east corner of building.

#### **LANDSCAPING**

# G F P NI NA ☑ □ □ □ □

#### Comments:

Landscape kept in good condition.



Landscaping: Landscaping in front of property.



Landscaping: Landscaping in front of property.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

## JDeeEn Inc. DBA

# **National Property Inspections**



Landscaping: Trees & hedges located in back of property.



Landscaping: Landscaping in front of property.



Landscaping: Landscaping on south side of property.



Landscaping: Typical landscaping around area between parking lot and structure.

## JDeeEn Inc. DBA

# **National Property Inspections**

# Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Landscaping: Landscaping at rear of property around trash enclosure.

#### **SIGNAGE & STATUES**

# G F P NI NA ☑ □ □ □ □

#### Comments:



Signage & statues: Road Frontage Sign



Signage & statues: Statues flanking entrance into hotel.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Signage & statues: Statues flanking entrance into hotel.



Signage & statues: Bronze Plaque embedded into concrete below lobby entrance statues.



Signage & statues: Address numbers on right side of exterior by lobby doors.



Signage & statues: Statues located at street entrance to hotel.

## MANSARD CONCRETE TILE ROOFING

G F P NI NA
☑ □ □ □ □

Age: 26 Year(s)

✓ Concrete Tile

Comments:

Leaks not always detectable.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

Design Life: 50+ Year(s)

Email: j@npi-sd.com

Layers: 1

#### JDeeEn Inc. DBA

# **National Property Inspections**



Mansard Concrete Tile Roofing: Typical field of concrete tile roofing shingles on perimeter of entire building.



Mansard Concrete Tile Roofing: Concrete applied to ridge tile where transition is made. All appeared to be in good condition.



Mansard Concrete Tile Roofing: Typical field of concrete tile roofing shingles on perimeter of entire building.



Mansard Concrete Tile Roofing: Concrete applied to ridge tile where transition is made. All appeared to be in good condition.

# JDeeEn Inc. DBA

# **National Property Inspections**



Mansard Concrete Tile Roofing: Typical field of concrete tile roofing shingles on perimeter of entire building.



Mansard Concrete Tile Roofing: Typical field of concrete tile roofing shingles on perimeter of entire building.



Mansard Concrete Tile Roofing: Typical view of various transitions in concrete roof tile.



Mansard Concrete Tile Roofing: Typical field of concrete tile roofing shingles on perimeter of entire building.



# **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

MAIN FLAT ROLLED ROOFING				V	
Age: 15-20 Year(s)	Design Life: 10-15 Year(s)				
☑ Walked On	☑ Asphalt / Composition	☑ Cupping / Curling / Lifting / Brittle			
☑ Excessive Granular Loss	☑ Previous Repairs Noted	☑ Suspected Leak(s)			

#### Comments:

This roof has passed its useful life and should be replaced. Active leaks and many recent repairs observed. Large areas of granular loss evident. Additional photos are located at end of report. See photos numbered between 14 and 19

NOTE: Unable to see breath of problem or water intrusion because no one available to indicate location of interstitial space between 2nd floor ceiling and roof. Cost discussion at end of report. See additional photos at end of report.



Main Flat Rolled Roofing: Field view of flat roof.




G F P NI NA

Main Flat Rolled Roofing: Typical wear and slight cracking at coping material run up parapet wall.

# **National Property Inspections**



Main Flat Rolled Roofing: Evidence of recent patch.



roof patching with 5 gallon pail of mastic (one



Main Flat Rolled Roofing: Evidence of another recent roof repair.



Main Flat Rolled Roofing: Existing crack and point of water intrusion that needs to be repaired before next rainfall.



# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Main Flat Rolled Roofing: Evidence of ponding and granular loss with it piling up at low spots.



Main Flat Rolled Roofing: Field view of flat roof.

### INTERIOR OF MANSARD FACAD

# G F P NI NA ☑ □ □ □ □

#### Comments:

Mansard interior accessed through ventilation plate that had fallen off. All other access points unavailable without destructive dismantling of other air vents.



Interior of Mansard Facad:



Interior of Mansard Facad:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

## JDeeEn Inc. DBA

# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Interior of Mansard Facad: OSB used to sheath deck of concrete tiled mansard roof.

## SOLAR PANELS INSTALLED ON ROOF

G	F	P	NI	NA
			V	

#### Comments:

Inspection of solar panels and the associated infrastructure are not part of this inspection. Photos and opinions provided herein are as a courtesy and are not to be taken as expert advice. Recommend retaining professional electrical contractor with specific solar system knowledge and experience to review system in its entirety.



Solar Panels Installed on Roof: Typical array of solar panels on stanchions.



Solar Panels Installed on Roof: Conduit identified for solar panel connection to inverter.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

## JDeeEn Inc. DBA

# **National Property Inspections**



Solar Panels Installed on Roof: Typical array of solar panels on stanchions.



Solar Panels Installed on Roof: Solar panel rack assembly roof attachments appear of good workmanship with rolled roofing material applied over Vulcan flashing boot.



Solar Panels Installed on Roof: Typical array of solar panels on stanchions.



Solar Panels Installed on Roof: Solar panel rack assembly roof attachments appear of good workmanship with rolled roofing material applied over Vulcan flashing boot.

#### JDeeEn Inc. DBA

## **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Solar Panels Installed on Roof: Typical array of solar panels on stanchions.



Solar Panels Installed on Roof: Conduit for solar panel connection to inverter.

#### **FLASHING/VALLEYS**

G	F	P	NI	NA
Ø				

#### Comments:



Flashing/Valleys: Valley flashing observed. Typical.



Flashing/Valleys: See next photo for close-up.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Flashing/Valleys: Step flashing observed. Typical.



Flashing/Valleys: Step flashing observed. Typical.



Flashing/Valleys: Typical concrete tile roof ridge.



Flashing/Valleys: Step flashing observed. Typical.

 $\overline{\mathbf{V}}$ 

#### **GUTTERS/DOWN SPOUTS**

✓ Steel

#### Comments:

There are no gutters on this property. The flat roof is serviced by interior downspouts with examples of entry and exit points shown in photos below.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

#### JDeeEn Inc. DBA

## **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Gutters/Down Spouts: Exit point of internal drain system.



Gutters/Down Spouts: Exit point of internal drain system.



Gutters/Down Spouts: Internal downspout drain missing debris cap. Typical.

#### **CHIMNEY**

G F P NI NA
☑ □ □ □ □

Comments:

Flue not inspected. Annual cleaning is recommended.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Chimney: Chimney for fireplace located in front lobby.



Chimney: Looking inside from fireplace hearth.

#### **EXTERIOR SURFACE**

✓Stucco	☑Wood					
		G	F	P	NI	NA
SIDING/TRIM		V				

#### Comments:



Exterior Surface: Typical stucco and wood siding in the tradition of the Tudor style.



Exterior Surface: Typical stucco and wood siding in the tradition of the Tudor style.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

## **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Exterior Surface: Typical stucco and wood siding in the tradition of the Tudor style.



Exterior Surface: Vent repair not complete. Requires stucco repair and paint.



Exterior Surface: Typical stucco and wood siding in the tradition of the Tudor style.



Exterior Surface: Typical 2nd floor surface structure to mimic a Juliet balcony.

#### JDeeEn Inc. DBA

## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Exterior Surface: Typical stucco and wood siding in the tradition of the Tudor style.

#### **WINDOWS**

☑ Metal ☑ Vinyl

☐ General Deterioration

#### Comments:



Windows: Combination of newer vinyl and older steel windows throughout the property.



Windows: Combination of newer vinyl and older steel windows throughout the property.

 $\overline{\mathbf{V}}$ 

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848 Email: j@npi-sd.com

NA

#### JDeeEn Inc. DBA

## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Windows: Typical structure to mimic window planter boxes or Juliet balconies throughout the property.



Windows: Combination of newer vinyl and older steel windows throughout the property.

## Attic / Roof

**Method of Inspection** ✓ No Access / Limited

ATTIC	FRAMIN	THINC

G	F	P	NI	NA
V				

☑ Plywood / Panel Board / OSB ☑ Rafters

#### Comments:

Limited view of attic space within mansard roof structure only. Onsite property manager stated that there was no attic to inspect.

Leaks not always detectable.

Inspection Date: 01/01/2001


Inspector: J. William Naish Inspector Phone: 858.888.0848



### JDeeEn Inc. DBA

## **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Attic Framing/Sheathing:



Attic Framing/Sheathing:

#### ATTIC VENTILATION

#### Comments:

Mansard roof ventilation observed.



Attic Ventilation: Mansard roof ventilation observed.



Attic Ventilation: Mansard roof ventilation observed.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848 Email: j@npi-sd.com

NI

NA



### JDeeEn Inc. DBA

## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

COMMON AREAS ELECTRICAL	G	F	P	NI	NA
SERVICE	Ø				
ENTRANCE CABLE	Ø				
PANEL	Ø				
SUB-PANEL	Ø				
BRANCH CIRCUITS	Ø				
BONDING/GROUNDING	Ø				
GFCI(IN PANEL)*	Ø				
ARC FAULT	Ø				
LOW VOLTAGE	Ø				

#### Comments:



Common Areas Electrical: Sub panels in temporary prep kitchen.



Common Areas Electrical: Main property vault for electrical service located at street within sidewalk in front of property.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

# NPI.

### JDeeEn Inc. DBA

## **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Common Areas Electrical: Electrical sub panels located in temporary food prep area servicing breakfast area.



Common Areas Electrical: Sub panel located in kitchen.



Common Areas Electrical: Sub panels in exercise room.

#### **ROOF SOLAR SYSTEM**

G	F	P	NI	NA
			Ø	

Comments:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

#### JDeeEn Inc. DBA

## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

For more information on electrical connections of roof solar system see section exterior/roof/roofing/solar.

Inspection of solar panels and the associated infrastructure are not part of this inspection. Photos and opinions provided herein are as a courtesy and are not to be taken as expert advice. Recommend retaining professional electrical contractor with specific solar system knowledge and experience to review system in its entirety.

LOW VOLTAGE/FIRE ALARM PANEL.	G	F	P	NI	NA
PANEL	Ø				
SMOKE DETECTORS*				Ø	

#### Comments:

Smoke detectors were not tested, nor was the alarm notification panel tested. Recommend retaining professional Safety & Security professional, licensed contractor to review.

Low voltage for various systems such as CCTV, cable TV, building automation system, or any other system wiring was not inspected as part of the scope of this Property Condition Assessment.



Low voltage/Fire Alarm Panel.: Low voltage wire (system unknown) on roof exposed to the elements and missing wire nuts.



Low voltage/Fire Alarm Panel.: Fire panel located in first floor south corridor next to elevator.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

## **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Low voltage/Fire Alarm Panel.: "Bug Eye" emergency lighting in place. Typical.

### **SECURITY SYSTEM**

G	F	P	NI	NA
			V	

#### Comments:



Security System: Typical CCTV located throughout the exterior of the property.



Security System: Typical CCTV located throughout the exterior of the property.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

#### JDeeEn Inc. DBA

## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Security System: Monitors for security system located in office behind reception desk.



Security System: Monitors for security system located in office behind reception desk.



Security System: Monitors for security system located in office behind reception desk.

HOTEL LAUNDRY FACILITIES (FIRST FLOOR)	G	F	P	NI	NA
UTILITY HOOKUPS	☑				
DRYER VENTS	Ø				
DRAIN	Ø				

#### Comments:

Commercial washers & dryers not inspected as part of this inspection. Recommend qualified company be retained to fully inspect for condition and maintenance practices. During courtesy inspection some of the equipment was operational.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

# NPI.

### JDeeEn Inc. DBA

## **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Hotel Laundry Facilities (First Floor): Commercial washers and dryers.



Hotel Laundry Facilities (First Floor):



Hotel Laundry Facilities (First Floor): Dumb Waiter to deliver clean sheets, towels, etc to second floor.



Hotel Laundry Facilities (First Floor): Water connections for washing machines.

#### JDeeEn Inc. DBA

## **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Hotel Laundry Facilities (First Floor):



Hotel Laundry Facilities (First Floor): Commercial washers and dryers.



Hotel Laundry Facilities (First Floor): Commercial washers and dryers.



Hotel Laundry Facilities (First Floor): Commercial washers and dryers.

GUEST LAUNDRY FACILITIES (SECOND FLOOR)	G	F	P	NI	NA
UTILITY HOOKUPS	Ø				
DRYER VENTS		Ø			
DRAIN	Ø				

#### Comments:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

#### JDeeEn Inc. DBA

## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Guest Laundry Facilities (Second Floor): Guest 2nd floor coin operated laundry facility. Some of the equipment non-operational.



Guest Laundry Facilities (Second Floor): Guest 2nd floor coin operated laundry facility. Some of the equipment non-operational.



Guest Laundry Facilities (Second Floor): Guest 2nd floor coin operated laundry facility. Some of the equipment non-operational.



Guest Laundry Facilities (Second Floor): Guest 2nd floor coin operated laundry facility. Some of the equipment non-operational.

### JDeeEn Inc. DBA

## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Guest Laundry Facilities (Second Floor): Water hookups and drain pipe.



Guest Laundry Facilities (Second Floor): Improper transition vent used to connect dryer to vertical steel vent pipe.



Guest Laundry Facilities (Second Floor): vertical vent pipe from dryers.



Guest Laundry Facilities (Second Floor): Guest 2nd floor coin operated laundry facility. Some of the equipment non-operational.

HOTEL LAUNDRY DRYER VENTING	Recommend Repairs	G	F	P	NI	NA
DRYER VENTS				Ø		

#### Comments:

Commercial laundry dryer vented directly outside near ground, accumulating and posing a fire hazard. Recommend remediation.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

#### JDeeEn Inc. DBA

## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Hotel Laundry Dryer Venting: Commercial laundry dryer vented directly outside near ground



Hotel Laundry Dryer Venting: Accumulation of dryer lint in planter bed directly outside commercial dryer.

 $\overline{\mathbf{V}}$ 

#### **ELEVATOR**

#### Comments:

Elevator inspection not part of this Property Condition Assessment. A visual, cursory inspection was performed. Recommend retaining professional licensed elevator contractor for further review.



Elevator: Interior of elevator.



Elevator: Control panel of elevator.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848 Email: j@npi-sd.com

ΝI

NA

### JDeeEn Inc. DBA

## **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Elevator: Certificate up to date.



Elevator: Interior of elevator.



Elevator: Door operational.



Elevator:

#### **UTILITY CONNECTIONS**

G	F	P	NI	NA
V				

#### Comments:

Unable to inspect main electrical room or entrance location due to no one on premises had a key to gain entry.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

#### JDeeEn Inc. DBA

## **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Utility Connections: Underground utilities located in front of hotel on the grounds directly in front of N. Vineyard.



Utility Connections: "Purple pipe" recycled water control box.



Utility Connections: Gas/eletric vault located in front of property.



Utility Connections: Electric vault located in front sidewalk.

### JDeeEn Inc. DBA

## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Utility Connections: Main water shut-off/backflow preventer.



Utility Connections: Gas distribution regulator.

#### **HEATING**

☑Gas	☑ Forced Air					
		G	F	P	NI	NA
OPERATION		V				

#### Comments:

Heater/air handling unit used for lobby area was not located. Onsite property manager did not know where the location was and the maintenance person had gone home for the day.



Heating: Heat/ventilation unit in kitchen undergoing remodeling.



Heating: Small furnance/air ventilation unit servicing meeting room.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



#### JDeeEn Inc. DBA

## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

#### INTERIOR/GROUND BASED COOLING

G	F	P	NI	NA
$\overline{\mathbf{Q}}$				

#### Comments:



Interior/Ground Based Cooling: One of two split systems located in Fitness Center. Compressor part visible in rooftop HVAC section.



Interior/Ground Based Cooling: Outside compressor unit for hotel laundry facility.



Interior/Ground Based Cooling: Typical 2nd floor guest room wall unit located under each room's window.



Interior/Ground Based Cooling: Typical built-in HVAC unit located in each guest room under the window.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



#### JDeeEn Inc. DBA

## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

		G	F	P	NI	NA	
ROOFTOP HVAC UNITS	☑ Recommend Repairs		Ø				

#### Comments:

Rooftop HVAC units in various stages of life expectancy. Recommend obtaining a professional licensed HVAC contractor to review each unit and advise on current condition and remaining life expectancy.



Rooftop HVAC Units: Newer rooftop condenser HVAC unit.



Rooftop HVAC Units: Older HVAC rooftop condensing unit.



Rooftop HVAC Units: Average life remaining on these two HVAC units.



Rooftop HVAC Units: Older HVAC rooftop condensing unit.

### JDeeEn Inc. DBA

## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Rooftop HVAC Units: This unit has been abandoned and should be replaced, see next photo.



Rooftop HVAC Units: Wires disconnected from unit.



Rooftop HVAC Units: Older HVAC rooftop condensing unit.

#### ROOFTOP POWER VENTILATION

	G	F	P	NI	NA
☑ Recommend Repairs		Ø			

## Comments:

Rooftop ventilator disassembled and inoperable. Recommend obtaining professional licensed mechanical contractor to review needs and determine replacement.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

#### JDeeEn Inc. DBA

## **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Rooftop Power Ventilation: Rooftop ventilator disassembled and inoperable.



Rooftop Power Ventilation: Unfamiliar with this type of ducting. Recommend professional mechanical contractor review and advise.



Rooftop Power Ventilation: Laundry room ventilator.



Rooftop Power Ventilation: Laundry room & equipment ventilator.

KITCHEN	G	F	P	NI	NA
CEILINGS				V	
WALL(S)				Ø	
WINDOWS/TRIM				Ø	
WINDOW SCREENS				V	
FLOOR/FINISH				Ø	
INTERIOR DOORS/HARDWARE				V	

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



#### JDeeEn Inc. DBA

## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999 ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.) $\sqrt{}$ GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST RECOMMENDED.) $\overline{\mathbf{V}}$ HEAT/AIR DISTRIBUTION $\overline{\mathbf{V}}$ COUNTERTOPS/CABINETS $\overline{\mathbf{A}}$ SINK/FAUCET $\overline{\mathbf{V}}$ EXHAUST FAN $\overline{\mathbf{V}}$ STOVE TOP/OVEN $\overline{\mathbf{V}}$ STOVE ANTI-TIP BRACKET $\checkmark$ WATER PRESSURE/FLOW/DRAINAGE $\checkmark$ DISHWASHER/CROSS FLOW PROTECTION $\checkmark$ $\overline{\mathbf{Q}}$ REFRIGERATOR MICROWAVE $\overline{\mathbf{V}}$

#### Comments:

GARBAGE DISPOSAL

Kitchen area under extensive remodeling with nothing functional.

Additional photos included at end of report (#1 thru #11.) Photos 9 & 10 show where an outside door was permanently closed and covered up with walled stainless steel in the easterly wall in the kitchen.



Kitchen: Kitchen under construction



 $\checkmark$ 

Kitchen: Fire suppression system partially installed. Recommend professional expert be hired to verify operation once construction is complete.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

## **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Kitchen: Kitchen under construction



Kitchen: Kitchen under construction



Kitchen: Electrical sub panel for kitchen.



Kitchen: Fire suppression system partially installed. Requires charging. Recommend professional expert be hired to verify operation once construction is complete.

# NPI.

#### JDeeEn Inc. DBA

## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Kitchen: Kitchen under construction



Kitchen: New kitchen grease trap/collector is being installed as part of kitchen remodel.

#### FRONT LOBBY FIREPLACE/STOVE

☑ Gas Log ☑ Metal Firebox

✓ Recommend Repairs □ ✓

G	F	P	NI	NA
	Ø			

#### Comments:

Safety glass bi-fold door glass is loose and requires repair.

Recommend annual cleaning - Fireplace design and soot / creosote buildup, in most cases, prevents view of chimney liner / cracks.



Front Lobby Fireplace/Stove: Fireplace located in lobby.



Front Lobby Fireplace/Stove: Fireplace located in lobby.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

#### JDeeEn Inc. DBA

## **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Front Lobby Fireplace/Stove: Fireplace located in lobby. Glass doors closing off fireplace broken.



Front Lobby Fireplace/Stove: Fireplace flue open.



Front Lobby Fireplace/Stove: Chimney on roof.

FIRST FLOOR LOBBY MEN'S RESTROOM	G	F	P	NI	NA
CEILINGS	Ø				
WALL(S)	Ø				
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST RECOMMENDED.)	Ø				
HEAT/AIR DISTRIBUTION	Ø				

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



### JDeeEn Inc. DBA

## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

COUNTERTOPS/CABINETS	Ø		
SINK/FAUCET	Ø		
TOILET	Ø		
TUB/SHOWER			Ø
TILE WORK/ENCLOSURE	Ø		
EXHAUST FAN	Ø		
WATER PRESSURE/FLOW/DRAINAGE	Ø		

#### Comments:



First Floor Lobby Men's Restroom:



First Floor Lobby Men's Restroom:



First Floor Lobby Men's Restroom:



First Floor Lobby Men's Restroom:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



### JDeeEn Inc. DBA

# **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

FIRST FLOOR WOMEN'S RESTROOM	G	F	P	NI	NA
CEILINGS	Ø				
WALL(S)	Ø				
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST RECOMMENDED.)	Ø				
HEAT/AIR DISTRIBUTION	Ø				
COUNTERTOPS/CABINETS	Ø				
SINK/FAUCET	Ø				
TOILET	Ø				
TILE WORK/ENCLOSURE	Ø				
EXHAUST FAN	Ø				
WATER PRESSURE/FLOW/DRAINAGE	Ø				

#### Comments:



First Floor Women's Restroom:



First Floor Women's Restroom:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

## JDeeEn Inc. DBA

# **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



First Floor Women's Restroom:

GUEST BATHROOM 104 (HANDICAP EQUIPPED)	G	F	P	NI	NA
CEILINGS	$\square$				
WALL(S)	V				
WINDOWS/TRIM	V				
WINDOW SCREENS	V				
FLOOR/FINISH	V				
INTERIOR DOORS/HARDWARE	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	V				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST RECOMMENDED.)	V				
HEAT/AIR DISTRIBUTION					
COUNTERTOPS/CABINETS					
SINK/FAUCET	V				
TOILET	V				
TUB/SHOWER					
JETTED TUB					Ø
TILE WORK/ENCLOSURE	$\square$				
EXHAUST FAN	$\square$				
WATER PRESSURE/FLOW/DRAINAGE	$\square$				

Comments:

Inspection Date: Inspector: J. William Naish 01/01/2001 Inspector Phone: 858.888.0848

# NPI.

### JDeeEn Inc. DBA

## **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Guest Bathroom 104 (handicap equipped):



Guest Bathroom 104 (handicap equipped):



Guest Bathroom 104 (handicap equipped):



Guest Bathroom 104 (handicap equipped):



Guest Bathroom 104 (handicap equipped):



Guest Bathroom 104 (handicap equipped):

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

## **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Guest Bathroom 104 (handicap equipped): Handicapped shower/tub chair.



Guest Bathroom 104 (handicap equipped): Wheelchair access to toilet.

GUEST BATHROOM 114	G	F	P	NI	NA
CEILINGS	Ø				
WALL(S)	Ø				
WINDOWS/TRIM	Ø				
WINDOW SCREENS	Ø				
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST RECOMMENDED.)	Ø				
HEAT/AIR DISTRIBUTION	Ø				
COUNTERTOPS/CABINETS	Ø				
SINK/FAUCET	Ø				
TOILET	Ø				
TUB/SHOWER	Ø				
JETTED TUB					Ø
TILE WORK/ENCLOSURE	Ø				
EXHAUST FAN	Ø				
WATER PRESSURE/FLOW/DRAINAGE	Ø				

#### Comments:

Inspection Date: Inspector: J. 01/01/2001 Inspector Ph

Inspector: J. William Naish Inspector Phone: 858.888.0848

# NPI.

### JDeeEn Inc. DBA

# **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Guest Bathroom 114:



Guest Bathroom 114:



Guest Bathroom 114:



Guest Bathroom 114: GFCI installed and operational

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

# **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Guest Bathroom 114:



Guest Bathroom 114:



Guest Bathroom 114:




## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

GUEST BATHROOM 119	G	F	P	NI	NA
CEILINGS	Ø				
WALL(S)	Ø				
WINDOWS/TRIM	Ø				
WINDOW SCREENS	Ø				
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST RECOMMENDED.)	Ø				
HEAT/AIR DISTRIBUTION	Ø				
COUNTERTOPS/CABINETS	☑				
SINK/FAUCET	☑				
TOILET	V				
TUB/SHOWER	☑				
JETTED TUB					Ø
TILE WORK/ENCLOSURE	Ø				
EXHAUST FAN	Ø				
WATER PRESSURE/FLOW/DRAINAGE	Ø				

## Comments: slow tub drain







Guest Bathroom 119:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

## **National Property Inspections**



Guest Bathroom 119: GFCI installed and operational



Guest Bathroom 119:



Guest Bathroom 119:



Guest Bathroom 119:



## **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999







Guest Bathroom 119:

GUEST BATHROOM 134	G	F	P	NI	NA
CEILINGS	Ø				
WALL(S)	Ø				
WINDOWS/TRIM	V				
WINDOW SCREENS	Ø				
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST RECOMMENDED.)	Ø				
HEAT/AIR DISTRIBUTION	Ø				
COUNTERTOPS/CABINETS	Ø				
SINK/FAUCET	Ø				
TOILET	Ø				
TUB/SHOWER	Ø				
JETTED TUB					Ø
TILE WORK/ENCLOSURE	Ø				
EXHAUST FAN	Ø				
WATER PRESSURE/FLOW/DRAINAGE	$\overline{\mathbf{A}}$				

Comments:

Inspection Date: Inspector: J. William Naish 01/01/2001 Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

## **National Property Inspections**



Guest Bathroom 134: So far all the exhaust fans seem to work



Guest Bathroom 134:



Guest Bathroom 134: GFCI installed and operational



Guest Bathroom 134:

### JDeeEn Inc. DBA

## **National Property Inspections**



Guest Bathroom 134:



Guest Bathroom 134:



Guest Bathroom 134: Slight mold and/or mildew present or caulk cracking at joint.



Guest Bathroom 134:



## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

CANDER DATABLE CONTROL					
GUEST BATHROOM 209	G	F	P	NI	NA
CEILINGS	$\square$				
WALL(S)					
WINDOWS/TRIM	Ø				
WINDOW SCREENS	Ø				
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST RECOMMENDED.)					
HEAT/AIR DISTRIBUTION	Ø				
COUNTERTOPS/CABINETS	Ø				
SINK/FAUCET	Ø				
TOILET	Ø				
TUB/SHOWER	Ø				
JETTED TUB					Ø
TILE WORK/ENCLOSURE	Ø				
EXHAUST FAN	Ø				
WATER PRESSURE/FLOW/DRAINAGE	Ø				

#### Comments:



Guest Bathroom 209:



Guest Bathroom 209: GFCI installed and operational

Inspection Date: Insp 01/01/2001 Insp

Inspector: J. William Naish Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

## **National Property Inspections**



Guest Bathroom 209:



Guest Bathroom 209:



Guest Bathroom 209:




Guest Bathroom 209: Slight mold and/or mildew present or caulk cracking at joint.



## **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999







Guest Bathroom 209:

GUEST BATHROOM 211	G	F	P	NI	NA
CEILINGS	Ø				
WALL(S)	Ø				
WINDOWS/TRIM	Ø				
WINDOW SCREENS	Ø				
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST RECOMMENDED.)	Ø				
HEAT/AIR DISTRIBUTION	Ø				
COUNTERTOPS/CABINETS	Ø				
SINK/FAUCET		Ø			
TOILET	Ø				
TUB/SHOWER	Ø				
JETTED TUB					Ø
TILE WORK/ENCLOSURE	Ø				
EXHAUST FAN	Ø				
WATER PRESSURE/FLOW/DRAINAGE					

#### Comments:

Inspection Date: Inspector: J. William Naish 01/01/2001 Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

## **National Property Inspections**



Guest Bathroom 211:



Guest Bathroom 211: GFCI installed and operational



Guest Bathroom 211: stopper missing



Guest Bathroom 211:



## **National Property Inspections**



Guest Bathroom 211: Slight mold and/or mildew present or caulk cracking at joint.



Guest Bathroom 211:



Guest Bathroom 211:



Guest Bathroom 211:



## **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

<b>GUEST BATHROOM 229</b>	☑ Recommend Repairs	G	F	P	NI	NA
CEILINGS	E Recommend Repairs	Ø	<u>г</u>		INI	NA D
CEILINGS		V	Ц	Ш	Ц	Ш
WALL(S)		$\square$				
WINDOWS/TRIM		V				
WINDOW SCREENS		V				
FLOOR/FINISH		V				
INTERIOR DOORS/HARDWARE		V				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURE	ES.)	V				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY	TEST RECOMMENDED.)	Ø				
HEAT/AIR DISTRIBUTION		V				
COUNTERTOPS/CABINETS		V				
SINK/FAUCET		V				
TOILET		V				
TUB/SHOWER				Ø		
JETTED TUB						Ø
TILE WORK/ENCLOSURE		V				
EXHAUST FAN		Ø				
WATER PRESSURE/FLOW/DRAINAGE		V				

#### Comments:

Shower/tub diverter broken, can't use shower



Guest Bathroom 229:



Guest Bathroom 229:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



## **National Property Inspections**



Guest Bathroom 229: GFCI installed and operational



Guest Bathroom 229:



Guest Bathroom 229: Slight mold and/or mildew present or caulk cracking at joint.



Guest Bathroom 229: Shower/tub diverter broken, can't use shower



## **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Guest Bathroom 229:



Guest Bathroom 229: Slight mold and/or mildew present or caulk cracking at joint.

GUEST BATHROOM 235	G	F	P	NI	NA
CEILINGS	Ø				
WALL(S)	Ø				
WINDOWS/TRIM	Ø				
WINDOW SCREENS	Ø				
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST RECOMMENDED.)	Ø				
HEAT/AIR DISTRIBUTION	Ø				
COUNTERTOPS/CABINETS	Ø				
SINK/FAUCET	Ø				
TOILET	Ø				
TUB/SHOWER	Ø				
JETTED TUB					Ø
TILE WORK/ENCLOSURE	Ø				
EXHAUST FAN	Ø				
WATER PRESSURE/FLOW/DRAINAGE	Ø				

Comments:

Inspection Date: Inspector: J. William Naish 01/01/2001 Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

## **National Property Inspections**



Guest Bathroom 235:



Guest Bathroom 235: GFCI installed and operational



Guest Bathroom 235: drain ok



Guest Bathroom 235:

### JDeeEn Inc. DBA

## **National Property Inspections**



Guest Bathroom 235:



Guest Bathroom 235:



Guest Bathroom 235: Slight mold and/or mildew present or caulk cracking at joint.



Guest Bathroom 235:



## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

<b>GUEST BATHROOM 241</b>	Recommend Repairs	G	F	P	NI	NA
CEILINGS		Ø				
WALL(S)		Ø				
WINDOWS/TRIM		$\square$				
WINDOW SCREENS		$\square$				
FLOOR/FINISH		Ø				
INTERIOR DOORS/HARDWARE		Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURE)	JRES.)			Ø		
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTH	ILY TEST RECOMMENDED.)	Ø				
HEAT/AIR DISTRIBUTION		$\square$				
COUNTERTOPS/CABINETS		Ø				
SINK/FAUCET			Ø			
TOILET		Ø				
TUB/SHOWER			Ø			
JETTED TUB						Ø
TILE WORK/ENCLOSURE		Ø				
EXHAUST FAN		Ø				
WATER PRESSURE/FLOW/DRAINAGE		Ø				

#### Comments:

Bathroom in room 241 has the wires crossed - the hot and neutral have been reversed.

Inspection Date: Insp 01/01/2001 Inspe

Inspector: J. William Naish Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

## **National Property Inspections**



Guest Bathroom 241: Bathroom in room 241 has the wires crossed - the hot and neutral have been reversed.



Guest Bathroom 241: GFCI installed and operational however the hot and neutral have been reversed.



Guest Bathroom 241: Sink drain stopper missing.



Guest Bathroom 241:



## **National Property Inspections**



Guest Bathroom 241:



Guest Bathroom 241: Shower diverter missing - could not turn on shower.



Guest Bathroom 241:



## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

CATACAT DA TANDO COMO ANO					
GUEST BATHROOM 258	G	F	P	NI	NA
CEILINGS	$\square$				
WALL(S)					
WINDOWS/TRIM	Ø				
WINDOW SCREENS					
FLOOR/FINISH					
INTERIOR DOORS/HARDWARE	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST RECOMMENDED.)					
HEAT/AIR DISTRIBUTION	Ø				
COUNTERTOPS/CABINETS	Ø				
SINK/FAUCET		Ø			
TOILET	Ø				
TUB/SHOWER	Ø				
JETTED TUB	Ø				
TILE WORK/ENCLOSURE	Ø				
EXHAUST FAN	Ø				
WATER PRESSURE/FLOW/DRAINAGE	Ø				

#### Comments:



Guest Bathroom 258: slow drain



Guest Bathroom 258: GFCI installed and operational

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

## **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Guest Bathroom 258:



Guest Bathroom 258: Slight mold and/or mildew present or caulk cracking at joint.



Guest Bathroom 258:



Guest Bathroom 258:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



## **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

GUEST BATHROOM 120	C	Е	D	NII	NT A
	G	F	P	NI	NA
CEILINGS	$\square$				
WALL(S)	☑				
WINDOWS/TRIM	Ø				
WINDOW SCREENS	Ø				
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST RECOMMENDED.)					
HEAT/AIR DISTRIBUTION	Ø				
COUNTERTOPS/CABINETS					
SINK/FAUCET					
TOILET	Ø				
TUB/SHOWER					
JETTED TUB					Ø
TILE WORK/ENCLOSURE	Ø				
EXHAUST FAN	Ø				
WATER PRESSURE/FLOW/DRAINAGE	Ø				

#### Comments:



Guest Bathroom 120:



Guest Bathroom 120:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

## **National Property Inspections**



Guest Bathroom 120:



Guest Bathroom 120:



Guest Bathroom 120:



Guest Bathroom 120: Slight mold and/or mildew present or caulk cracking at joint.

### JDeeEn Inc. DBA

## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Guest Bathroom 120: Slight mold and/or mildew present or caulk cracking at joint.

FRONT LOBBY	G	F	P	NI	NA
CEILINGS	Ø				
WALLS	Ø				
WINDOWS/TRIM	Ø				
WINDOW SCREENS	Ø				
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE					Ø
CLOSET					Ø
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
HEAT/AIR DISTRIBUTION	Ø				

Comments:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

## **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Front Lobby:



Front Lobby:



Front Lobby:



Front Lobby:

DECERTION ADEA/COUNTED					
RECEPTION AREA/COUNTER	G	F	P	NI	NA
CEILINGS	Ø				
WALLS	Ø				
WINDOWS/TRIM	Ø				
WINDOW SCREENS	Ø				
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
CLOSET	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
HEAT/AIR DISTRIBUTION	Ø				

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

#### Comments:



Reception Area/Counter:



Reception Area/Counter:



Reception Area/Counter:



Reception Area/Counter:

### JDeeEn Inc. DBA

## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Reception Area/Counter:



Reception Area/Counter:



Reception Area/Counter:

### MEETING ROOM - CURRENTLY BEING USED AS

BREAKFAST ROOM	Recommend Repairs	G	F	P	NI	NA
CEILINGS		☑				
WALLS		Ø				
WINDOWS/TRIM		Ø				
WINDOW SCREENS		Ø				
FLOOR/FINISH		Ø				
INTERIOR DOORS/HARDWARE		Ø				
CLOSET						Ø
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTUR	ES.)					

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



### **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

HEAT/AIR DISTRIBUTION

#### Comments:

Burnt power strip still plugged into wall. Recommend removal.



Meeting Room - currently being used as breakfast room:



Meeting Room - currently being used as breakfast room: Burnt power strip still plugged into wall. Recommend removal.



Meeting Room - currently being used as breakfast room:



Meeting Room - currently being used as breakfast room:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

## **National Property Inspections**



Meeting Room - currently being used as breakfast room:



Meeting Room - currently being used as breakfast room:



Meeting Room - currently being used as breakfast room:



## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

EXERCISE ROOM	G	F	P	NI	NA
CEILINGS	Ø				
WALLS	Ø				
WINDOWS/TRIM	Ø				
WINDOW SCREENS	Ø				
FLOOR/FINISH					
INTERIOR DOORS/HARDWARE	Ø				
CLOSET					Ø
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
HEAT/AIR DISTRIBUTION	Ø				

#### Comments:



Exercise Room:



Exercise Room:

Email: j@npi-sd.com

Inspection Date: Inspector: J. William Naish 01/01/2001

### JDeeEn Inc. DBA

## **National Property Inspections**



Exercise Room:



Exercise Room:



Exercise Room: Random sampling of electrical outlets indicated proper operation.



Exercise Room:



## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999







Exercise Room:

TEMPORARY KITCHEN/COOLERS/STORAGE/WARMING ROOM	G	F	P	NI	NA
CEILINGS	V				
WALLS	Ø				
WINDOWS/TRIM					Ø
WINDOW SCREENS					Ø
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
CLOSET					Ø
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
HEAT/AIR DISTRIBUTION	V				

#### Comments:

Make-shift area where continental breakfast items are stored and refrigerated while kitchen undergoes major remodeling.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

## **National Property Inspections**



Temporary Kitchen/Coolers/Storage/Warming Room:



Temporary Kitchen/Coolers/Storage/Warming Room:



Temporary Kitchen/Coolers/Storage/Warming Room:



Temporary Kitchen/Coolers/Storage/Warming Room:

#### JDeeEn Inc. DBA

## **National Property Inspections**



Temporary Kitchen/Coolers/Storage/Warming Room:



Temporary Kitchen/Coolers/Storage/Warming Room: Cooler not operational.



Temporary Kitchen/Coolers/Storage/Warming Room: Food maintained in acceptable "cool" range indicating functional refrigeration.



Temporary Kitchen/Coolers/Storage/Warming Room: Food maintained in acceptable "cool" range indicating functional refrigeration.



## **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

DINING ROOM	G	F	P	NI	NA
CEILINGS				Ø	
WALLS				V	
WINDOWS/TRIM				V	
WINDOW SCREENS				V	
FLOOR/FINISH				V	
INTERIOR DOORS/HARDWARE				V	
CLOSET				Ø	
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)				V	
HEAT/AIR DISTRIBUTION				Ø	

#### Comments:

Dining Room vacant and unused during kitchen remodel.







Dining Room:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

## **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Dining Room:



Dining Room:



Dining Room:



Dining Room:



Dining Room:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



### **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

GUEST ROOM 104 (HANDICAPPED)	G	F	P	NI	NA
CEILINGS					
WALLS	Ø				
WINDOWS/TRIM	Ø				
WINDOW SCREENS	Ø				
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
CLOSET	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)		Ø			
HEAT/AIR DISTRIBUTION	Ø				
RUNNING WATER			Ø		

#### Comments:

Bar sink drains slow. Refrigerator and microwave appear operational. Hot water present Water pressure good. **No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 6 feet of sink.** This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.



Guest Room 104 (handicapped):



Guest Room 104 (handicapped):

#### JDeeEn Inc. DBA

# **National Property Inspections**



Guest Room 104 (handicapped): Newer style HVAC wall unit operational at time of inspection.





Guest Room 104 (handicapped):



Guest Room 104 (handicapped): Refrigerator and microwave appear operational. Hot water present Water pressure good. No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 5 feet of sink. This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.

### JDeeEn Inc. DBA

# **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Guest Room 104 (handicapped): Water slow to drain from sink.



Guest Room 104 (handicapped):

GUEST ROOM 114	G	F	P	NI	NA
CEILINGS	Ø				
WALLS	V				
WINDOWS/TRIM	V				
WINDOW SCREENS	V				
FLOOR/FINISH	V				
INTERIOR DOORS/HARDWARE	V				
CLOSET	V				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)		Ø			
HEAT/AIR DISTRIBUTION	V				

#### Comments:

Vinyl windows difficult to open. (typical)

Refrigerator and microwave appear operational. Hot water present Water pressure good. **No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 6 feet of sink.** This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

# NPI.

## JDeeEn Inc. DBA

# **National Property Inspections**



Guest Room 114:



Guest Room 114:



Guest Room 114:



Guest Room 114: Older style HVAC wall air conditioner separating from wall slightly. Unit was operational at time of inspection.

#### JDeeEn Inc. DBA

# **National Property Inspections**



Guest Room 114:



Guest Room 114:



Guest Room 114:



Guest Room 114: Refrigerator and microwave appear operational. Hot water present Water pressure good. No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 5 feet of sink. This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.



# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

GUEST ROOM 119	G	F	P	NI	NA
CEILINGS	Ø				
WALLS	Ø				
WINDOWS/TRIM	Ø				
WINDOW SCREENS	Ø				
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
CLOSET	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)		Ø			
HEAT/AIR DISTRIBUTION	Ø				
RUNNING WATER			Ø		

#### Comments:

Bar sink slow to drain. **No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 6 feet of sink.** This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.



Guest Room 119:



Guest Room 119:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

#### JDeeEn Inc. DBA

# **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Guest Room 119:



Guest Room 119: Sink slow to drain



Guest Room 119: Refrigerator and microwave appear operational. Hot water present Water pressure good. No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 6 feet of sink. This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.



Guest Room 119: Older style HVAC wall unit functional at time of inspection.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999







Guest Room 119:

GUEST ROOM 134	G	F	P	NI	NA
CEILINGS	Ø				
WALLS	Ø				
WINDOWS/TRIM	V				
WINDOW SCREENS	Ø				
FLOOR/FINISH	V				
INTERIOR DOORS/HARDWARE	Ø				
CLOSET	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)		Ø			
HEAT/AIR DISTRIBUTION	Ø				
RUNNING WATER					

#### Comments:

No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 6 feet of sink. This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

# NPI.

#### JDeeEn Inc. DBA

# **National Property Inspections**



Guest Room 134:



Guest Room 134:



Guest Room 134:



Guest Room 134: Refrigerator and microwave appear operational. Hot water present Water pressure good. No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 5 feet of sink. This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.

## JDeeEn Inc. DBA

# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Guest Room 134: Sink slow to drain.



Guest Room 134: Newer style HVAC wall unit operational at time of inspection.



Guest Room 134:



Guest Room 134:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



# **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

GUEST ROOM 209	G	F	P	NI	NA
CEILINGS	Ø				
WALLS	Ø				
WINDOWS/TRIM	Ø				
WINDOW SCREENS	Ø				
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
CLOSET	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)		Ø			
HEAT/AIR DISTRIBUTION	Ø				
RUNNING WATER			Ø		

#### Comments:

Bar sink slow to drain. No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 6 feet of sink. This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.



Guest Room 209:



Guest Room 209: Refrigerator and microwave appear operational. Hot water present Water pressure good. No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 5 feet of sink. This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

# NPI.

## JDeeEn Inc. DBA

# **National Property Inspections**



Guest Room 209: Sink slow to drain.



Guest Room 209:



Guest Room 209: Steel windows difficult to open. Newer style HVAC wall unit operational at time of inspection.



Guest Room 209:

## JDeeEn Inc. DBA

# **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999







Guest Room 209:

GUEST ROOM 211	G	F	P	NI	NA
CEILINGS	V				
WALLS	V				
WINDOWS/TRIM	Ø				
WINDOW SCREENS	V				
FLOOR/FINISH	V				
INTERIOR DOORS/HARDWARE	Ø				
CLOSET	V				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)		Ø			
HEAT/AIR DISTRIBUTION	V				

#### Comments:

No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 6 feet of sink. This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

### JDeeEn Inc. DBA

# **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Guest Room 211:



Guest Room 211: Refrigerator and microwave appear operational. Hot water present Water pressure good. No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 6 feet of sink. This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.



Guest Room 211:



Guest Room 211: Newer HVAC wall unit operational at time of inspection.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

## JDeeEn Inc. DBA

# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Guest Room 211:



Guest Room 211: Slight tear in wallpaper.



Guest Room 211:



Guest Room 211:

GUEST ROOM 229	G	F	P	NI	NA
CEILINGS	Ø				
WALLS	Ø				
WINDOWS/TRIM	Ø				
WINDOW SCREENS	Ø				
FLOOR/FINISH					
INTERIOR DOORS/HARDWARE	Ø				
CLOSET					
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)		Ø			
HEAT/AIR DISTRIBUTION	Ø				

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

#### JDeeEn Inc. DBA

# **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

#### Comments:

No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 6 feet of sink. This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.



Guest Room 229:



Guest Room 229: Refrigerator and microwave appear operational. Hot water present Water pressure good. No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 6 feet of sink. This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.



Guest Room 229:



Guest Room 229:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

# NPI.

## JDeeEn Inc. DBA

# **National Property Inspections**



Guest Room 229: Newer style HVAC wall unit operational at time of inspection.



Guest Room 229:



Guest Room 229:



Guest Room 229: Wallpaper peeling at seams.



# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

<b>GUEST ROOM 235</b>	☑ Recommend Repairs	G	F	P	NI	NA
CEILINGS	<u> </u>			Ø		
WALLS		Ø				
WINDOWS/TRIM		Ø				
WINDOW SCREENS		Ø				
FLOOR/FINISH		Ø				
INTERIOR DOORS/HARDWARE		Ø				
CLOSET		Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)			Ø			
HEAT/AIR DISTRIBUTION		Ø				

#### Comments:

Incomplete patch around ceiling fire sprinkler & masking tape on wallpaper seam.



Guest Room 235:



Guest Room 235:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

# NPI.

## JDeeEn Inc. DBA

# **National Property Inspections**



Guest Room 235:



Guest Room 235:



Guest Room 235: Newer HVAC wall unit was operational at time of inspection.



Guest Room 235:



# **National Property Inspections**

#### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Guest Room 235: Incomplete patch around ceiling fire sprinkler & masking tape on wallpaper seam.



Guest Room 235: typical this room wallpaper seams pealing

GUEST ROOM 241	G	F	P	NI	NA
CEILINGS	Ø				
WALLS	V				
WINDOWS/TRIM	V				
WINDOW SCREENS	Ø				
FLOOR/FINISH	V				
INTERIOR DOORS/HARDWARE	V				
CLOSET	V				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	V				
HEAT/AIR DISTRIBUTION	☑				

#### Comments:

No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 6 feet of sink. This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

# NPI.

#### JDeeEn Inc. DBA

# **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Guest Room 241:



Guest Room 241: Drain slow to drain. Hot water handle nameplate missing.



Guest Room 241: Refrigerator and microwave appear operational. Hot water present Water pressure good. No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 6 feet of sink. This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.



Guest Room 241:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



# **National Property Inspections**



Guest Room 241: Newer style HVAC wall unit was operational at time of inspection.



Guest Room 241:



Guest Room 241: Wallpaper seam separating



Guest Room 241:



# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

GUEST ROOM 258	G	F	P	NI	NA
CEILINGS	V				
WALLS	V				
WINDOWS/TRIM	Ø				
WINDOW SCREENS	Ø				
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
CLOSET	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)		Ø			
HEAT/AIR DISTRIBUTION	Ø				

#### Comments:



Guest Room 258:



Guest Room 258: Light over sink inoperable

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

#### JDeeEn Inc. DBA

# **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Guest Room 258: Refrigerator and microwave appear operational. Hot water present Water pressure good. No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 5 feet of sink. This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.



Guest Room 258:



Guest Room 258: Newer style HVAC wall unit operational at time of inspection.



Guest Room 258:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

## JDeeEn Inc. DBA

# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999







Guest Room 258:

GUEST ROOM 120	G	F	P	NI	NA
CEILINGS	Ø				
WALLS					
WINDOWS/TRIM	☑				
WINDOW SCREENS					
FLOOR/FINISH	☑				
INTERIOR DOORS/HARDWARE					
CLOSET	☑				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)		Ø			
HEAT/AIR DISTRIBUTION	☑				
RUNNING WATER			Ø		

#### Comments:

Low water pressure. No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 6 feet of sink. This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

#### JDeeEn Inc. DBA

# **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Guest Room 120: Low water pressure.
Refrigerator and microwave appear operational. Hot water present. No Ground Fault Circuit Interrupter (GFCI) on electrical outlet within 6 feet of sink. This may or may not be grand-fathered in due to age of building, Suggest contacting a professional licensed electrical contractor for review.



Guest Room 120:



Guest Room 120:



Guest Room 120:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

# NPI.

## JDeeEn Inc. DBA

# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Guest Room 120: Older style HVAC wall unit operational at time of inspection.



Guest Room 120:



Guest Room 120:



Guest Room 120:

### FIRST FLOOR LOBBY STAIRS

Comments:
-----------

G	F	P	NI	NA
Ø				

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

# NPI.

## JDeeEn Inc. DBA

# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



First Floor Lobby Stairs:



First Floor Lobby Stairs:



First Floor Lobby Stairs:



G

 $\sqrt{}$ 

First Floor Lobby Stairs:

## FIRST FLOOR HALLWAYS

$\cap r$	n	m	<b>A1</b>	nts	•

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848 Email: j@npi-sd.com

NI

NA

## JDeeEn Inc. DBA

# **National Property Inspections**



First Floor Hallways:



First Floor Hallways:



First Floor Hallways:



First Floor Hallways: Executive workspace at corner to intersecting hallways.

# NPI.

## JDeeEn Inc. DBA

# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



First Floor Hallways:



First Floor Hallways: Automatic fire doors, typical.



First Floor Hallways:



First Floor Hallways: Emergency lighting during power failure throughout. Typical.

G

 $\overline{\mathbf{Q}}$ 

## FIRST FLOOR NORTH STARWAY

Comments:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848 Email: j@npi-sd.com

NI

NA

## JDeeEn Inc. DBA

# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



First Floor North Starway:



First Floor North Starway:



First Floor North Starway:



First Floor North Starway:



First Floor North Starway:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

### SOUTHWEST FIRST FLOOR STAIRWAY

G	F	P	NI	NA
V				

#### Comments:



Southwest First Floor Stairway:



Southwest First Floor Stairway:



Southwest First Floor Stairway:

## SECOND FLOOR HALLWAY

G	F	P	NI	NA
V				

Comments:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

## JDeeEn Inc. DBA

# **National Property Inspections**


## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Second Floor Hallway:



Second Floor Hallway:



Second Floor Hallway:



Second Floor Hallway:



Second Floor Hallway:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



# **National Property Inspections**

### Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

SWIMMING POOL EQUIPMENT		F	P	NI	NA
HEATER ☑Gas	Ø				
FILTER	Ø				
PUMP(S)	Ø				
ELECTRICAL	Ø				

#### Comments:

NOTE: Pool Bodies, Diving Boards, Slides, Self-Cleaning & Chlorinating Devices are beyond the scope of this inspection.



Swimming Pool Equipment : Diatomaceous earth used as filter media.



Swimming Pool Equipment: Spa gas heater.



Swimming Pool Equipment: Pool gas heater.



Swimming Pool Equipment:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

## JDeeEn Inc. DBA

# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Swimming Pool Equipment: Inspection portal shows no "bubbles" indicating no leak within the system.



Swimming Pool Equipment: Pump room electrical sub panel and low voltage time clocks.



Swimming Pool Equipment: Boxes of Muriatic Acid used for cleaning.

SAFETY/SIGNAGE/ADA	G	F	P	NI	NA
SAFETY/SIGNAGE/ADA	Ø				
ANTI ENTRAPMENT COVERS	Ø				
SKIMMER EQUIPMENT	Ø				
LADDERS AND HANDRAILS	Ø				
HANDICAP/ADA CHAIR LIFT	Ø				

#### Comments:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

## JDeeEn Inc. DBA

# **National Property Inspections**




Safety/Signage/ADA: Emergency switch located close to hot tub.



Safety/Signage/ADA: Drowning safety equipment present.



Safety/Signage/ADA:



Safety/Signage/ADA: Chemical testing log present.


## JDeeEn Inc. DBA

# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Safety/Signage/ADA: Dual suction intake drains located minimum 5 feet apart.



Safety/Signage/ADA: Skimmer basket



Safety/Signage/ADA: Handrail & steps entering pool



Safety/Signage/ADA:

#### **POOL & COPING**

☑ Plaster / Shotcrete	☑In Ground					
		G	F	P	NI	NA
SHELL/LINER/HARDCOAT		Ø				
DECK/APRON		Ø				

#### Comments:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

## JDeeEn Inc. DBA

# **National Property Inspections**

# Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Pool & Coping:



Pool & Coping:



Pool & Coping:



Pool & Coping:



Pool & Coping:



Pool & Coping:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

## JDeeEn Inc. DBA

# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Pool & Coping:

DOOL FENCING					
POOL FENCING	G	F	P	NI	NA
CHILD SAFETY FENCE	Ø				
CHILD SAFETY GATE	Ø				

#### Comments:



Pool Fencing: Auto-close, self locking fence gate operational



Pool Fencing: Small pool house holds operating equipment.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



# **National Property Inspections**



Pool Fencing:



Pool Fencing:



Pool Fencing:



# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

#### **HOT TUB / SPA**

☑Built-In	☑Outdoor					
		G	F	P	NI	NA
HEATER		✓				
PUMP(S)		$\square$				
BLOWER		☑				
ELECTRICAL		$\square$				
LIGHT(S)		$\square$				
GFCI (CHECKED W/TES	T BUTTON ONLY).	☑				
SHELL/FRAME		$\square$				
HANDRAIL		☑				
HANDICAP/ADA EQUIP	MENT	☑				

#### Comments:

NOTE: Spa Bodies are beyond the scope of this inspection.



Hot Tub / Spa: Whirlpool & aeration operational.



Hot Tub / Spa:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848

## JDeeEn Inc. DBA

# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Hot Tub / Spa: Yellow arrow indicates emergency shut-off switch & timer.



Hot Tub / Spa: ADA assistance chair device for hot tub/spa.



Hot Tub / Spa:

DUMPSTER ENCLOSURE		F	P	NI	NA
EXTERIOR FINISH	Ø				
STRUCTURAL	Ø				

#### Comments:

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



# **National Property Inspections**



Dumpster Enclosure:



Dumpster Enclosure:



Dumpster Enclosure:



3

5

# JDeeEn Inc. DBA

# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999





Kitchen under construction.



Kitchen under construction.



Kitchen under construction.



Kitchen under construction.



Kitchen under construction.



Kitchen under construction.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

7



Kitchen under construction.

9



Exterior door has been covered up in new kitchen. See next interior photo.

8



Kitchen under construction.

10



Interior wall which used to be exterior doors as shown in the previous photo.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999





Exterior grease trap for new kitchen being installed, not complete.





Typical emergency egress lighting.

13



Security camera inside dining room.

14



Roofing

15



Roofing

16



Roofing

Email: j@npi-sd.com

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



# **National Property Inspections**

# Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999



Roofing

19



Roofing



Low voltage wiring pipe chase.

Inspection Date: 01/01/2001

Inspector: J. William Naish Inspector Phone: 858.888.0848



# **National Property Inspections**

## Website Sample Commercial, 1234 Main Ave., San Diego, CA, 99999

**INVOICE #: TEMPLATE** 

Client Name: John Smith

Website Sample Commercial

Inspection Date: 1/1/2001 12:00 AM

Property Location: 1234 MAIN AVE.

ID. E. L. BDA

SAN DIEGO CA 99999

JDeeEn Inc. DBA National Property Inspections

Billing Address:

1234 Main Ave.

4275 Executive Square

San Diego CA 99999

Suite 200 La Jolla 92037

Client Phone: (858) 888-0848 Client Email: j@npi-sd.com

#### TYPE OF INSPECTIONS PERFORMED

TYPE OF INSPECTIONS PERFORMED		
Full Property Assessment of Hotel located at above address		\$2,295.00
	Total	\$2,295.00
12/13/2017	Check	\$0.00
	Amount Due	\$2,295.00

Inspection Date: Inspector: J. William Naish

01/01/2001 Inspector Phone: 858.888.0848