

Home Inspection Report

Prepared for: Sample Client

123 Main St Somewhere, USA 12345



Inspected by: NPI Inspector National Property Inspections Inspection Date: 6/22/2023



Sample Client Page 6 of 41

Maintenance Summary

This summary page is provided for convenience and is not a substitute for reading the entire report and should not be relied upon as the complete list for the client's reference.

A home inspector may not report on the market value or marketability of a property or whether a property should or should not be purchased.

Maintenance Definition: Maintenance of the item is recommended to prevent premature failure or to maintain its functionality.

Lots and Grounds

Grading: Minor slope	Recommend maintain dirt as r	needed to provide proper drainage away from the building.	
Window Wells/Egress: м	etal Recommend clea	n debris from window wells.	
Trees/Shrubs at Building	J: Bushes, Vegetation	Recommend trim bushes away from the house.	
Exterior Surface and Components			

Entire Exterior Surface Type: Aluminum siding, Brick veneer Tuck point maintenance is required. Soffit/ Fascia: Aluminum, Wood There is loose trim present on the South side.

Roof

Leaders/Extensions: Aluminum, Corrugated plastic Recommend add proper aluminum leaders where missing and ensure all leaders extend 6 feet beyond the foundation perimeter.

Middle of roof Chimney Chase/Cap/Flue: Brick chase, Concrete cap, Clay flue, Metal cap There are cracks present in the mortar joints which require tuck point maintenance.

Plumbing

Sump Pump / Exterior Discharge: Pedestal The sump pump motor was noisy when operated. The unit maybe nearing the end of its functional life.

Air Conditioning

Main AC System Refrigerant Lines: Serviceable condition There is torn/missing insulation observed. Finished Rooms

Living Room, Kitchen, Dining Areas, Bedrooms, Bathrooms, Basement Rec Room Finished Room Doors: Wood The 2nd floor NW bedroom door has minor damage present.

Living Room, Kitchen, Dining Areas, Bedrooms, Bathrooms, Basement Rec Room Finished

Room Windows: Vinyl casement, Fixed, Vinyl double hung Several of the window sashes do not properly operate. Maintenance is required. This is common with casement type windows that are not continually utilized. Recommend a qualified contractor inspect and repair/ replace as needed.

Bathroom

2nd Floor - Full Bathroom Fixtures/Plumbing: PVC, Brush Nickel faucet The shower diverter is not functioning properly, all water is not flowing to showerhead. Caulk tub diverter and/ or faucet as needed.



Table of Contents		
Definitions	11	
General Information	11	
Overview Pictures	13	
Lots and Grounds	17	
Exterior Surface and Components		
Roof	20	
Garage	23	
Attic	23	
Structure	25	
Basement	26	
Fireplace	26	
Plumbing	27	
Electrical	30	
Heating System	33	
Air Conditioning	34	
Finished Rooms	35	
Bathroom	36	
Kitchen	38	
Laundry Room/ area	39	
Environmental	39	
Final Comments	41	



Overview Pictures (Continued)

Overview Pictures: (continued)



5. Overview Pictures: Garage



Lots and Grounds

EXTERIORS - LOTS AND GROUNDS (a) A home inspector shall observe and describe the condition of all of the following: ... 5. Decks, balconies, stoops, steps and porches including railings. ... 7. Grading, drainage, driveways, patios, walkways, and retaining walls that abut the dwelling unit. (c) A home inspector is not required to observe the following: ... 4. Fences or privacy walls. ... 8. Geological or soil conditions. 9. Recreational facilities. 10. Out-buildings other than garages and carports. 11. Trees, shrubs and other vegetation.

Note: Grade should remain a minimum of 6" below existing siding. Promote positive drainage away from the foundation and extend runoff from roofing and downspouts a minimum of 6' from foundation. Building standards have changed throughout the years. The deck / porch / balcony attachment to the structure requires certain construction methods to comply with current standards. It may be common due to the age of the home / structure and current building standards that the deck / porch / balcony may not be attached with proper components. It is common in older deck / porch systems for the vertical wood support posts to be buried below grade. This is no longer a recognized building practice. Not all of the footings maybe visible at the time of inspection. The attached structure(s) are NOT inspected to current code as it is out of the scope of the inspection to do so.

- 1. Functional Driveway: Asphalt
- 2. Functional Walkways: Concrete, Brick
- 3. Functional Steps/Stoops/Railings: Concrete
- 4. Not Present Porch: Not present
- 5. Functional Patio: Concrete
- 6. Not Present Deck: Not present
- 7. Not Present Balcony: Not present
- 8. Maintenance Grading: Minor slope
- from the building.

Recommend maintain dirt as needed to provide proper drainage away

Sample Client Page 28 of 41



Plumbing (Continued) Drain/Vent Pipes: PVC 5. Functional Drain/Vent Pipe Supports: Metal, Plastic 6. Functional 7. Functional Floor Drain: Surface drain 8. Functional Gas Meter: Exterior mount Gas Service Lines: Black pipe 9. Functional Note: There are no gas leaks observed at time of inspection. Gas Service Line Supports: Metal 10. Functional Sump Pump / Exterior Discharge: Pedestal 11. Maintenance The sump pump motor was noisy when operated. The unit maybe nearing the end of its functional life. 12. Not Inspected Grey Water Crock: Not visible The grey water crock/pump has a sealed cover, unable to test pump for operation or inspect components inside pit. Lateral Clean-out: Accessible 13. Functional 14. Not Inspected





Sample Client Page 38 of 41

Kitchen

INTERIORS. (a) A home inspector shall observe and describe the condition of all of the following: 1. Walls, ceilings and floors. 2. Steps, stairways, balconies and railings. 3. Counters and all sink base cabinets. 4. A random sample of doors and windows. 5. Separation walls, ceilings, and doors between a dwelling unit and an attached garage or another dwelling unit. 6. Signs of water penetration into the building or signs of abnormal or harmful condensation on building components. (b) A home inspector is not required to observe any of the following: 1. Paint, wallpaper, and other cosmetic finish treatments on the interior walls, ceilings and floors. 2. Carpeting. 3. Draperies, blinds or other window treatments. 4. Household appliances. 5. Recreational facilities or another dwelling unit.

Note: The inspection does not cover any damage concealed by rugs, carpeting, wall paneling, furniture or fixtures. Typical wall/ ceiling minor cracks/ touch-ups are considered minor and are not included in the report.

1st Floor Kitchen -

- 1. Functional
- 2. Functional

Refrigerator: General Electric Cooking Appliances: General Electric

- 3. Functional
- 4. Functional
- 5. Not Inspected

Ventilator: Allure Dishwasher: Bosch Not inspected due to contents inside the appliance. Recommend verify with the seller for proper operation before closing.





- 6. Functional
- 7. Functional
- 8. Functional
- 9. Functional

Air Gap Present: Yes

Microwave: Panasonic

- Counter/Cabinet: Solid Surface, Granite, Wood
 - Fixtures/Plumbing: PVC, Chrome faucet
 - Sink/Basin: Molded single bowl