

National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712



Monday, September 23, 2019
Inspector
Dave Faber
(479) 777-1007
dave.faber@npiinspect.com

Inspection Date: 09/23/2019

Inspector: Dave Faber

Inspector Phone: (479) 777-1007



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712

GENERAL INFORMATION

GENERAL CONDITIONS AT TIME OF INSPECTION:

Property Occupied: Yes Estimated Age Of Property: 19 Year(s) Property Faces: □ North ☑ South □ East □ West	Temperature: 85 F Weather: ☑ Sunny
Type of Property: ☑ Single-Family Primary Construction: ☑ Poured Concrete	Soil Conditions : ☑ Dry Persons Present :

DEFINITIONS:

Below are listed the definitions used throughout the report to describe each feature of the property.

ACC (ACCEPTABLE) The item/system was performing its intended function at the time of the inspection.

MAR (MARGINAL) The item/system was marginally acceptable. It performed its designed function at the time of the

inspection. However, due to age and/or deterioration, it will likely require early repair or replacement.

NI (NOT INSPECTED) The item/system was not inspected due to safety concerns, inaccessibility and/or concealment or seasonal

conditions and no representations of whether or not it was functioning as intended were made.

NP (NOT PRESENT) The item/system does not exist or was visually concealed at the time of the inspection.

RR (REPAIR/REPLACE) The item/system failed to operate/perform its intended function, was structurally deficient, was unsafe or

was hazardous at the time of the inspection.

SCOPE OF THE INSPECTION:

We wish to remind you that every property requires a certain amount of ongoing maintenance: drains sometimes clog, gutters, downspouts and the grading around the property must be properly maintained to help prevent water intrusion in to the basement or crawlspace; roofs, furnaces, air conditioners and other components require regular maintenance and inspection. This property will be no exception and we strongly suggest that you both expect and budget for regular maintenance/repairs.

The following report is based on visual inspection of the readily accessible areas of this property and on a random sampling of like items, <u>not every item was or could be inspected</u>. Please read the entire report carefully, ask your inspector any questions you might have <u>and obtain estimates or discuss noted items with a contractor before</u> closing.

Inspection Date: Inspector: Dave Faber Email: dave.faber@npiinspect.com



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712

GRADING / DRAINAGE

ACC MAR NI NP RR
☑ □ □ □ □

☑Near Level

Comments:



Grading / Drainage: West Side of Home



Grading / Drainage: East Side of House



Grading / Drainage: Deck in Back of Home



Grading / Drainage: Off Lower Deck

Inspection Date: 09/23/2019

Inspector: Dave Faber

Inspector Phone: (479) 777-1007



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712

	ACC	MAR	NI	NP	RR
DRIVEWAY	V				

☑ Concrete

Comments:

Driveway slopes towards the garage and appears to have adequate drainage.



Driveway: Driveway drain

WALKS / STEPS	ACC MAR NI NP RR
☑ Concrete	
Comments:	
	ACC MAR NI NP RR
PORCHES / STOOPS	ACC MAR NI NP RR
PORCHES / STOOPS ☑ Open	

Inspection Date: 09/23/2019

Inspector: Dave Faber

Inspector Phone: (479) 777-1007



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712

DECKS / BALCONY ACC MAR NI NP RR DECKS / BALCONY

☑ Wood

Comments:



Decks / Balcony: Lower Deck



Decks / Balcony: Upper Deck

RETAINING WA	LLS		ACC MAR NI NP RR
☑ Sides	☑Block		
Comments:			
ROOFING			ACC MAR NI NP RR
Age: < 5 Year(s)	Design Life: 15-20 Year(s)	Layers: 1	90% Visible
☑ Walked On	☑ Asphalt / Composition		

Comments:

Inspection does not guarantee insurability. This inspection is made on the basis of what is visible and accessible at the time of the inspection and is not a warranty of the roof system or how long it will be watertight in the future.

Leaks not always detectable.

Inspection Date: Inspector: Dave Faber Email: dave.faber@npiinspect.com



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712



Roofing: Roof #1



Roofing: Roof #3



Roofing: Garage Roof Front



Roofing: Roof #2



Roofing: Garage Front Roof



Roofing: Roof towards back of lot

Inspection Date: 09/23/2019

Inspector: Dave Faber

Inspector Phone: (479) 777-1007



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712

FLASHING/VALLEYS		ACC ☑	MAR	NI	NP	RR
☑ Composition / Membrane ☑ Metal						
Comments:						
CUTTEDS/DOWN SDOUTS	Man da i		MAR	NI	NP	RR
GUTTERS/DOWN SPOUTS	☑ Recommend Repairs					

Comments:

Downspout on West side of home is disconnected and should be repaired to avoid drainage from seeping into foundation. Recommend further evaluation/repair by qualified contractor(s).



Gutters/Down Spouts: Downspout disconnected

		ACC	MAR	NI	NP	RR
CHIMNEY		\square				
☑ Framed	✓ Stone Vaneer					

Comments:

Inspection of Chimney is limited to that portion of flue visible above chimney cap or from fireplace damper. Unable to determine if flashing exists around stone chimney and roofing. Caulking was present on 3 of the 3 sides inspected.

Flue not inspected. Annual cleaning is recommended.

Inspection Date: Inspector: Dave Faber Email: dave.faber@npiinspect.com



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712



Chimney: Unable to see flashing



Chimney: Unable to see flashing



Chimney:

EXTERIOR SURFACE

☑ Monitor Condition

⊻ Metal	✓ Synthetic Stucco	✓ Stone Veneer					
			ACC	MAR	NI	NP	RR
SIDING/TRIM				Ø			
EXTERIOR FAUCETS			Ø				
EXTERIOR ELECTRICAL O	UTLETS		Ø				
EXTERIOR LIGHTING			Ø				

Comments:

Inspection Date: Ins 09/23/2019 Ins

Inspector: Dave Faber

Inspector Phone: (479) 777-1007



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712

Synthetic Stucco identified on front and West side of home. Recommend trimming back bushes at least 18" from the synthetic stucco surface to avoid moisture related issues.

Front also has stone veneer with not visible cracks.

Aluminum siding and trim around house appear to be functional with no significant visible damage.



Exterior Surface:



Exterior Surface:

			ACC	MAR	NI	NP	RR
WINDOWS		Recommend Repairs					Ø
✓Vinyl	☑ Insulated Pane(s)	☑ Needs Caulk / Seal					

Comments:

Front window on West side has a crack near the bottom that could allow moisture to seep in and cause deterioration. Recommend repair by qualified window contractor.



Windows: Cracked Window sill

Inspection Date: Inspector: Dave Faber

09/23/2019 Inspector Phone: (479) 777-1007



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712

	ACC	MAR	NI	NP	RR
EXTERIOR DOORS	\square				
☑Wood		·			
Comments:					
	ACC	MAR	NI	NP	RR
FOUNDATION	\square				

Comments:

☑ Concrete

Vegetation growing on or near the exterior walls may obstruct view and limit inspection. It may introduce pests and/or accelerate deterioration of exterior wall covering by retaining moisture. Landscaping materials, plants and shrubs may retain moisture against foundation and effects the soils ability to support the foundation. Suggest all landscaping materials, plants, and shrubs maintain 18" clearance from foundations. Inspection of foundation is limited to that which is visible. Where possible, I inspect the portion of the foundation visible at the home exterior between grade and the bottom of the exterior wall covering. Shrinkage cracks are often visible and are not a structural concern.



☑ Slab

Foundation:



Foundation:

Inspection Date: Inspector: Dave Faber Email: dave.faber@npiinspect.com

Inspector Phone: (479) 777-1007

09/23/2019 ©**1996-2019**



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712

GARAGE/CARPORT

☑2 Cars ☑ Attached					
	ACC	MAR	NI	NP	RR
FLOOR/WALLS/CEILING/ELECTRICAL	☑				
ROOF	Ø				
SIDING/TRIM	Ø				
ELECTRICAL			Ø		

Comments:

Not all electrical receptacles were tested for GFCI because personal belongings did not allow inspector to identify GFCI plug to reset.



Garage/Carport:



Garage/Carport:



Garage/Carport:



Garage/Carport:

Inspection Date: Inspector: Dave Faber

09/23/2019 Inspector Phone: (479) 777-1007



National Property Inspections

123 Arkansas Dr., Bent	conville, AR 72712	
OVERHEAD GARAGE DOORS		ACC MAR NI NP RR
# of Openers: 1		
☑Metal		
Comments:		
		ACC MAR NI NP RR
GARAGE PEDESTRIAN DOOR INTO HOUSE	☑ Monitor Condition	

✓ Metal

Comments:

Any door between the house and the garage should have an automatic door closer that is tight fitting and weatherstripped for fire safety and to reduce the chance of gasoline or exhaust fumes entering the home however it was not needed at the time of construction of this home. Recommend installation of auto-closure unit.



Garage Pedestrian Door into House: No Auto-Closer

Inspection Date: Inspector: Dave Faber Email: dave.faber@npiinspect.com Inspector Phone: (479) 777-1007 09/23/2019

©1996-2019



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712

Attic	/	Ro	of

Method of Inspection
☐ Physical Entry 80 % Visible

ATTIC FRAMING/SHEATHING

ACC MAR NI NP RR
☑ □ □ □ □

☑ Plywood / Panel Board / OSB

SB ☑Rafters

Comments:

Leaks not always detectable.



Attic Framing/Sheathing:

ATTIC VENT	ILATION	ACC MAR NI NP RR
✓Soffit	☑ Static Vent	
Comments:		
	A.T.Y.O.Y.	ACC MAR NI NP RR
ATTIC INSUL	LATION	ACC MAR NI NP RR ☑ □ □ □ □

Inspection Date: 09/23/2019

Comments:

Inspector: Dave Faber

Inspector Phone: (479) 777-1007



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712

		ACC	MAR	NI	NP	RR
ATTIC ELECTRICAL	☑ Recommend Repairs					Ø

☑ Open Splices / Junction Boxes


Comments:

Unable to inspect all electrical componants in the attic due to insulation cover and/or obstructed view.

One or more junction boxes visible in the attic was missing a cover plate at the time of the inspection. This is a shock/potential fire hazard.

Recommend further evaluation/repair by qualified electrical contractor(s).

Limited visibility due to obstructions. See Electrical Section for additional Information.



Attic Electrical:

Interior Foundation

Foundation Type
☐ Basement ☐ Slab On Grade

INTERIOR FOUNDATION

ACC MAR NI NP RR

Comments:

Inspection Date: 09/23/2019

Inspector: Dave Faber

Inspector Phone: (479) 777-1007



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712

UNDER FLOOR F	RAMING & SUPPORT	ACC	MAR	NI	NP	RR
BEAMS						
JOISTS				V		
POSTS				V		
PIERS				V		
Comments: NOTE: Limited visibility	/ due to ceiling.					
FLOOR/SLAB		ACC	C MAR	NI 🗹	NP	RR
☑ Concrete	☑ Obscured / Covered					
oundation at the time o	re view of slab. No reportable concerns were observed vor inspection. However, our service does not guarantee by ement and/or foundation failure.	or warrant agains	t future	e leak	ιο,	
oundation at the time or cracks, settlement, mo	of inspection. However, our service does not guarantee vement and/or foundation failure. ☑ Recomme		t future	e leak		
oundation at the time o	of inspection. However, our service does not guarantee vement and/or foundation failure. ☑ Recomme					
ELECTRICAL SERVICE SIZE (Main I	of inspection. However, our service does not guarantee evement and/or foundation failure. Recommon	end Repairs ☑ 120 / 2		t (Non		
ELECTRICAL SERVICE SIZE (Main I) ☑ Brand: Cutler Hammer ☑ 225 AMP	of inspection. However, our service does not guarantee evement and/or foundation failure. Recommon	end Repairs ☑ 120 / 2	240 Vol	t (Non	ninal)	
ELECTRICAL SERVICE SIZE (Main I) Brand: Cutler Hammer 2225 AMP SERVICE ENTRANCE CABLE	of inspection. However, our service does not guarantee evement and/or foundation failure. Recommon	end Repairs 120 / 2 ACC	240 Vol	t (Non	ninal)	
ELECTRICAL SERVICE SIZE (Main I Brand: Cutler Hammer 2225 AMP SERVICE ENTRANCE CABLE PANEL	of inspection. However, our service does not guarantee evement and/or foundation failure. Recommon	end Repairs 120 / 2 ACC	240 Vol	t (Non	ninal)	
ELECTRICAL SERVICE SIZE (Main I 2225 AMP SERVICE ENTRANCE CABLE PANEL SUB-PANEL	of inspection. However, our service does not guarantee evement and/or foundation failure. Recomme Panel) Main Disconnect Location: Garage	end Repairs 120 / 2 ACC 2	240 Vol	t (Non	NP □	
ELECTRICAL SERVICE SIZE (Main I) Brand: Cutler Hammer 1225 AMP SERVICE ENTRANCE CABLE PANEL SUB-PANEL BRANCH CIRCUITS	of inspection. However, our service does not guarantee evement and/or foundation failure. Recommon	end Repairs 2 120 / 2 ACC 2 2	240 Vol	t (Non	ninal)	
ELECTRICAL SERVICE SIZE (Main I) Brand: Cutler Hammer 2225 AMP SERVICE ENTRANCE CABLE PANEL SUB-PANEL BRANCH CIRCUITS BONDING/GROUNDING	of inspection. However, our service does not guarantee evement and/or foundation failure. Recomme Panel) Main Disconnect Location: Garage	end Repairs 120 / 2 ACC 2	240 Vol	t (Non	NP □	
ELECTRICAL SERVICE SIZE (Main I DESCRICE SIZE SIZE (Main I DESCRICE SIZE SIZE SIZE SIZE	of inspection. However, our service does not guarantee evement and/or foundation failure. Recomme Panel) Main Disconnect Location: Garage	end Repairs 2 120 / 2 ACC 2 2	240 Vol	t (Non	ninal)	
ELECTRICAL SERVICE SIZE (Main I) Brand: Cutler Hammer 2225 AMP SERVICE ENTRANCE CABLE PANEL SUB-PANEL BRANCH CIRCUITS BONDING/GROUNDING	of inspection. However, our service does not guarantee evement and/or foundation failure. Recomme Panel) Main Disconnect Location: Garage	end Repairs 2 120 / 2 ACC 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	240 Vol	t (Non	ninal)	

09/23/2019

Inspection Date:

Inspector: Dave Faber

Inspector Phone: (479) 777-1007



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712

Incorrect over current protection (wrong AMP breaker) on Heat Pump/AC circuit according to information on condensing unit

data plate maximum breaker should be 50 AMP. While this is a common practice it may void the manufactures warranty and poses a safety hazard should an over current condition occur. Recommend evaluation of installation practices by a qualified electrical contractor to include but not limited to:

- 1. Ampacity of conductors.
- 2. Type of over current device i.e. HACR (Heating Air Conditioning Refrigeration).
- 3. Size of over current device.

Correct application of the above will prevent a breaker from tripping due to a inductive load during start-up. Breaker trips caused by factors other than inductive load should by evaluated to determine cause. Recommend further evaluation/repair by qualified electrical contractor(s).

*Smoke Detectors / GFCI's checked with test button only. Monthly Test Recommended.



Electrical: 50 AMP MAX





Electrical: Bonded



Electrical: Panel with Cover Off

Inspection Date: 09/23/2019

Inspector: Dave Faber

Inspector Phone: (479) 777-1007



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712

PLUMBING						
Water Service						
☑ Water Public	☑ Shut Off Location: Basement					
Sewage Service						
☑ Sewage Public						
		AC	MAR	NI	NP	RR
SUPPLY		✓				
DRAINS		☑				
EJECTOR PUMP					Ø	
VENTS		✓				

Comments:

Inspection is limited to visible components only. Any supply, drain or vent not readily accessible, obstructed or underground is excluded from this inspection. It is not within the scope of this inspection to determine if water supply or sewage disposal is public or private.

Inspection of Corrugated Stainless Steel Tubing (CSST) gas supply line is NOT within the scope of this inspection. CSST gas pipe had been associated with lightning related fires, product defect allegations and litigation.

Main utility line, septic systems and gray water systems are excluded from this Inspection.



Plumbing:



Plumbing:

Inspection Date: Inspector: Dave Faber Email: dave.faber@npiinspect.com



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712

	ACC	MAR	NI	NP	RR
WATER HEATER	V				

Brand: Ruud Model: PE2M-52-2 Size: 50 Gallons Age: 5-10 Year(s)

Design Life: 10-15 Year(s) SerialNo: RU0212259351

☑Electric

Comments:

Please Note: If water has been shut off, Temperature Pressure Relief Valves (TPRV) often leak when water is turned back on. Buyer should inspect TPRV valve for leakage immediately after water service is restored.







Water Heater

LAUNDRY FACILITIES

Location: Laundry room					
	ACC	MAR	NI	NP	RR
UTILITY HOOKUPS			Ø		
DRYER VENTS			Ø		
LAUNDRY TUB	☑				
DRAIN			V		

Comments:

Suggest checking and cleaning dryer vent on regular basis to prevent build up of flammable lint.

Laundry supply and drains are visually inspected only, no other testing is performed.

Inspection Date: Inspector: Dave Faber Email: dave.faber@npiinspect.com



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712



Laundry Facilities:

HEATING

HEATING							
Brand: Armstrong Air SerialNo: 1612C02241	Model: 4SHP14LE160P-5	Age: 5-10 Year(s)	Design Life: 15-20 Year(s)				
☑Electric	☑ Forced Air	☑ Heat Pump					
			ACC	MAR	NI	NP	RR
OPERATION			☑				
ABOVE GROUND STORAGE	E TANKS				V		
HUMIDIFIER					Ø		

Comments:

Heat Pump was not tested due to unsafe operation temperature outside of 86 degrees Fahrenheit. Emergency Heat was tested and is functioning.

Inspection Date: Inspector: Dave Faber Email: dave.faber@npiinspect.com



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712



Heating: Em Heating Temp



ACC MAR

 \checkmark

NI

NP

RR

Heating: EM Heat

DRAFT CONTROL/VENT

☑ Metal Pipe

Comments:

HEATING DISTRIBUTION

☑Ductwork

	ACC	MAR	NI	NP	RR
DISTRIBUTION	Ø				
BLOWER	Ø				
CONTROLS/THERMOSTAT (CALIBRATIONS/TIMED FUNCTIONS NOT CHECKED.)	Ø				
CIRCULATOR PUMP			V		

Comments:

Filter Size 18 x 24 x 1

Filter location in return air duct at bottom of air handler cabinet.

Inspection Date: 09/23/2019

Inspector: Dave Faber

Inspector Phone: (479) 777-1007



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712



Heating Distribution:

COOLING

ACC MAR NI NP RR

COOLING

Brand: Armstrong Air Model: 4SHP14LE160P-5 Size: 5 Ton Age: 10-15 Year(s)

Design Life: 10-15 Year(s) SerialNo: 1612C02241

☑ Electric ☑ Central Air ☑ Heat Pump

Comments:

Suggest yearly maintenance check by qualified HVAC contractor per manufactures instructions for safe and efficient operations.



Cooling: Return Air Temp



Cooling: Supply Air Temp

Inspection Date: Inspector: Dave Faber Email: dave.faber@npiinspect.com



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712



Cooling:



Cooling:



Cooling:



Cooling:

KITCHEN	☑ Monitor Condition	ACC	MAR	NI	NP	RR
CEILINGS		Ø				
WALL(S)		Ø				
WINDOWS/TRIM		Ø				
WINDOW SCREENS		Ø				
FLOOR/FINISH		V				
INTERIOR DOORS/HARDWARE		Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)		V				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST	RECOMMENDED.)		V			

Inspection Date: 09/23/2019

Inspector: Dave Faber

Inspector Phone: (479) 777-1007



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712

HEAT/AIR DISTRIBUTION			
COUNTERTOPS/CABINETS	Ø		
SINK/FAUCET			
EXHAUST FAN	Ø		
STOVE TOP/OVEN			
STOVE ANTI-TIP BRACKET	Ø		
WATER PRESSURE/FLOW/DRAINAGE	Ø		
DISHWASHER/CROSS FLOW PROTECTION	Ø		
REFRIGERATOR		Ø	
MICROWAVE	Ø		
GARBAGE DISPOSAL	Ø		

Comments:

Inspection of appliances is not within the State Standards of Practice and is performed as a courtesy. Appliances regardless of age can fail at any time. Inspection is only to determine if unit is operational at the time of inspection. No evaluation of overall performance, secondary features, settings, cycles, or life expectancy is made. It is advisable to operate all appliances during final walk through prior to purchase.

GFCI receptacles present on side of counters where sink existed but on the other counter, that is not connected to the other, does not have GFCI protection. At time of construction GFCI were only required 6' from Sink, however current standards require all kitchen receptacles to be GFCI protected. Recommend further evaluation/repair by qualified electrical contractor(s).







Kitchen: Kitchen

Inspection Date: Inspector: Dave Faber Email: dave.faber@npiinspect.com



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712



Kitchen: Cook Top



Kitchen: Oven



Kitchen: Broiler



ACC MAR

ΝI

NP

RR

Kitchen: Microwave

FIREPLACE/STOVE	FIREPL	ACE/S	STOVE
-----------------	--------	-------	-------

☑ Gas Log ☑ Woodburning

Comments:

Upstairs Gas Log fireplace was functional at time of inspection.

Downstairs Wood burning fireplace flue had signs of soot buildup. Recommend inspection by certified chimney sweep.

 $Recommend\ annual\ cleaning\ \textbf{-}\ Fireplace\ design\ and\ soot\ /\ creosote\ buildup,\ in\ most\ cases,\ prevents\ view\ of\ chimney\ liner\ /\ cracks.$

Inspection Date: 09/23/2019

Inspector: Dave Faber

Inspector Phone: (479) 777-1007



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712







Fireplace/Stove:

DATHDOOM					
BATHROOM	ACC	MAR	NI	NP	RR
CEILINGS	$\overline{\mathbf{A}}$				
WALL(S)	☑				
WINDOWS/TRIM	V				
WINDOW SCREENS	Ø				
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	V				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST RECOMMENDED.)	Ø				
HEAT/AIR DISTRIBUTION	Ø				
COUNTERTOPS/CABINETS	Ø				
SINK/FAUCET	V				
TOILET	Ø				
TUB/SHOWER	Ø				
JETTED TUB No GFCI No Service Access	Ø				
TILE WORK/ENCLOSURE	Ø				
EXHAUST FAN	Ø				
WATER PRESSURE/FLOW/DRAINAGE	Ø				

Comments:

Inspector does NOT perform leak test on shower pans or shower enclosures.

Inspection Date: Inspector: Dave Faber Email: dave.faber@npiinspect.com



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712

GFCI for Jetted Tub was not detectable due to no access door on Jetted Tub.



Bathroom: Jetted Tub Functional



Bathroom: Master Bath



Bathroom: No Access Panel



Bathroom: Master Bath

Inspection Date: 09/23/2019

Inspector: Dave Faber


Inspector Phone: (479) 777-1007



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712







Bathroom: Basement Bath

INTERIOR LIVING AREAS	ACC	MAR	NI	NP	RR
CEILINGS	Ø				
WALLS	Ø				
WINDOWS/TRIM	Ø				
WINDOW SCREENS	Ø				
FLOOR/FINISH	☑				
INTERIOR DOORS/HARDWARE	Ø				
CLOSET	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
HEAT/AIR DISTRIBUTION	Ø				

Comments:

Inspection Date: 09/23/2019

Inspector: Dave Faber

Inspector Phone: (479) 777-1007

NPI .

Big Dude Enterprises DBA

National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712



Interior Living Areas: Living Room



Interior Living Areas: Dining Room



Interior Living Areas: Living Room



Interior Living Areas: Den

INETRIOR SLEEPING AREAS	ACC	MAR	NI	NP	RR
CEILINGS	☑				
WALLS	Ø				
WINDOWS/TRIM	☑				
WINDOW SCREENS	V				
FLOOR/FINISH	\square				
INTERIOR DOORS/HARDWARE	V				
CLOSET	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	☑				
HEAT/AIR DISTRIBUTION	Ø				

Inspection Date: Inspector: Dave Faber

09/23/2019 Inspector Phone: (479) 777-1007



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712

Comments:



Inetrior Sleeping Areas: Master Bedroom



Inetrior Sleeping Areas: Guest Bedroom



Inetrior Sleeping Areas: Master Bedroom



Inetrior Sleeping Areas: Basement Bedroom

Inspection Date: 09/23/2019

Inspector: Dave Faber

Inspector Phone: (479) 777-1007



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712

BASEMENT	☑ Monitor Condition	ACC	MAR	NI	NP	RR
CEILINGS		Ø				
WALLS		V				
WINDOWS/TRIM		Ø				
WINDOW SCREENS		Ø				
FLOOR/FINISH		Ø				
INTERIOR DOORS/HARDWARE		Ø				
CLOSET		Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)		Ø				
HEAT/AIR DISTRIBUTION		☑				
SINK			Ø			

Comments:

Basement Wet Bar Sink has faucets plumbed in reverse with the Hot on the left and Cold on the right.



Basement: Basement Fireplace



Basement: Basement

Inspection Date: Inspector: Dave Faber Email: dave.faber@npiinspect.com 09/23/2019 Inspector Phone: (479) 777-1007

NPI

Big Dude Enterprises DBA

National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712



Basement: Basement



Basement: Basement Work Area



Basement: Furnace, Hot Water & Storage



Basement: Basement Work Area



Basement: Furnace, Hot Water & Storage



Basement: Basement Sink

Inspection Date: Inspector: Dave Faber

09/23/2019 Inspector Phone: (479) 777-1007



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712

	ACC	MAR	NI	NP	RR
STAIRS / RAILINGS	V				

Comments:

Inspection Date: Inspector: Dave Faber

09/23/2019 Inspector Phone: (479) 777-1007



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712

Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

1 GUTTERS/DOWN SPOUTS

REPAIR/REPLACE

Downspout on West side of home is disconnected and should be repaired to avoid drainage from seeping into foundation. Recommend further evaluation/repair by qualified contractor(s).



GUTTERS/DOWN SPOUTS: Downspout disconnected

Inspection Date: 09/23/2019

Inspector: Dave Faber

Inspector Phone: (479) 777-1007



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712

2 EXTERIOR SURFACE

Siding/Trim MARGINAL

Synthetic Stucco identified on front and West side of home. Recommend trimming back bushes at least 18" from the synthetic stucco surface to avoid moisture related issues.

Front also has stone veneer with not visible cracks.

Aluminum siding and trim around house appear to be functional with no significant visible damage.



EXTERIOR SURFACE: Bushes against Synthetic Stucco

Inspection Date: 09/23/2019

Inspector: Dave Faber

Inspector Phone: (479) 777-1007



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712

3 WINDOWS REPAIR/REPLACE

Front window on West side has a crack near the bottom that could allow moisture to seep in and cause deterioration. Recommend repair by qualified window contractor.



WINDOWS: Cracked Window sill

4 GARAGE PEDESTRIAN DOOR INTO HOUSE

MARGINAL

Any door between the house and the garage should have an automatic door closer that is tight fitting and weather-stripped for fire safety and to reduce the chance of gasoline or exhaust fumes entering the home however it was not needed at the time of construction of this home. Recommend installation of auto-closure unit.

5 ATTIC ELECTRICAL

REPAIR/REPLACE

One or more junction boxes visible in the attic was missing a cover plate at the time of the inspection. This is a shock/potential fire hazard.

Recommend further evaluation/repair by qualified electrical contractor(s).

Inspection Date: 09/23/2019


Inspector: Dave Faber

Inspector Phone: (479) 777-1007



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712



ATTIC ELECTRICAL:

Inspection Date: 09/23/2019

Inspector: Dave Faber

Inspector Phone: (479) 777-1007



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712

6 ELECTRICAL

Branch Circuits REPAIR/REPLACE

Incorrect over current protection (wrong AMP breaker) on Heat Pump/AC circuit according to information on condensing unit

data plate maximum breaker should be 50 AMP. While this is a common practice it may void the manufactures

warranty and poses a safety hazard should an over current condition occur. Recommend evaluation of installation

practices by a qualified electrical contractor to include but not limited to:

- 1. Ampacity of conductors.
- 2. Type of over current device i.e. HACR (Heating Air Conditioning Refrigeration).
- 3. Size of over current device.

Correct application of the above will prevent a breaker from tripping due to a inductive load during start-up. Breaker

trips caused by factors other than inductive load should by evaluated to determine cause. Recommend further evaluation/repair by qualified electrical contractor(s).



ELECTRICAL: 50 AMP MAX



ELECTRICAL: 60 AMP Breaker

Inspection Date: Inspector: Dave Faber Email: dave.faber@npiinspect.com
09/23/2019 Inspector Phone: (479) 777-1007



National Property Inspections

123 Arkansas Dr., Bentonville, AR 72712

7 KITCHEN

GFCI Protection (Checked with Test Button Only. Monthly Test Recommended.)

MARGINAL

GFCI receptacles present on side of counters where sink existed but on the other counter, that is not connected to the other, does not have GFCI protection. At time of construction GFCI were only required 6' from Sink, however current standards require all kitchen receptacles to be GFCI protected. Recommend further evaluation/repair by qualified electrical contractor(s).

8 BASEMENT

Sink MARGINAL

Basement Wet Bar Sink has faucets plumbed in reverse with the Hot on the left and Cold on the right.



BASEMENT: Basement Sink

MAR (MARGINAL)

The item/system was marginally acceptable. It performed its designed function at the time of the inspection. However, due to age and/or deterioration, it will likely require early repair or replacement.

RR (REPAIR/REPLACE)

The item/system failed to operate/perform its intended function, was structurally deficient, was unsafe or was hazardous at the time of the inspection.

Inspection Date: Inspector: Dave Faber Email: dave.faber@npiinspect.com