

National Property Inspections

EXAMPLE, Olympia, WA



Monday, November 18, 2019
Inspector
Erik Peters
360-480-5812
erik.peters@npiinspect.com

Inspection Date: 11/18/2019

Inspector: Erik Peters

Inspector Phone: 360-480-5812



National Property Inspections

EXAMPLE, Olympia, WA

GENERAL INFORMATION

GENERAL CONDITIONS AT TIME OF INSPECTION:

Property Occupied: Yes	Weather:
Estimated Age Of Property: 38 Year(s) Property Faces: \square North \square South \square East \square West	☑ Overcast
Type of Property: ☑ Single-Family Primary Construction: ☑ Wood	Soil Conditions: ☑ Damp/Wet ☑ Damp Persons Present: ☑ Owner

DEFINITIONS:

Below are listed the definitions used throughout the report to describe each feature of the property.

ACC (ACCEPTABLE)

The item/system was performing its intended function at the time of the inspection.

MAR (MARGINAL)

The item/system was marginally acceptable. It performed its designed function at the time of the inspection. However, due to age and/or deterioration, it will likely require early repair or replacement.

NI (NOT INSPECTED)

The item/system was not inspected due to safety concerns, inaccessibility and/or concealment or seasonal conditions and no representations of whether or not it was functioning as intended were made.

NP (NOT PRESENT)

The item/system does not exist or was visually concealed at the time of the inspection.

RR (REPAIR/REPLACE)

The item/system failed to operate/perform its intended function, was structurally deficient, was unsafe or was hazardous at the time of the inspection.

SCOPE OF THE INSPECTION:

We wish to remind you that every property requires a certain amount of ongoing maintenance: drains sometimes clog, gutters, downspouts and the grading around the property must be properly maintained to help prevent water intrusion in to the basement or crawlspace; roofs, furnaces, air conditioners and other components require regular maintenance and inspection. This property will be no exception and we strongly suggest that you both expect and budget for regular maintenance/repairs.

The following report is based on visual inspection of the readily accessible areas of this property and on a random sampling of like items, <u>not every item was or could be inspected</u>. Please read the entire report carefully, ask your inspector any questions you might have <u>and obtain estimates or discuss noted items with a contractor before</u> closing.

Inspection Date: Inspector: Erik Peters Email: erik.peters@npiinspect.com



National Property Inspections

EXAMPLE, Olympia, WA

		ACC	MAR	NI	NP	RR
GRADING / DRAINAGE	☑ Monitor Condition		\square			

☑ Near Level ☑ Negative Slope

Comments:

Negative slope noted at various points around the perimeter of the home. May cause drainage problems/water intrusion during rainfall. The current condition may contribute to water intrusion.



Grading / Drainage: South side negative slope

DRIVEWAY

ACC MAR NI NP RR

☑ Asphalt

Comments:

The driveway was in generally good condition with minor cracks, no settlement and had an acceptable surface.

Inspection Date: Inspector: Erik Peters Email: erik.peters@npiinspect.com



National Property Inspections

EXAMPLE, Olympia, WA



Driveway:

WALKS / STEPS Concrete		ACC MAR NI	NP RR □ □
Comments:			
PORCHES / STOOPS Comments:		ACC MAR NI	NP RR □ □
PATIO ☑ Concrete	☑ Monitor Condition	ACC MAR NI	NP RR

Comments

Patio roof supports look improperly installed under shingles.

Wavy appearance in Patio Roof. Cause unknown. Did not walk patio roof.

Recommend further evaluation of Patio Roof by licensed Roofing contractor.

Inspection Date: Inspector: Erik Peters Email: erik.peters@npiinspect.com



National Property Inspections

EXAMPLE, Olympia, WA



Patio: Patio roof footing



Patio: Patio supports



Patio: Patio roof support



Patio: Patio



Patio: Patio roof



Patio: Patio roof separation in fascia

Inspection Date: 11/18/2019

Inspector: Erik Peters

Inspector Phone: 360-480-5812



National Property Inspections

EXAMPLE, Olympia, WA



Patio: Patio roof support poorly install under shingles.

DETAINING WALLS	
RETAINING WALLS	
Comments:	ACC MAR NI NP RR
Comments.	
ROOFING	ACC MAR NI NP RR
Age: 10-15 Year(s) Design Life: 20 Year(s) Layers: 1 ☑ Asphalt / Composition	

Comments:

The roof consists of asphalt/composite architectural shingles, which showed typical signs of wear for the age of the home. No signs of leaks noted from inside the attic at the time of inspection.

Leaks not always detectable.

Inspection Date: In 11/18/2019 In:

Inspector: Erik Peters

Inspector Phone: 360-480-5812



National Property Inspections

EXAMPLE, Olympia, WA



Roofing:



Roofing:



Roofing:



Roofing:



Roofing:



Roofing:

Inspection Date: 11/18/2019

Inspector: Erik Peters

Inspector Phone: 360-480-5812



National Property Inspections

EXAMPLE, Olympia, WA







ACC MAR

 $\overline{\mathbf{V}}$

NP

RR

Roofing:

FLASHING/VALLEYS

☑ Composition / Membrane

☑ Filled with Debris

Comments:

All valleys and flashings that were readily visible at time of inspection were acceptable.



Flashing/Valleys:



Flashing/Valleys:

Inspection Date: 11/18/2019

Inspector: Erik Peters

Inspector Phone: 360-480-5812



National Property Inspections

EXAMPLE, Olympia, WA

				ACC	MAR	NI	NP	RR
GUTTERS/DOWN SPOUTS		☑ Monitor Co.	ondition		Ø			
✓Aluminum	☑ Filled with Debris	☑Loose	\square_{M}	isaligi	ned			

☑ Missing Extension / Splash Block

Comments:

Some of the downspouts were damaged and loose.

Downspouts were discharging close to the foundation wall. Recommend the downspouts have extensions added to a minimum of six (6) feet away from the foundation wall. This could help reduce water pressure against the foundation which could lead to leakage and water related problems at the interior.



Gutters/Down Spouts:



Gutters/Down Spouts:



Gutters/Down Spouts:



Gutters/Down Spouts:

Inspection Date: Inspector: Erik Peters

11/18/2019 Inspector Pho

Inspector Phone: 360-480-5812



National Property Inspections

EXAMPLE, Olympia, WA

	ACC	MAR	NI	NP	RR
CHIMNEY					

Framed

Comments:

Not in use at time of inspection. Chimney appeared in good condition with rain cap present.

Flue not inspected. Annual cleaning is recommended.



Chimney: chimney flashing



Chimney: Rain cap spark arrester in place at the time of inspection.

EXTERIOR SURFACE

☑ Composite					
	ACC	MAR	NI	NP	RR
SIDING/TRIM	☑				
EXTERIOR FAUCETS	☑				
EXTERIOR ELECTRICAL OUTLETS	☑				
EXTERIOR LIGHTING	Ø				

Comments:

All exterior siding/surface appeared in good state of repair at time of inspection with no major defects noted. . Exterior of the house and the components listed were acceptable at time of inspection.

Inspection Date: Inspector: Erik Peters Email: erik.peters@npiinspect.com



National Property Inspections

EXAMPLE, Olympia, WA



Exterior Surface:



Exterior Surface:



Exterior Surface:



Exterior Surface:



Exterior Surface:



Exterior Surface:

Inspection Date: 11/18/2019

Inspector: Erik Peters

Inspector Phone: 360-480-5812



National Property Inspections

EXAMPLE, Olympia, WA

WINDOWS

ACC MAR NI NP RR
☑ □ □ □ □

Comments:

All windows appeared to be in good repair at time of inspection from the exterior.



Windows:

EXTERIOR DOORS

ACC MAR NI NP RR
☑ □ □ □ □

✓ Metal

Comments:

Doors appear to be functioning properly and seal properly when closed.



Exterior Doors:

Inspection Date: 11/18/2019

Inspector: Erik Peters

Inspector Phone: 360-480-5812



National Property Inspections

EXAMPLE, Olympia, WA

		ACC	MAR	NI	NP	RR
FOUNDATION	☑ Monitor Condition		Ø			

☑Concrete

Comments:

Foundation walls were found to have minimal cracking and appeared acceptable at time of inspection. One vertical cracks noted, looked to have been sealed.



Foundation: crack in foundation.

GARAGE/CARPORT

☑2 Cars	☑ Attached	☑ Obscured / Limited View	Outlets (NOT GFCI) Prote		Prote	cted	
			ACC	MAR	NI	NP	RR
FLOOR/WALLS/CEILI	NG/ELECTRICAL		Ø				
ROOF			\square				
SIDING/TRIM			Ø				

Comments:

Garage condition was acceptable at time of inspection.

Inspection Date: Inspector: Erik Peters Email: erik.peters@npiinspect.com



National Property Inspections

EXAMPLE, Olympia, WA



Garage/Carport:

OVERHEAD GARAGE DOORS

ACC MAR NI NP RR
☑ □ □ □ □

☑ Wood

Comments:

The operation of the garage door, opener and all related safety devices appear to be satisfactory at time of inspection.

Crack in frame of garage door.



Overhead Garage Doors:



Overhead Garage Doors:

Inspection Date: 11/18/2019

Inspector: Erik Peters

Inspector Phone: 360-480-5812



National Property Inspections

EXAMPLE, Olympia, WA

	ACC	MAR	NI	NP	RR
GARAGE PEDESTRIAN DOOR INTO HOUSE	☑				

☑ Solid Core

Comments:

Door had self closure and seals were acceptable. Door has a 20 minute fire rating which is correct for this application.

Inspection Date: Inspector: Erik Peters Email: erik.peters@npiinspect.com



National Property Inspections

EXAMPLE, Olympia, WA

Attic / Roof

Method of Inspection ☑ Visual from Access

ATTIC FRAMING/SHEATHING

✓ Monitor Condition ☑ Recommend Repairs

ACC	MAR	NI	NP	RR
	Ø			

 \square Plywood / Panel Board / OSB

☑ Rafters

Comments:

The attic interior was visually examined for leaks and/or water stains. No cracked trusses or rafters, stains, or leaks were observed at time of inspection.

Framing/sheathing appeared to be functioning as designed at time of inspection. It appeared to be built within standards of practice for time of construction.

Missing cover for attic access, This is a fire hazard..Recommend further evaluation/repair by qualified licensed contractor.

Leaks not always detectable.



Attic Framing/Sheathing:



Attic Framing/Sheathing:

Inspection Date: Inspector: Erik Peters Email: erik.peters@npiinspect.com

Inspector Phone: 360-480-5812



National Property Inspections

EXAMPLE, Olympia, WA



Attic Framing/Sheathing:



Attic Framing/Sheathing:



Attic Framing/Sheathing: missing access cover.



Attic Framing/Sheathing:



Attic Framing/Sheathing:

Inspection Date: 11/18/2019

Inspector: Erik Peters

Inspector Phone: 360-480-5812



National Property Inspections

EXAMPLE, Olympia, WA

☑ Soffit ☑ Static Vent

Comments:

The attic was ventilated properly. No deficiencies were observed at time of inspection.



Attic Ventilation:

ATTIC INSULATION

☑Loose Fill

Comments:

Insulation over Garage area not present.



Attic Insulation:

Inspection Date: Inspector: Erik Peters

11/18/2019 Inspector Phone: 360-480-5812

Email: erik.peters@npiinspect.com

ACC MAR NI

 $\overline{\mathbf{V}}$

NP

RR



National Property Inspections

EXAMPLE, Olympia, WA

ATTIC ELECTRICAL

ACC	MAR	NI	NP	RR
Ø				

Comments:

Limited visibility. what was visible was acceptable at the time of inspection.

Limited visibility due to obstructions. See Electrical Section for additional Information.



Attic Electrical:

Interior Foundation

		ACC	MAR	NI	NP	RR
INTERIOR FOUNDATION	☑ Monitor Condition		V			

☑ Efflorescence / Suspected Leak(s)

☑ Horizontal Cracks

Comments:

Vertical crack in foundation wall. sealed.

Hole present in foundation wall recommend closing hole against vermin.

Efflorescence along foundation wall. Efflorescence is a powdery deposit of salts which forms on the surface of bricks and mortar. It is usually caused by water intrusion.

Electrical wires hanging touching ground in some places.

Inspection Date: Inspector: Erik Peters Email: erik.peters@npiinspect.com



National Property Inspections

EXAMPLE, Olympia, WA



Interior Foundation: hole thru foundation.





Interior Foundation:



Interior Foundation:

Inspection Date: 11/18/2019

Inspector: Erik Peters

Inspector Phone: 360-480-5812



National Property Inspections

EXAMPLE, Olympia, WA



Interior Foundation:



Interior Foundation: electrical wires



Interior Foundation: electrical wires

UNDER	FLOOR FRAMING & SUPPORT	ACC	MAR	NI	NP	RR
BEAMS	☑ Dimensional Lumber	Ø				
JOISTS	☑ Dimensional Lumber	Ø				
POSTS	☑ Dimensional Lumber	V				
PIERS	☑ Dimensional Lumber	V				

Comments

All framing under the floor was acceptable at time of inspection.

Inspection Date: Inspec

Inspector: Erik Peters

Inspector Phone: 360-480-5812



National Property Inspections

EXAMPLE, Olympia, WA



Under Floor Framing & Support:



Under Floor Framing & Support:



Under Floor Framing & Support:



Under Floor Framing & Support:

	ACC	MAR	NI	NP	RR
CRAWL SPACE	V				

☑ Insulation Present

Comments:

☑ Limited Access

Limited access only 70% of crawl space was viable. Duct work and plumbing denied access.

☑ Physical Entry

Inspection Date: Inspector: Erik Peters Email: erik.peters@npiinspect.com



National Property Inspections

EXAMPLE, Olympia, WA







☑ 200 AMP

Crawl Space:

☑ 120 / 240 Volt (Nominal)

	ACC	MAR	NI	NP	RR
SUMP/SUMP PUMP				V	
☑No Pump Present					
Comments:					

ELECTRICAL

SERVICE SIZE (Main Panel)

☑ Main Disconnect Location: Garage

SERVICE SIZE (Sub Panel)

,					
☑ 40 AMP					
	ACC	MAR	NI	NP	RR
SERVICE Underground	☑				
ENTRANCE CABLE	☑				
PANEL	Ø				
SUB-PANEL	Ø				
BRANCH CIRCUITS	Ø				
BONDING/GROUNDING	Ø				
GFCI(IN PANEL)*	Ø				
ARC FAULT	Ø				
SMOKE DETECTORS*	Ø				

Inspection Date: Inspector: Erik Peters

11/18/2019 Inspector Phone: 360-480-5812



National Property Inspections

EXAMPLE, Olympia, WA

Comments:

*Smoke Detectors / GFCI's checked with test button only. Monthly Test Recommended.



Electrical:



Electrical:



Electrical: Sub panel



Email: erik.peters@npiinspect.com

Electrical:

Inspection Date: Inspector: Erik Peters



National Property Inspections

EXAMPLE, Olympia, WA







Electrical:

PLUMBING

	vice

☑ Water Public ☑ Shut Off Location: Unknown

	ACC	MAR	NI	NP	RR
SUPPLY	Ø				
DRAINS ØABSØPVC	V				
EJECTOR PUMP				Ø	
VENTS	$\overline{\mathbf{A}}$				

Comments:

No defects were found pertaining to the main plumbing system.

Main utility line, septic systems and gray water systems are excluded from this Inspection.

Inspection Date: 11/18/2019

Inspector: Erik Peters

Inspector Phone: 360-480-5812



National Property Inspections


EXAMPLE, Olympia, WA



Plumbing:



Plumbing:



The Property of the Property o

Plumbing:



Plumbing:

Inspection Date: Inspector: Erik Peters Email: erik.peters@npiinspect.com
11/18/2019 Inspector Phone: 360-480-5812



National Property Inspections

EXAMPLE, Olympia, WA

	ACC	MAR	NI	NP	RR	
WATER HEATER	Ø					

Brand: Bradford White Model: M250T6DS-1NCW Size: 50 Gallons Age: 5-10 Year(s)

Design Life: 10-15 Year(s) SerialNo: GG13756123

Comments:

The operation and installation of the water heater appeared to be satisfactory at time of inspection. Routine maintenance such as draining the water heater could prolong its lifespan. Always refer to manufactures' specifications before doing any maintenance on your water heater.



Water Heater:

LAUNDRY FACILITIES	ACC	MAR	NI	NP	RR
UTILITY HOOKUPS	Ø				
DRYER VENTS	Ø				
LAUNDRY TUB				Ø	
DRAIN	Ø				

Comments:

Washer and dryer performed satisfactorily at time of inspection. Recommend cleaning behind the dryer and the metal vent periodically. In addition the lint trap/screen should be cleaned after every use. The aforementioned actions will reduce the possibility of fires and prolong the life expectancy of the unit.


Inspection Date: Inspector: Erik Peters Email: erik.peters@npiinspect.com



National Property Inspections

EXAMPLE, Olympia, WA







Laundry Facilities: dryer vent.

HEATING

Model: MBVC1200AA-1AC	Age: 10-15 Year(s)	Design Life: 10-15 Year(s)	SerialNo: 1104100166				
✓ Forced Air							
			ACC	MAR	NI	NP	RR
OPERATION							
ABOVE GROUND STORAGE TA	ANKS					Ø	
HUMIDIFIER						Ø	

Comments:

Furnace was clean and running properly at time of inspection. Heat distribution was acceptable with no problems to report.

Heat Exchanger - Unable to detect cracks/holes without dismantling unit.

Inspection Date: 11/18/2019

Inspector Phone: 360-480-5812

Inspector: Erik Peters



National Property Inspections

EXAMPLE, Olympia, WA



Heating:



Heating:



Heating:

HEATING DISTRIBUTION

☑Ductwork

	ACC	MAR	NI	NP	RR
DISTRIBUTION	Ø				
BLOWER	V				
CONTROLS/THERMOSTAT (CALIBRATIONS/TIMED FUNCTIONS NOT CHECKED.)	V				
CIRCULATOR PUMP	\square				

Comments:

Distribution was acceptable at time of inspection.

Inspection Date: 11/18/2019

Inspector: Erik Peters

Inspector Phone: 360-480-5812



National Property Inspections

EXAMPLE, Olympia, WA

COOLING

ACC MAR NI NP RR

Comments:

AC was not run due to temperature below 60 degrees.



Cooling:



Cooling:



Cooling:

Inspection Date: 11/18/2019

Inspector: Erik Peters

Inspector Phone: 360-480-5812



National Property Inspections

EXAMPLE, Olympia, WA

KITCHEN	☑ Monitor Condition	ACC	MAR	NI	NP	RR
CEILINGS		Ø				
WALL(S)		Ø				
WINDOWS/TRIM		Ø				
WINDOW SCREENS		Ø				
FLOOR/FINISH		Ø				
INTERIOR DOORS/HARDWARE		Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	1	Ø				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY T	EST RECOMMENDED.)		Ø			
HEAT/AIR DISTRIBUTION		Ø				
COUNTERTOPS/CABINETS		Ø				
SINK/FAUCET		Ø				
EXHAUST FAN		Ø				
STOVE TOP/OVEN		\square				
STOVE ANTI-TIP BRACKET				Ø		
WATER PRESSURE/FLOW/DRAINAGE		\square				
DISHWASHER/CROSS FLOW PROTECTION		Ø				
REFRIGERATOR		Ø				
MICROWAVE		Ø				
GARBAGE DISPOSAL		Ø				

Comments:

All components in kitchen were acceptable at time of inspection.

No GFI protection in the Kitchen

Inspection Date: Inspector: Erik Peters Email: erik.peters@npiinspect.com



National Property Inspections

EXAMPLE, Olympia, WA



Kitchen: Garbage disposal



Kitchen: Dining room



Kitchen:



ACC MAR

NI

NP

RR

Kitchen: Patio sliding door

FIREPLACE/STOVE

☑Electric

Comments:

Appeared to operate as designed. No defects noted.

Recommend annual cleaning - Fireplace design and soot / creosote buildup, in most cases, prevents view of chimney liner / cracks.


Inspection Date: Inspector: Erik Peters Email: erik.peters@npiinspect.com
11/18/2019 Inspector Phone: 360-480-5812



National Property Inspections

EXAMPLE, Olympia, WA







Fireplace/Stove: Electric fireplace

BATHROOM	ACC	MAR	NI	NP	RR
CEILINGS	Ø				
WALL(S)	Ø				
WINDOWS/TRIM				V	
WINDOW SCREENS				V	
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST RECOMMENDED.)	Ø				
HEAT/AIR DISTRIBUTION	Ø				
COUNTERTOPS/CABINETS	Ø				
SINK/FAUCET	V				
TOILET	Ø				
TUB/SHOWER	\square				
JETTED TUB	\square				
TILE WORK/ENCLOSURE	\square				
EXHAUST FAN	\square				
WATER PRESSURE/FLOW/DRAINAGE	☑				

Comments:

Inspection Date: Inspector: Erik Peters

11/18/2019 Inspector Phone: 360-480-5812



National Property Inspections

EXAMPLE, Olympia, WA



Bathroom: bathroom



Bathroom:



Bathroom:



Bathroom: bathroom



Bathroom:

Inspection Date: 11/18/2019

Inspector: Erik Peters

Inspector Phone: 360-480-5812



National Property Inspections

EXAMPLE, Olympia, WA

MASTER BATHROOM	☑ Recommend Repairs	ACC	MAR	NI	NP	RR
CEILINGS		Ø				
WALL(S)		Ø				
WINDOWS/TRIM					Ø	
WINDOW SCREENS					Ø	
FLOOR/FINISH		V				
INTERIOR DOORS/HARDWARE		V				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)		Ø				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST	T RECOMMENDED.)				Ø	
HEAT/AIR DISTRIBUTION		\square				
COUNTERTOPS/CABINETS		V				
SINK/FAUCET		V				
TOILET		V				
TUB/SHOWER		Ø				
JETTED TUB					Ø	
TILE WORK/ENCLOSURE		Ø				
EXHAUST FAN						Ø
WATER PRESSURE/FLOW/DRAINAGE		Ø				

Comments:

Vent fan in master bath broken.

Hole around master bathroom showerhead.

Recommend further evaluation/repair by qualified contractor(s).

Inspection Date: Inspector: Erik Peters Email: erik.peters@npiinspect.com



National Property Inspections

EXAMPLE, Olympia, WA



master bathroom:

LIVING ROOM	ACC	MAR	NI	NP	RR
CEILINGS	V				
WALLS	V				
WINDOWS/TRIM	☑				
WINDOW SCREENS	Ø				
FLOOR/FINISH	V				
INTERIOR DOORS/HARDWARE	Ø				
CLOSET	V				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	☑				
HEAT/AIR DISTRIBUTION	V				

Comments:

Ceiling and walls were free of cracks. Window(s) functioned properly and seals were acceptable.

Inspection Date: Inspector: Erik Peters Email: erik.peters@npiinspect.com



National Property Inspections

EXAMPLE, Olympia, WA



living room: living room



living room: living room



living room: living room

MASTER BEDROOM	ACC	MAR	NI	NP	RR
CEILINGS	☑				
WALLS	V				
WINDOWS/TRIM	Ø				
WINDOW SCREENS	V				
FLOOR/FINISH	\square				
INTERIOR DOORS/HARDWARE	V				
CLOSET	V				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	V				
HEAT/AIR DISTRIBUTION	V				

Inspection Date: Inspector: Erik Peters

11/18/2019 Inspector Phone: 360-480-5812



National Property Inspections

EXAMPLE, Olympia, WA

Comments:

Ceiling and walls were free of cracks. Window(s) functioned properly and seals were acceptable.



Master bedroom:



Master bedroom:



Master bedroom:

Inspection Date: 11/18/2019

Inspector: Erik Peters

Inspector Phone: 360-480-5812



National Property Inspections

EXAMPLE, Olympia, WA

BEDROOM 2	ACC	MAR	NI	NP	RR
CEILINGS					
WALLS	Ø				
WINDOWS/TRIM	V				
WINDOW SCREENS	\square				
FLOOR/FINISH	\square				
INTERIOR DOORS/HARDWARE	\square				
CLOSET					
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	\square				
HEAT/AIR DISTRIBUTION	V				

Comments:

Ceiling and walls were free of cracks. Window(s) functioned properly and seals were acceptable.



Bedroom 2:

Inspection Date: Inspector: Erik Peters Email: erik.peters@npiinspect.com



National Property Inspections

EXAMPLE, Olympia, WA

BEDROOOM 3	ACC	MAR	NI	NP	RR
CEILINGS	Ø				
WALLS	Ø				
WINDOWS/TRIM	Ø				
WINDOW SCREENS	Ø				
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
CLOSET	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
HEAT/AIR DISTRIBUTION	Ø				

Comments:

Ceiling and walls were free of cracks. Window(s) functioned properly and seals were acceptable.



Bedrooom 3:



Bedrooom 3:

Inspection Date: Inspector: Erik Peters Email: erik.peters@npiinspect.com



National Property Inspections

E	XAMPLE, Olympia, WA				
STAIRS / RAILINGS	ACC	MAR	NI	NP ☑	RR
Comments:					

Inspection Date: Inspector: Erik Peters Email: erik.peters@npiinspect.com



National Property Inspections

EXAMPLE, Olympia, WA

Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

1 GRADING / DRAINAGE

MARGINAL

Negative slope noted at various points around the perimeter of the home. May cause drainage problems/water intrusion during rainfall. The current condition may contribute to water intrusion.

2 PATIO MARGINAL

Patio roof supports look improperly installed under shingles.

Wavy appearance in Patio Roof. Cause unknown. Did not walk patio roof.

Recommend further evaluation of Patio Roof by licensed Roofing contractor.

3 GUTTERS/DOWN SPOUTS

MARGINAL

Some of the downspouts were damaged and loose.

Downspouts were discharging close to the foundation wall. Recommend the downspouts have extensions added to a minimum of six (6) feet away from the foundation wall. This could help reduce water pressure against the foundation which could lead to leakage and water related problems at the interior.

4 FOUNDATION MARGINAL

Foundation walls were found to have minimal cracking and appeared acceptable at time of inspection. One vertical cracks noted, looked to have been sealed.

5 ATTIC FRAMING/SHEATHING

MARGINAL

Missing cover for attic access, This is a fire hazard..Recommend further evaluation/repair by qualified licensed contractor.

6 INTERIOR FOUNDATION

MARGINAL

Vertical crack in foundation wall. sealed.

Hole present in foundation wall recommend closing hole against vermin.

Efflorescence along foundation wall. Efflorescence is a powdery deposit of salts which forms on the surface of bricks and mortar. It is usually caused by water intrusion.

Electrical wires hanging touching ground in some places.

Inspection Date: Inspector: Erik Peters Email: erik.peters@npiinspect.com



National Property Inspections

EXAMPLE, Olympia, WA

7 KITCHEN

GFCI Protection (Checked with Test Button Only. Monthly Test Recommended.)

MARGINAL

No GFI protection in the Kitchen

8 MASTER BATHROOM

Exhaust Fan REPAIR/REPLACE

Vent fan in master bath broken.

Hole around master bathroom showerhead.

Recommend further evaluation/repair by qualified contractor(s).

MAR (MARGINAL) The item/system was marginally acceptable. It performed its designed function at the time of the

inspection. However, due to age and/or deterioration, it will likely require early repair or replacement.

RR (REPAIR/REPLACE) The item/system failed to operate/perform its intended function, was structurally deficient, was unsafe or

was hazardous at the time of the inspection.

Inspection Date: Inspector: Erik Peters Email: erik.peters@npiinspect.com