Insured/Applicant Name: Client Name	Name Application / Policy #:				
Address Inspected: Client Address					
Actual Year Built: 2013		Date Inspected:	03/25/2021		
Minimum Photo Requirements ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plur ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Flore	nbing: Water heater, under cabin lorida-licensed inspector must				
Be advised that Underwriting will rely on the informat This information only is used to determine insurability			btained from the Florida licensed professional of your choice. ty, fitness or longevity of any of the systems inspected.		
Electrical System Separate documentation of any aluminum wiring reme	diation must be provided and	certified by a license	ed electrician.		
Main Panel Type: ☑ Circuit breaker □ Fuse Total Amps: 200 Is amperage sufficient for current usage? ☑ Yes □ No (explain)		Second Panel Type: Circuit breaker Fuse Total Amps: Is amperage sufficient for current usage? Yes No (explain)			
Indicate presence of any of the following:					
Cloth wiring					
Active knob and tube					
Branch circuit aluminum wiring (If present, describe	the usage of all aluminum wirir	ng):			
* If single strand (aluminum branch) wiring, provide det	-	-	vork must be provided.		
Connections repair via COPALUM crimp					
Connections repair via AlumniConn					
Hazards Present		Double taps			
Blowing fuses		Exposed wiring			
Tripping breakers		Unsafe wiring			
Empty sockets		Improper breaker size			
Loose Wiring		Scorching			
Improper grounding		Other (explain)			
Corrosion					
Over fusing					
General condition of the electrical system: ☑ Satisfact	tory 🔲 Unsatisfactory (explai	n)			
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: 8	Panel age:		Copper NM, BX or Conduit		
Year last updated: N/A	Year last updated:	_			
Brand/Model: Eaton	Brand/Model:				

National Property Inspections (NPI) 03/25/2021

HVAC System							
Central AC: Yes I No							
Central heat: Yes I No							
If not central heat, indicate primary heat source and fuel type:							
Are the heating, ventilation and air conditioning systems in good working order? \checkmark Yes	No (explain)						
Date of last HVAC servicing/inspection: <u>N/A</u>							
Hazards Present Wood burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☑ N Space heater used as primary heat source? ☐ Yes ☑ No Is the source portable? ☐ Yes ☑ No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, in ☐ Yes ☑ No							
Supplemental Information							
Age of system: 8							
Year last updated: N/A							
(Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)							
Plumbing System							
Is there a temperature pressure relief valve on the water heater? ☑ Yes □ No							
Is there any indication of an active leak? Yes V No Is there any indication of a prior leak? Yes V No							
Water heater location: Garage							
General condition of the following plumbing fixtures and connections to applicances:							
Satisfactory Unsatisfactory N/A	Satisfactory Unsatisfactory N/A						
Dishwasher	Toilets						
Refrigerator	Sinks						
Washing Machine	Sump pump						
Water Heater	Main shut off valve						
Showers/Tubs	All other visible						
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosid	on, grout/caulk, etc.).						
Supplemental Information							
Age of Piping System:	<u>Type of pipes (check all that apply)</u>						
X Original to home	$\mathbf{\nabla} Copper$						
Completely re-piped	✓ PVC/CPVC						
	Galvanized						
Partially re-piped (Provide year and extent of renovation in the comments below)	□ PEX						
(11011de year and extent of renovation in the comments below)	Polybutylene						

Other (specify)

National Property Inspections (NPI) 03/25/2021

Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i>)				
Predominant Roof Covering material:Architectural shingle	Secondary Roof Covering material:			
Roof age (years): 8	Roof age (years):			
Remaining useful life (years): 7-12	Remaining useful life (years):			
Date of last roofing permit: Unk				
	Date of last roofing permit:			
Date of last update: N/A If updated (check one):	Date of last update:			
Full Replacement	Full Replacement			
Partial Replacement	Partial Replacement			
% of replacement	% of replacement			
Overall condition:	Overall condition:			
Satisfactory	Satisfactory			
Unsatisfactory (explain below)	Unsatisfactory (explain below)			
Any visible signs of damage / deterioration?	Any visible signs of damage / deterioration?			
(check all that apply and explain below)	(check all that apply and explain below)			
Cracking	Cracking			
Cupping/Curling	Cupping/Curling			
Excessive granule loss	Excessive granule loss			
Exposed asphalt	Exposed asphalt			
Exposed felt	Exposed felt			
Missing/loose/cracked tabs or tiles	Missing/loose/cracked tabs or tiles			
Soft spots in decking	Soft spots in decking			
Visible hail damage	Visible hail damage			
Any visible signs of leaks 🔲 Yes 🔽 No	Any visible signs of leaks Yes No			
Attic/underside of decking 🔲 Yes 🗹 No	Attic/underside of decking Ves No			
Interior ceilings 🔲 Yes 🗹 No	Interior ceilings Yes No			
Additional Comments/Observations (use additional pages if nee	ded):			
HVAC/Electrical/Plumbing/Roof appears original				

	Silui			
All 4-Point Inspection Forms must be com I certify that the above statements are prue		lorida-licensed inspector.		
I certify that the above statements are falle				
1 mg m	Licensed Home Inspector	HI12972	03/25/2021	
Inspector Signature	Title	License Number	Date	
National Property Inspections (NPI)	Home Inspector	941.254.1583		
Company Name	License Type	Work Phone		

National Property Inspections (NPI) 03/25/2021

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. Acceptable Condition means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos



Electrical System

Panel Photos




Additional Photos

HVAC System

HVAC Equipment





Plumbing System

Under cabinet plumbing & drains



Master Bathroom

1st Floor Bathroom

Kitchen

Exposed Valves



2nd Floor Bathroom

2nd Floor Bathroom





Master Bathroom

1st Floor Bathroom

Water Heater











