

Sample-Townhouse



Monday, November 14, 2022 Inspector Eddie Restani 312-771-1293

450.012272 Expires: 11/30/2024

Inspection Date: 11/14/2022



		ACC	MAR	NI	NP	RR
DECKS / BAL	CONY					
⊠ Wood	General Deterioration					

#### Comments:

All exterior areas such as the deck/balcony are the responsibility of the HOA (Home Owners Association). Any areas of concern may need to be addressed with the HOA.

Limited inspection of deck due to snow cover. Visible areas appeared acceptable, with general deterioration and weather damage. Recommend further evaluation when snow has melted. Regular wood treatment maintenance should be done to preserve remaining life expectancy of construction materials.



Decks / Balcony:



Decks / Balcony:



Decks / Balcony:

Inspection Date: 11/14/2022

Inspector: Eddie Restani Inspector Phone: 312-771-1293



Composition / Membrane

General Deterioration

#### Comments:

Roof and valley flashings believed to be maintained by the HOA (Home Owners Association). Any areas of concern may need to be addressed with the HOA.

Limited visibility due to snow cover. Recommend re-inspection after snow is gone.

☑ Metal



Flashing/Valleys:



Flashing/Valleys:



ACC MAR

 $\checkmark$ 

NI

NP

RR

Flashing/Valleys:



Flashing/Valleys:

Inspection Date: 11/14/2022

Inspector: Eddie Restani Inspector Phone: 312-771-1293 Email: 450.012272 Expires: 11/30/2024

©1996-2022



## Sample-Townhouse

			ACC	MAR	NI	NP	RR
<b>GUTTERS/DOWN SPOUTS</b>		☑ Recommend Repairs					Ø
Aluminum	Missing Extension / Splash Block						

#### Comments:

Missing extensions at downspouts. Recommend installing downspout extensions to divert water 4 to 6 feet away from the foundation.

Limited observation due to snow cover.



Gutters/Down Spouts:



Gutters/Down Spouts:



Gutters/Down Spouts:

Inspection Date: 11/14/2022

Inspector: Eddie Restani Inspector Phone: 312-771-1293



### **GARAGE/CARPORT**

☑2 Cars	☑ Attached	General Deterioration	Obscured / Limited View				
			ACC	MAR	NI	NP	RR
FLOOR/WALLS/CEILI	NG/ELECTRICAL		V				
ROOF			Ø				
SIDING/TRIM			Ø				

#### Comments:


At time of inspection, the garage/carport and all related components were acceptable.



Garage/Carport:



Garage/Carport:



Garage/Carport:

Inspection Date: 11/14/2022

Inspector: Eddie Restani Inspector Phone: 312-771-1293



# Attic / Roof

*Method of Inspection* Visual from Access

### ATTIC FRAMING/SHEATHING

Plywood / Panel Board / OSB Trusses

#### Comments:

The attic was inspected from the attic access opening only due to inadequate headroom and/or no floor. Defects may not have been visible.

Leaks not always detectable.



Attic Framing/Sheathing:



ACC MAR

 $\mathbf{\nabla}$ 

NI

NP

RR

Attic Framing/Sheathing:



Attic Framing/Sheathing:

Inspection Date: 11/14/2022

Inspector: Eddie Restani Inspector Phone: 312-771-1293



Sample-Townhouse							
Interior Foundation   Foundation Type Ø Basement							
INTERIOR FOUND	ATION ☑Limited Observation		ACC	MAR	NI	NP	RR

#### Comments:

All visible interior foundation walls appeared to be in acceptable condition with no apparent major defects (settlement, cracking, bowing, movement, or moisture issues) noted at time of inspection. General deterioration of construction materials only.

Limited visibility due to insulation cover.



Interior Foundation:



Interior Foundation:



Interior Foundation:

Inspection Date: 11/14/2022

Inspector: Eddie Restani Inspector Phone: 312-771-1293



### **UNDER FLOOR FRAMING & SUPPORT**

General Deterioration

	ACC	MAR	NI	NP	RR
BEAMS	V				
JOISTS	V				
POSTS	V				
PIERS			Ø		

Comments:

Where visible, framing and support was in good condition.



Under Floor Framing & Support:



Under Floor Framing & Support:



Under Floor Framing & Support:

Inspection Date: 11/14/2022

Inspector: Eddie Restani Inspector Phone: 312-771-1293



ELECTRICAL RAN	DOM SAMPLE					
SERVICE SIZE (Main Pa	nnel)					
☑ Brand: Eaton	Main Disconnect Location: Lower Level	☑ 120 / 24	40 Volt	(Non	ninal)	
☑ 200 AMP						
		ACC	MAR	NI	NP	RR
SERVICE						
ENTRANCE CABLE		Ø				
PANEL						
SUB-PANEL					Ø	
BRANCH CIRCUITS		Ŋ				
BONDING/GROUNDING		Ŋ				
GFCI(IN PANEL)*					Ø	
ARC FAULT		Ø				
SMOKE DETECTORS*		Ø				
CLOSETS		Ø				
BREAKERS						

Comments:

Electrical acceptable at time of inspection.

\*Smoke Detectors / GFCI's checked with test button only. Monthly Test Recommended.



Electrical Random Sample:



Electrical Random Sample:

Inspection Date: 11/14/2022

Inspector: Eddie Restani Inspector Phone: 312-771-1293



# **National Property Inspections**

Sample-Townhouse

PLUMBING					
Water Service					-
☑ Water Public					
Sewage Service					
☑ Sewage Public					
General Deterioration					
	ACC	MAR	NI	NP	RR
SUPPLY					
DRAINS					
EJECTOR PUMP					
VENTS					

#### Comments:

No defects were found pertaining to the main plumbing system.

Main utility line, septic systems and gray water systems are excluded from this Inspection.



Plumbing:



Plumbing:

Inspection Date: 11/14/2022

Inspector: Eddie Restani Inspector Phone: 312-771-1293



### Sample-Townhouse



Plumbing:

#### **HEATING**

Brand: Carrier	Age: 3 Year(s)	Design Life: 15-20 Year(s)	SerialNo: 1	619A	60478		
⊠Gas	☑ Forced Air						
			ACC	MAR	NI	NP	RR
OPERATION			M				
ABOVE GROUND STOR	AGE TANKS					V	
HUMIDIFIER					V		

Comments:

Furnace was running properly at time of inspection. Heat distribution was acceptable with no problems to report. It is important that the furnace be properly maintained for efficiency and greater life span. Recommend a yearly maintenance program be set up with a local heating company to service and clean the furnace. This could greatly improve the life span of unit.

Heat Exchanger - Unable to detect cracks/holes without dismantling unit.



# Sample-Townhouse



Heating:



Heating:

Inspection Date: 11/14/2022

Inspector: Eddie Restani Inspector Phone: 312-771-1293



**Property Inspections Plus, Inc. DBA** 

# **National Property Inspections**

### Sample-Townhouse

KITCHEN/BREAKFAST	ACC	MAR	NI	NP	RR
CEILINGS	V				
WALL(S)	V				
WINDOWS/TRIM	V				
WINDOW SCREENS	V				
FLOOR/FINISH	V				
INTERIOR DOORS/HARDWARE	V				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	V				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST RECOMMENDED.)	V				
HEAT/AIR DISTRIBUTION	V				
COUNTERTOPS/CABINETS	V				
SINK/FAUCET	V				
EXHAUST FAN	V				
STOVE TOP/OVEN	V				
STOVE ANTI-TIP BRACKET	V				
WATER PRESSURE/FLOW/DRAINAGE	V				
DISHWASHER/CROSS FLOW PROTECTION	V				
REFRIGERATOR	V				
MICROWAVE	V				
GARBAGE DISPOSAL	V				

Comments:

All components in kitchen were acceptable at time of inspection.



# Sample-Townhouse



Kitchen/Breakfast:



Kitchen/Breakfast:



Kitchen/Breakfast:



# **Summary**

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

### **1 GUTTERS/DOWN SPOUTS**

REPAIR/REPLACE

Missing extensions at downspouts. Recommend installing downspout extensions to divert water 4 to 6 feet away from the foundation.

Limited observation due to snow cover.



**GUTTERS/DOWN SPOUTS:** 



**GUTTERS/DOWN SPOUTS:** 

MAR (MARGINAL)	The item/system was marginally acceptable. It performed its designed function at the time of the inspection. However, due to age and/or deterioration, it will likely require early repair or replacement.
RR (REPAIR/REPLACE)	The item/system failed to operate/perform its intended function, was structurally deficient, was unsafe or was hazardous at the time of the inspection.