

National Property Inspections

Jim Sample, 000 Main St, New Carlisle, IN, 46552









Tuesday, April 13, 2021
Inspector
Steven Hampton
574-404-7559
steven.hampton@npiinspect.com
HI02100025
NPI Michiana - Sample Report

Inspection Date: 04/13/2021

Inspector: Steven Hampton
Inspector Phone: 574-404-7559

Email: steven.hampton@npiinspect.com



National Property Inspections

Jim Sample, 000 Main St, New Carlisle, IN, 46552

GENERAL INFORMATION

GENERAL CONDITIONS AT TIME OF INSPECTION:

Property Occupied: Yes Estimated Age Of Property: 22 Ye Property Faces: ☑ North □ South □ E	Sunny
Type of Property: ☑ Single-Family Primary Construction: ☑ Block ☑ Wood	Soil Conditions : ☑ Dry Persons Present : ☑ Buyer

DEFINITIONS:

Below are listed the definitions used throughout the report to describe each feature of the property.

ACC (ACCEPTABLE) The item/system was performing its intended function at the time of the inspection.

MAR (MARGINAL) The item/system was marginally acceptable. It performed its designed function at the time of the

inspection. However, due to age and/or deterioration, it will likely require early repair or replacement.

NI (NOT INSPECTED) The item/system was not inspected due to safety concerns, inaccessibility and/or concealment or seasonal

conditions and no representations of whether or not it was functioning as intended were made.

NP (NOT PRESENT) The item/system does not exist or was visually concealed at the time of the inspection.

DEF (DEFECTIVE)The item/system failed to operate/perform its intended function, was structurally deficient, was unsafe or

was hazardous at the time of the inspection.

SCOPE OF THE INSPECTION:

We wish to remind you that every property requires a certain amount of ongoing maintenance: drains sometimes clog, gutters, downspouts and the grading around the property must be properly maintained to help prevent water intrusion in to the basement or crawlspace; roofs, furnaces, air conditioners and other components require regular maintenance and inspection. This property will be no exception and we strongly suggest that you both expect and budget for regular maintenance/repairs.

The following report is based on visual inspection of the readily accessible areas of this property and on a random sampling of like items, <u>not every item was or could be inspected</u>. Please read the entire report carefully, ask your inspector any questions you might have <u>and obtain estimates or discuss noted items with a contractor before</u> closing.

Inspection Date: Inspector: Steven Hampton Email: steven.hampton@npiinspect.com

04/13/2021 Inspector Phone: 574-404-7559 HI02100025



National Property Inspections

Jim Sample, 000 Main St, New Carlisle, IN, 46552

GRADING / DRAINAGE Monitor Condition ACC MAR NI NP DEF Output Outp							
	GRADING / DRAINAGE	☑ Monitor Condition					
			ACC	MAR	NI	NP	DEF

☑ Negative Slope ☑ Positive Slope

Comments:

• Some spots of negative sloping/erosion near foundation. The grade and downspouts around the structure should direct water at least 4 feet away from the foundation around entire perimeter.



Grading / Drainage:

			ACC	MAR	NI	NP	DEF
DRIVEWAY			\square				
☑ Concrete	☑ Cracks	☑ General Deterioration					

Comments:

The driveway was in generally good condition with minor cracks, no settlement and had an acceptable surface.

Inspection Date: 04/13/2021

Inspector: Steven Hampton Inspector Phone: 574-404-7559 Email: steven.hampton@npiinspect.com



National Property Inspections

Jim Sample, 000 Main St, New Carlisle, IN, 46552







ACC MAR

 $\overline{\mathbf{V}}$

NP

DEF

Roofing: Hail dents

FLASHING/VALLEYS

☑ Composition / Membrane ☑ Metal

☑Exposed Nails

Comments:

- All valleys and flashings that were readily visible at time of inspection were acceptable.
- Flashing on roof vents may require periodic routine maintenance from time to time.



Flashing/Valleys: Junction of upper home to lower home roofing



Flashing/Valleys:

Inspection Date: 04/13/2021

Inspector: Steven Hampton Inspector Phone: 574-404-7559 Email: steven.hampton@npiinspect.com



National Property Inspections

Jim Sample, 000 Main St, New Carlisle, IN, 46552

Attic / Roof

Method of Inspection ☑ Visual from Access ☑ No Access / Limited 10 % Visible

ATTIC FRAMING/SHEATHING

ACC MAR NI NP DEF $\sqrt{}$

☑ Plywood / Panel Board / OSB


☑ Rafters

☑Trusses

Comments:

- Attic access point was in the closet of main bedroom.
- Attic access was restricted/limited by the homeowner's possessions and narrow design of attic entryway.
- Observation of the sheathing and supports from the access point revealed no active moisture stains or damage.

Leaks not always detectable.



Attic Framing/Sheathing: Another view of upper house attic access for context



Attic Framing/Sheathing: Roof sheathing with static attic vent

ACC MAR

ATTIC VENTILATION $\overline{\mathbf{V}}$ **☑** Gable ☑ Static Vent

Comments:

At the time of inspection, attic ventilation was acceptable.

Inspection Date: Inspector: Steven Hampton Email: steven.hampton@npiinspect.com Inspector Phone: 574-404-7559 04/13/2021 HI02100025

NP

DEF



National Property Inspections

Jim Sample, 000 Main St, New Carlisle, IN, 46552

PLUMBING

Water Service

☑ Water Public

☑ Shut Off Location: Basement utility room

Sewage Service

☑ Sewage Public

Fuel Service

☑ Shut Off Location: Exterior rear

	ACC	MAR	NI	NP	DEF
SUPPLY Copper CPVC	Ø				
DRAINS	Ø				
EJECTOR PUMP				Ø	
VENTS	Ø				

Comments:

No defects were found pertaining to the main plumbing system.

Main utility line, septic systems and gray water systems are excluded from this Inspection.



Plumbing: Plumbing and heat venting from hot water heater in utility room



Plumbing: Drain assembly under kitchen sink

Inspection Date: 04/13/2021

Inspector: Steven Hampton Inspector Phone: 574-404-7559 Email: steven.hampton@npiinspect.com



National Property Inspections

Jim Sample, 000 Main St, New Carlisle, IN, 46552

HEATING	☑ Monitor Condition						
Brand: Armstrong Design Life: 10-20 Year(s)	Model: GUJ075D10-3A SerialNo: 8498L26004	BTUs: 60000	Age: 23	Year(s)			
 Gas	☑ Forced Air	☑Beyond Design Life	☑ Corro	led / Le	aking		
☑ Needs Normal Maintenance	/ Cleaning						
			AC	MAR	NI	NP	DEF
OPERATION			✓				
ABOVE GROUND STORAGE T	TANKS					Ø	
HUMIDIFIER			☑				
AGE OF UNIT				Ø			

Comments:

Unit was operational and produced heat with a blue, conical flame at burners at time of inspection.

- HVAC unit is beyond design life. Date of manufacture: 11/1998. Average lifespan is 10 to 20 years.
- There was corrosion inside and on the outside of the cabinet.
- Some calcification was also present as was previously noted.
- Heater had a mist-type humidifier installed. Suspect spray from mechanism at some point.
- Recommend service and cleaning of unit.

Heat Exchanger - Unable to detect cracks/holes without dismantling unit.







Heating: Flame burners operational

Inspection Date: Inspector: Steven Hampton Email: steven.hampton@npiinspect.com 04/13/2021 Inspector Phone: 574-404-7559 HI02100025



National Property Inspections

Jim Sample, 000 Main St, New Carlisle, IN, 46552

KITCHEN	☑ Monitor Condition	ACC	MAR	NI	NP	DEF
CEILINGS		Ø				
WALL(S)		V				
WINDOWS/TRIM			Ø			
WINDOW SCREENS Damaged			Ø			
FLOOR/FINISH		V				
INTERIOR DOORS/HARDWARE		V				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)		V				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST	Γ RECOMMENDED.)	Ø				
HEAT/AIR DISTRIBUTION		V				
COUNTERTOPS/CABINETS		V				
SINK/FAUCET		V				
EXHAUST FAN					Ø	
STOVE TOP/OVEN Gas		V				
STOVE ANTI-TIP BRACKET					V	
WATER PRESSURE/FLOW/DRAINAGE		V				
DISHWASHER/CROSS FLOW PROTECTION				V		
REFRIGERATOR		V				
MICROWAVE		Ø				
GARBAGE DISPOSAL					V	

Comments:

- Light on microwave did not work.
- Did not test dishwasher due to dishes present inside unit at the time of inspection.
- Caulk separation at the rear of the countertop
- Client stated countertops were just redone and suspect work was done incorrectly.
- Recommend checking with original installer to see if a warranty is available for repairs.
- Recommend evaluation/repair by licensed contractor as needed.

Inspection Date: Inspector: Steven Hampton Email: steven.hampton@npiinspect.com Inspector Phone: 574-404-7559 04/13/2021



National Property Inspections

Jim Sample, 000 Main St, New Carlisle, IN, 46552



Kitchen:



Kitchen:



Kitchen:



Kitchen: Recaulking needed along back of sink countertop



National Property Inspections

Jim Sample, 000 Main St, New Carlisle, IN, 46552

BATHROOM	ACC	MAR	NI	NP	DEF
CEILINGS	Ø				
WALL(S)	Ø				
WINDOWS/TRIM				Ø	
WINDOW SCREENS				V	
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST RECOMMENDED.)	Ø				
HEAT/AIR DISTRIBUTION	Ø				
COUNTERTOPS/CABINETS	Ø				
SINK/FAUCET	Ø				
TOILET	Ø				
TUB/SHOWER	Ø				
EXHAUST FAN	Ø				
WATER PRESSURE/FLOW/DRAINAGE	Ø				

Comments:

- All components in bathroom were acceptable at time of inspection.
- Recommend recaulking around tub and sink as part of routine maintenance.



Bathroom:

Inspection Date: Inspector: Steven Hampton Email: steven.hampton@npiinspect.com Inspector Phone: 574-404-7559 04/13/2021