

Sample Report, Single Family Sample Report, Key Largo, Fl, 33037









Thursday, March 27, 2025
Inspector
Juan Restrepo
305.713.5010
juan.restrepo@npiinspect.com
HI13753



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037

GENERAL INFORMATION

GENERAL CONDITIONS AT TIME OF INSPECTION:

Property Occupied: Yes Estimated Age Of Property: 2 Year(s) Property Faces: □ North ☑ South □ East □ West	Temperature: 83 F Weather: ☑ Sunny
Type of Property: ☑ Single-Family	Soil Conditions : ☑ Dry
Primary Construction: ☐ Block	Persons Present : ☑ Buyer's Agent ☑ Seller's Agent

DEFINITIONS:

Below are listed the definitions used throughout the report to describe each feature of the property.

ACC (ACCEPTABLE) The item/system was performing its intended function at the time of the inspection.

MAR (MARGINAL) The item/system was marginally acceptable. It performed its designed function at the time of the

inspection. However, due to age and/or deterioration, it will likely require early repair or replacement.

NI (NOT INSPECTED) The item/system was not inspected due to safety concerns, inaccessibility and/or concealment or seasonal

conditions and no representations of whether or not it was functioning as intended were made.

NP (NOT PRESENT) The item/system does not exist or was visually concealed at the time of the inspection.

RR (REPAIR/REPLACE) The item/system failed to operate/perform its intended function, was structurally deficient, was unsafe or

was hazardous at the time of the inspection.

SCOPE OF THE INSPECTION:

We wish to remind you that every property requires a certain amount of ongoing maintenance: drains sometimes clog, gutters, downspouts and the grading around the property must be properly maintained to help prevent water intrusion in to the basement or crawlspace; roofs, furnaces, air conditioners and other components require regular maintenance and inspection. This property will be no exception and we strongly suggest that you both expect and budget for regular maintenance/repairs.

The following report is based on visual inspection of the readily accessible areas of this property and on a random sampling of like items, <u>not every item was or could be inspected</u>. Please read the entire report carefully, ask your inspector any questions you might have <u>and obtain estimates or discuss noted items with a contractor before</u> closing.

Inspection Date: Inspector: Juan Restrepo Email: juan.restrepo@npiinspect.com

03/27/2025 Inspector Phone: 305.713.5010 HI13753



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037

DRIVEWAY ACC MAR NI NP RR D □ □ □ □

☑ Gravel


Comments:

Gravel driveways may erode from heavy rains. Recommend monitoring the condition and repair as necessary.









Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037

	ACC	MAR	NI	NP	RR
WALKS / STEPS	V				

☐ Concrete

Comments:

Walkways/steps to the house and around the property were in good condition at time of the inspection.









Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037

3RD FLOOR BALCONY

ACC MAR NI NP RR

Comments:

Balcony and all related components appeared to be acceptable at time of inspection.









Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037



2ND FLOOR BALCONY

ACC MAR NI NP RR

Comments:

Balcony and all related components appeared to be acceptable at time of inspection.





Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037







	ACC	MAR	NI	NP	RR
ROOFTOP BALCONY	V				

Comments:

Rooftop area and all related components appeared to be acceptable at time of inspection.

Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037













Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037



BACKYARD

☑ Faux Grass

Comments:

☑ Concrete

Backyard area was in acceptable condition Area was functional at time of inspection.





ACC MAR

 $\overline{\mathbf{V}}$

NP

RR

Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037





ACC MAR

 $\overline{\mathbf{V}}$

NP

RR

FENCES / GATES

☑Metal

Comments:

Metal fence was in generally good condition with operational gate(s).





Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037













Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037

			ACC MAR NI NP RR
ROOFING			
Age: 2 Year(s)	Design Life: 15-20 Year(s)	Layers: 1	100% Visible
✓Metal	☑Concrete Roof		

Comments:

The flat roof appeared to be in acceptable condition for its age. Recommend an annual inspection and tune-up to minimize the risk of leakage and to maximize the life of the roof.

A metal roof was present. Metal roofs require routine maintenance such as painting. Monitor condition and paint as necessary.

Metal roofs should be coated periodically.

Overall the roof was in acceptable condition with no active leaks noted on day of inspection.

Leaks not always detectable.





Inspection Date: 03/27/2025


Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037













Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037

GUTTERS/DOWN SPOUTS

☑ Recommend Repairs

ACC	MAR	NI	NP	RR
	Ø			

Comments:

Gutter downspouts were crushed, recommend repair to allow proper water flow









Rain Chain present

Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037

EXTERIOR SURFACE

☑ Stucco

	ACC	MAR	NI	NP	RR
SIDING/TRIM					
EXTERIOR FAUCETS	Ø				
EXTERIOR ELECTRICAL OUTLETS	Ø				
EXTERIOR LIGHTING	V				

Comments:

Exterior of the house and the components listed were acceptable at time of inspection.

All exterior siding/surface appeared in good state of repair at time of inspection with no major defects noted.






Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037













Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037


EXTERIOR SURFACE - ADDITIONAL PHOTOGRAPHS	ACC	MAR	NI	NP	RR
SIDING/TRIM	Ø				
EXTERIOR FAUCETS	Ø				
EXTERIOR ELECTRICAL OUTLETS	Ø				
EXTERIOR LIGHTING	V				

Comments:

Exterior of the house and the components listed were acceptable at time of inspection.

All exterior siding/surface appeared in good state of repair at time of inspection with no major defects noted.









Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037

	ACC	MAR	NI	NP	RR
WINDOWS	☑				

☑Metal

Comments:

All accessible windows were checked for leaks and operation. No leaks or water stains were observed and windows were operating properly.

All windows appeared to be in good repair at time of inspection from the exterior.










Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037



EXTERIOR DOORS

ACC MAR NI NP RR

Comments:

Entry doors and the associated hardware were tested and operated as intended. The exterior doors are in acceptable condition with no visual flaws or defects.





Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037



Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037

ELECTRICAL							
SERVICE SIZE (Main I	Panel)						
☑Brand: Square D	☑ 120 / 240 Volt (Nominal)	☑200 AMP					
			ACC	MAR	NI	NP	RR
SERVICE			\square				
ENTRANCE CABLE			Ø				
PANEL			Ø				
SUB-PANEL			Ø				
BRANCH CIRCUITS			Ø				
BONDING/GROUNDING			Ø				
GFCI(IN PANEL)*			Ø				
ARC FAULT			Ø				
SMOKE DETECTORS*			✓				

Comments:

The electrical service entrance and panel are in good condition and appear to be performing as intended.

A random sampling of electrical outlets and light switches was conducted. All defects may not be identified in this inspection. Only a competent licensed electrician spending considerable time and effort, physically removing receptacles, switches and fixtures, could do a full and complete electrical inspection.

*Smoke Detectors / GFCI's checked with test button only. Monthly Test Recommended.





Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037



Primary electrical panel located on third floor next to main bedroom



Second electrical panel in storage closet under stairs

TESTED ELECTRICAL OUTLETS

ACC MAR NI NP RR ☑ □ □ □ □

Comments:

Electrical outlets were tested at random, all tested outlets were found to be acceptable at time of inspection

A random sampling of electrical outlets and light switches was conducted. All defects may not be identified in this inspection. Only a competent licensed electrician spending considerable time and effort, physically removing receptacles, switches and fixtures, could do a full and complete electrical inspection.





Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037







PLUMBING

Water Service

☑ Water Public

Sewage Service

☑ Sewage Public

	ACC	MAR	NI	NP	RR
SUPPLY CPVC	Ø				
DRAINS PVC	Ø				
EJECTOR PUMP				V	
VENTS PVC	Ø				

Inspection Date: 03/27/2025

Inspector: Juan Restrepo

Inspector Phone: 305.713.5010

Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037

Comments:

No defects were found pertaining to the main plumbing system at time of inspection.

Not all plumbing leaks or moisture can be found as it is sometimes hidden in wall cavities or beneath the floor. A regular check of all fixtures and plumbing components is recommended.

Inspecting plumbing components in hidden areas such as in walls, ceilings, and underground is beyond the scope of this general home inspection.

Main utility line, septic systems and gray water systems are excluded from this Inspection.










Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037











Sample Report, Single Family Sample Report, Key Largo, Fl, 33037

			ACC MAR NI NP RR
WATER HEATER			
Model: RSC199iP	Age: 2 Year(s)	Design Life: 10-15 Year(s)	SerialNo: PF.BA-131048
 Gas	☐Tankless		

Comments:

The operation and installation of the water heater appeared to be satisfactory at time of inspection. Hot water heater operation was considered satisfactory as hot water was delivered on request.

The tankless water heater was acceptable at time of inspection.

Gas-fired tankless water heater installed and appeared to be in acceptable condition and supplied hot water upon demand at the time of the inspection.







Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037

LAUNDRY FACILITIES

Location: Laundry room

	ACC	MAR	NI	NP	RR
UTILITY HOOKUPS	V				
DRYER VENTS	Ø				
LAUNDRY TUB	Ø				
DRAIN	Ø				

Comments:

The washer was run through a short cycle to test the drain capability. There were no issue at the time of the inspection. The dryer was tested and ran and vented properly at the time of the inspection. All components in laundry room were acceptable at time of inspection.





Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037













Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037

			A	ACC	MAR	NI	NP	RR
COOLING UNIT 1				Ø				
Brand: Rheem SerialNo: W102253871	Model: RH1T3617STANJA	Age: 2 Year(s)	Design Life: 10-15 Year(s)					
☑Electric	☑ Central Air							

Comments:

The air conditioning system responded to the controls and appeared to operate in a satisfactory manner. All visible components of the air-conditioning system appeared to be in serviceable condition at the time of the inspection. Adequate air flow was present. Recommend bi-annual cleaning of ductwork in order to maintain proper operation and to extend life expectancy of unit.

Recommend repair/regular service to maintain peak performance.









Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037



COOLING UNIT 2

Brand: Rheem Model: RH1T4821STANJA Age: 2 Year(s) Design Life: 10-15 Year(s)

SerialNo: W172227344

☑ Electric ☑ Central Air

Comments:

The air conditioning system responded to the controls and appeared to operate in a satisfactory manner. All visible components of the air-conditioning system appeared to be in serviceable condition at the time of the inspection. The air conditioning system responded to the controls and appeared to operate in a satisfactory manner. Adequate air flow was present. Recommend bi-annual cleaning of ductwork in order to maintain proper operation and to extend life expectancy of unit.

Recommend repair/regular service to maintain peak performance.





ACC MAR NI

 $\overline{\mathbf{Q}}$

NP


RR

Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037







KITCHEN	ACC	MAR	NI	NP	RR
CEILINGS	☑				
WALL(S)	Ø				
WINDOWS/TRIM	Ø				
WINDOW SCREENS	Ø				
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST RECOMMENDED.)	Ø				

Inspection Date: 03/27/2025

Inspector: Juan Restrepo

Inspector Phone: 305.713.5010

Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037

HEAT/AIR DISTRIBUTION	Ø			
COUNTERTOPS/CABINETS	Ø			
SINK/FAUCET	Ø			
EXHAUST FAN	Ø			
STOVE TOP/OVEN Gas	Ø			
STOVE ANTI-TIP BRACKET			Ø	
WATER PRESSURE/FLOW/DRAINAGE	Ø			
DISHWASHER/CROSS FLOW PROTECTION	Ø			
REFRIGERATOR	Ø			
MICROWAVE	Ø			
GARBAGE DISPOSAL	Ø			

Comments:

All components in kitchen were acceptable at time of inspection.





Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037













Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037

MAIN ROOM BATHROOM	ACC	MAR	NI	NP	RR
CEILINGS	Ø				
WALL(S)	Ø				
WINDOWS/TRIM	Ø				
WINDOW SCREENS				Ø	
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST RECOMMENDED.)	Ø				
HEAT/AIR DISTRIBUTION	V				
COUNTERTOPS/CABINETS	Ø				
SINK/FAUCET	Ø				
TOILET	Ø				
TUB/SHOWER	Ø				
JETTED TUB	Ø				
TILE WORK/ENCLOSURE				Ø	
EXHAUST FAN	Ø				
WATER PRESSURE/FLOW/DRAINAGE	Ø				

Comments

All components in bathroom were acceptable at time of inspection.





Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037








Water heater delivering hot water at time of inspection



Acceptable water flow in shower



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037



BATHROOM 2	ACC	MAR	NI	NP	RR
CEILINGS	V				
WALL(S)	Ø				
WINDOWS/TRIM	Ø				
WINDOW SCREENS				Ø	
FLOOR/FINISH	V				
INTERIOR DOORS/HARDWARE	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST RECOMMENDED.)	V				
HEAT/AIR DISTRIBUTION	Ø				
COUNTERTOPS/CABINETS	V				
SINK/FAUCET	Ø				
TOILET	V				
TUB/SHOWER	V				
JETTED TUB					
TILE WORK/ENCLOSURE	Ø				
EXHAUST FAN	Ø				
WATER PRESSURE/FLOW/DRAINAGE	V				

Comments:

All components in bathroom were acceptable at time of inspection.


Inspection Date: 03/27/2025


Inspector: Juan Restrepo

Inspector Phone: 305.713.5010

Email: juan.restrepo@npiinspect.com















Water heater delivering hot water at time of inspection



Acceptable water flow in shower





Outlets properly wired in this area



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037

BATHROOM 3	۸СС	MAR	NI	NP	RR
CEILINGS	ACC ☑				
WALL(S)	Ø				
WINDOWS/TRIM	Ø				
WINDOW SCREENS				V	
FLOOR/FINISH	V				
INTERIOR DOORS/HARDWARE	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	V				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST RECOMMENDED.)	V				
HEAT/AIR DISTRIBUTION	Ø				
COUNTERTOPS/CABINETS	V				
SINK/FAUCET	V				
TOILET	Ø				
TUB/SHOWER	V				
JETTED TUB				Ø	
TILE WORK/ENCLOSURE	Ø				
EXHAUST FAN	Ø				
WATER PRESSURE/FLOW/DRAINAGE	V				

Comments:

All components in bathroom were acceptable at time of inspection.

Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com








Water heater delivering hot water at time of inspection







Sample Report, Single Family Sample Report, Key Largo, Fl, 33037



BATHROOM 4	ACC	MAR	NI	NP	RR
CEILINGS	Ø				
WALL(S)	Ø				
WINDOWS/TRIM	Ø				
WINDOW SCREENS				Ø	
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST RECOMMENDED.)	Ø				
HEAT/AIR DISTRIBUTION	Ø				
COUNTERTOPS/CABINETS	Ø				
SINK/FAUCET	Ø				
TOILET	Ø				
TUB/SHOWER	Ø				
JETTED TUB				Ø	
TILE WORK/ENCLOSURE	Ø				
EXHAUST FAN	Ø				
WATER PRESSURE/FLOW/DRAINAGE	Ø				

Comments:

All components in bathroom were acceptable at time of inspection.

Inspection Date: Inspector: Juan Restrepo Email: juan.restrepo@npiinspect.com

03/27/2025 Inspector Phone: 305.713.5010 HI13753











Water heater delivering hot water at time of inspection





Acceptable water flow in shower





Outlets properly wired in this area



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037

MAIN ROOM	ACC	MAR	NI	NP	RR
CEILINGS	//CC				
WALLS	V				
WINDOWS/TRIM					
WINDOW SCREENS	Ø				
FLOOR/FINISH	☑				
INTERIOR DOORS/HARDWARE	Ø				
CLOSET	V				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
HEAT/AIR DISTRIBUTION	V				

Comments:

Ceiling and walls were free of cracks. Window(s) functioned properly and seals were acceptable. Receptacles and lights were wired correctly.

Sliding glass doors functioned properly and seals were acceptable.






Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037





BEDROOM 2	ACC	MAR	NI	NP	RR
CEILINGS	V				
WALLS	Ø				
WINDOWS/TRIM	Ø				
WINDOW SCREENS	V				
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	V				
CLOSET	V				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	V				
HEAT/AIR DISTRIBUTION	V				

Comments:

Ceiling and walls were free of cracks. Window(s) functioned properly and seals were acceptable. Receptacles and lights were wired correctly.

Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037













Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037



Proper wiring noted along electrical outlets in area

BEDROOM 3	ACC	MAR	NI	NP	RR
CEILINGS	☑				
WALLS	Ø				
WINDOWS/TRIM	V				
WINDOW SCREENS				V	
FLOOR/FINISH	V				
INTERIOR DOORS/HARDWARE	Ø				
CLOSET	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	V				
HEAT/AIR DISTRIBUTION	Ø				

Comments:

Ceiling and walls were free of cracks. Window(s) functioned properly and seals were acceptable. Receptacles and lights were wired correctly.

Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037













Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037



Proper wiring noted along electrical outlets in area

BEDROOM 4	ACC	MAR	NI	NP	RR
CEILINGS	Ø				
WALLS	Ø				
WINDOWS/TRIM	V				
WINDOW SCREENS				Ø	
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
CLOSET	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
HEAT/AIR DISTRIBUTION	Ø				

Comments:


Ceiling and walls were free of cracks. Window(s) functioned properly and seals were acceptable. Receptacles and lights were wired correctly.

Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com














Sample Report, Single Family Sample Report, Key Largo, Fl, 33037







CORRIDOR ACCESS TO ROOMS	ACC	MAR	NI	NP	RR
CEILINGS	V				
WALLS	Ø				
WINDOWS/TRIM				Ø	
WINDOW SCREENS				Ø	
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
CLOSET	Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
HEAT/AIR DISTRIBUTION	\square				

Comments:


Ceiling and walls were free of cracks. Receptacles and lights were wired correctly.

Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037









				,	
LIVING/DINING ROOM	ACC	MAR	NI	NP	RR
CEILINGS	Ø				
WALLS	Ø				
WINDOWS/TRIM	☑				
WINDOW SCREENS	Ø				
FLOOR/FINISH	V				
INTERIOR DOORS/HARDWARE	Ø				
CLOSET	V				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
HEAT/AIR DISTRIBUTION	Ø				

Inspection Date: 03/27/2025

Inspector: Juan Restrepo

Inspector Phone: 305.713.5010

Email: juan.restrepo@npiinspect.com




Sample Report, Single Family Sample Report, Key Largo, Fl, 33037


Comments:

Ceiling and walls were free of cracks. Window(s) functioned properly and seals were acceptable. Receptacles and lights were wired correctly.

Sliding glass doors functioned properly and seals were acceptable










Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037





1ST FLOOR LOUNGE AREA	ACC	MAR	NI	NP	RR
CEILINGS	V				
WALLS	Ø				
WINDOWS/TRIM				Ø	
WINDOW SCREENS				Ø	
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
CLOSET					
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	☑				
HEAT/AIR DISTRIBUTION	☑				

Comments:


Ceiling and walls were free of cracks. Receptacles and lights were wired correctly.

Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037









STORAGE ROOM	ACC	MAR	NI	NP	RR
CEILINGS	Ø				
WALLS	Ø				
WINDOWS/TRIM				Ø	
WINDOW SCREENS				Ø	
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
CLOSET				Ø	
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
HEAT/AIR DISTRIBUTION				V	

Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037

Comments:

Storage room functional at time of inspection, no evidence of damage noted to structures







Bathroom for 1st floor located in 1st floor storage room

STAIRS / RAILINGS - EXTERIOR OF HOME

ACC	MAR	NI	NP	RR
V				

Comments:

Stairs and Railings were acceptable at time of inspection

Inspection Date: 03/27/2025


Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037















Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037





STAIRS / RAILINGS - INTERIOR OF HOME

ACC MAR NI NP RR ☑ □ □ □ □

Comments:

Stairs and Railings were acceptable at time of inspection






Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037



HUMIDITY THROUGHOUT PROPERTY

ACC MAR NI NP RR

Comments:

Overall no damaging levels of humidity were detected throughout property upon random sampling with a noninvasive moisture meter.





Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037

	ACC	MAR	NI	NP	RR
ELEVATOR ACCESS	☑				

Comments:

Elevator access was acceptable at time of inspection

The elevator functioned and went up and down the floors with ease. The elevator arrived at the floor called when called.

Review all safety features regarding this device before operation









Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037







	ACC	MAR	NI	NP	RR
STEAMER/SAUNA MACHINE	\square				

Comments:

Steamer/Sauna machine noted in closet of main bedroom, this unit was observed to be functional at time of inspection, recommend general maintenance to prevent deterioration

Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037













Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com





Control panel for steamer in shower



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037

SWIMMING POOL

☑ In Ground ☑ Concrete					
	ACC	MAR	NI	NP	RR
SHELL/LINER/HARDCOAT	Ø				
HEATER ☑Gas	Ø				
FILTER	☑				
PUMP(S)	☑				
ELECTRICAL	V				
LIGHTS	☑				
GFCI (CHECKED W/TEST BUTTON ONLY).					
CHILD SAFETY FENCE				Ø	
CHILD SAFETY GATE				Ø	
DECK/APRON	Ø				

Comments:

All components of the pool system appeared to be acceptable at time of inspection. No child safety fence/gate installed.

Luminaries worked properly at time of inspection.

NOTE: Pool Bodies, Diving Boards, Slides, Self-Cleaning & Chlorinating Devices are beyond the scope of this inspection.





Inspection Date: 03/27/2025


Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com















Sample Report, Single Family Sample Report, Key Largo, Fl, 33037

SWIMMING POOL MACHINERY

ACC MAR NI NP RR

Comments:

All components of the pool system appeared to be acceptable at time of inspection.

Pool heater was turned on remotely and was observed to be working at time of inspection









Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037









©1996-2025



Sample Report, Single Family Sample Report, Key Largo, Fl, 33037

Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

1 GUTTERS/DOWN SPOUTS

MARGINAL

Gutter downspouts were crushed, recommend repair to allow proper water flow



MAR (MARGINAL)

The item/system was marginally acceptable. It performed its designed function at the time of the inspection. However, due to age and/or deterioration, it will likely require early repair or replacement.

RR (REPAIR/REPLACE)

The item/system failed to operate/perform its intended function, was structurally deficient, was unsafe or was hazardous at the time of the inspection.

Inspection Date: 03/27/2025

Inspector: Juan Restrepo Inspector Phone: 305.713.5010 Email: juan.restrepo@npiinspect.com