

National Property Inspections

Commercial Sample-Homewood, IL, IL



Monday, November 14, 2022 Inspector Eddie Restani 312-771-1293

450.012272 Expires: 11/30/2024

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



National Property Inspections

Commercial Sample-Homewood, IL, IL

PARKING LOT/DRIVEWAYS

G F P NI NA
□ ☑ □ □ □

✓ Asphalt ✓ Cracks ✓ General D

☑ General Deterioration ☑ Settlement

Comments:

Curbs cracked, light pole base loose, loose wood beneath metal by entrance, driveway has settled away from building.

Recommend further evaluation/repair by qualified contractor(s).



Parking Lot/Driveways:



Parking Lot/Driveways:



Parking Lot/Driveways:

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



National Property Inspections

Commercial Sample-Homewood, IL, IL

	G	F	P	NI	NA
ROOFING		Ø			


Age: Undetermined Year(s) Design Life: 20-25 Year(s)

☑ Ladder at Eaves ☑ Walked On ☑ Rolled Composition ☑ Previous Repairs Noted

☑ Suspected Leak(s)

Comments:


Several cracked areas, ponding and previous repairs noted. Recommend further evaluation/repair by qualified roofing contractor(s).



Roofing:



Roofing:



Roofing:



Roofing:

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



National Property Inspections

Commercial Sample-Homewood, IL, IL

EXTERIOR SURFACE

 ✓ Stucco	☑ Concrete	☑ Cracked	☑ General Deterioration			n	
☑Missing / Loose	☑ Needs Caulk / Seal	☑ Poor Earth / Siding Clearance	,				
			G	F	P	NI	NA
EXTERIOR WALL FINISH				Ø			
EXTERIOR FAUCETS						Ø	
EXTERIOR ELECTRICAL OUTLETS					☑		
EXTERIOR LIGHTING AND	SIGNAGE		\square				

Comments:

Several areas around building had loose/deteriorated seal, cracks or holes. Roots/vines stuck in siding. All exterior outlets inoperable and GFCI did not trip under fault conditions.


All outlets did not have a weather cap that allows long term fixtures to be plugged in while cap is closed.

Recommend replacing with a weather cap cover that accommodates plug.

Recommend further evaluation/repair by qualified electrician(s).



Exterior Surface:



Exterior Surface: Inoperable.

Inspection Date: Inspector: Eddie Restani Email:




National Property Inspections

Commercial Sample-Homewood, IL, IL



Exterior Surface:



Exterior Surface:

PARAPET WALL SYSTEM

✓Metal	☑ Cracked	☐ General Deterioration	☑Needs Caulk / Seal				
			G	F	P	NI	NA
EXTERIOR FINISH				Ø			
CAP FLASHING			☑				
COVING / FLASHING			☑				
SCUPPERS			V				

Comments:

Ponding/possible leaks above entrance and other areas. Recommend further evaluation/repair by qualified contractor(s).



Parapet Wall System:



Parapet Wall System:

Inspection Date: 11/14/2022

Inspector: Eddie Restani Inspector Phone: 312-771-1293 Email:



National Property Inspections

Commercial Sample-Homewood, IL, IL

FENESTRATION SYSTEMS

G F P NI NA
□ □ ☑ □ □

✓Metal

☑Fogged

☐ General Deterioration

☑ Needs Caulk / Seal

Comments:

Most thermal windows around the building were fogged due to loss of thermal seal. Recommend further evaluation/repair by qualified window contractor(s).



Fenestration Systems:



Fenestration Systems:



Fenestration Systems:



Fenestration Systems:

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



National Property Inspections

Commercial Sample-Homewood, IL, IL

Attic / Roof

Method of Inspection ☑ No Access / Limited

ATTIC / ROOF FRAMING AND SHEATHING

G F P NI NA
☑ □ □ □ □

☑ Steel Decking

Comments:

Limited access due to design and ductwork.

Where visible, framing and decking in acceptable condition.

Leaks not always detectable.



Attic / Roof Framing and Sheathing:



Attic / Roof Framing and Sheathing:



Attic / Roof Framing and Sheathing:

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



National Property Inspections

Commercial Sample-Homewood, IL, IL

ELECTRICAL 1

SERVICE SIZE (Main Panel) ☑400 AMP ☑ Main Disconnect Location: Interior Middle ☑Brand: Square D **2**08Y/120 NA G NI SERVICE \checkmark ENTRANCE CABLE $\overline{\mathbf{V}}$ PANEL $\overline{\mathbf{V}}$

Comments:

SUB-PANEL

BRANCH CIRCUITS

Exterior service exposed wires and cement settling.

Exposed wires interior.

BONDING / GROUNDING

Recommend further evaluation/repair by qualified electrical contractor(s).



Electrical 1:



 $\overline{\mathbf{V}}$

 $\sqrt{}$

 $\overline{\mathbf{V}}$

Electrical 1:

Inspection Date: Inspector: Eddie Restani Email:



National Property Inspections

Commercial Sample-Homewood, IL, IL







Electrical 1:

DI	TITA	/IDI	TATA	\sim 1
М		ИKI	HN(l i l

Water Service

☑ Water Public

Sewage Service

☑ Sewage Public

☑ General Deterioration

	G	F	P	NI	NA
SUPPLY	V				
DRAINS	V				
VENTS	V				
FIRE SUPPRESSION SYSTEM				Ø	

Comments:

No defects were found pertaining to the main plumbing system.

Main utility line, septic systems and gray water systems are excluded from this Inspection.

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



National Property Inspections

Commercial Sample-Homewood, IL, IL



Plumbing 1:



 \checkmark

Plumbing 1:

WATER HEATER 1

Brand: AO Smith Size: 40 Gallon(s) Age: 3 Year(s) Design Life: 10-12 Year(s)

SerialNo: 1806109225077

Gas

Comments:

Possible asbestos pipes above water heater. Recommend further evaluation/repair by qualified contractor(s).



Water Heater 1:



Water Heater 1:

Email:

Inspection Date: Inspector: Eddie Restani 11/14/2022 Inspector Phone: 312-771-1293

Inspector Phone: 312-771-1293 450.012272 Expires: 11/30/2024

NI

NA



National Property Inspections

Commercial Sample-Homewood, IL, IL

HEATING VI

Age: Undetermined Year(s) Design Life: 15-20 Year(s)

☐ Gas ☐ Forced Air

Comments:

Unit inoperable.

Recommend further evaluation/repair by qualified HVAC contractor(s).



Heating VI:

HEATING VII

Brand: Bryant Age: 16 Year(s) Design Life: 15-20 Year(s) SerialNo: Unknown

☑ Gas ☑ Forced Air

Comments:

Rated fair due to age. Unit functional at time of inspection.

Inspection Date: Inspector: Eddie Restani Email:



National Property Inspections

Commercial Sample-Homewood, IL, IL







Heating VII:

HVAC DISTRIBUTION 1

☑ Ductwork

	G	F	P	NI	NA
DISTRIBUTION	Ø				
BLOWER	Ø				
CONTROLS/THERMOSTAT (CALIBRATIONS/TIMED FUNCTIONS NOT CHECKED.)	Ø				

Comments:

Distribution was acceptable at time of inspection.



HVAC Distribution 1:



HVAC Distribution 1:

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



National Property Inspections

Commercial Sample-Homewood, IL, IL

				G	F	P	NI	NA
HVAC					Ø			
Brand: Rheem	Age: Undetermin Year(s)	Design Life: 10-15 Year(s)	Serial	lo: N	lo tag			
☑ Electric	☑ Central Air							

Comments:

Rated marginal due to age of unit. Budget for eventual replacement.

A/C unit should not be tested in cool mode with temperature below 65 degrees for fear of damaging compressor. Recommend checking when ambient air is warmer. The temperature splits could not be properly tested with the low temperatures, even if it was safe to operate.



HVAC:

				G	F	P	NI	NA
COOLING V					Ø			
Brand: Carrier	Age: 32 Year(s)	Design Life: 10-15 Year(s)	Serial	No: 1	1789E	68494		

Comments:

☑ Electric

Rated fair due to age of unit. Budget for eventual replacement.

☑Central Air


A/C unit should not be tested in cool mode with temperature below 65 degrees for fear of damaging compressor. Recommend checking when ambient air is warmer. The temperature splits could not be properly tested with the low temperatures, even if it was safe to operate.

Inspection Date: Inspector: Eddie Restani Email:



National Property Inspections

Commercial Sample-Homewood, IL, IL







Cooling V:

ROOMS	G	F	P	NI	NA
CEILINGS	Ø				
WALLS	Ø				
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE	Ø				
ELECTRICAL	Ø				
HEAT/AIR DISTRIBUTION	Ø				
WINDOWS AND SILL					

Comments


Peeling paint, inoperable windows and moisture present. Recommend further evaluation/repair by qualified contractor(s).

Inspection Date: Inspector: Eddie Restani Email:



National Property Inspections

Commercial Sample-Homewood, IL, IL



Rooms:



Rooms:



Rooms:



Rooms: Moisture.

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



National Property Inspections

Commercial Sample-Homewood, IL, IL

Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

1 PARKING LOT/DRIVEWAYS

FAIR

Curbs cracked, light pole base loose, loose wood beneath metal by entrance, driveway has settled away from building.

Recommend further evaluation/repair by qualified contractor(s).



PARKING LOT/DRIVEWAYS:



PARKING LOT/DRIVEWAYS:



PARKING LOT/DRIVEWAYS:

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:




National Property Inspections

Commercial Sample-Homewood, IL, IL

2 ROOFING FAIR


Several cracked areas, ponding and previous repairs noted. Recommend further evaluation/repair by qualified roofing contractor(s).



ROOFING:



ROOFING:



ROOFING:



ROOFING:

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



National Property Inspections

Commercial Sample-Homewood, IL, IL

3 EXTERIOR SURFACE

Exterior Wall Finish

Exterior Electrical Outlets

FAIR

POOR

Several areas around building had loose/deteriorated seal, cracks or holes. Roots/vines stuck in

All exterior outlets inoperable and GFCI did not trip under fault conditions.

All outlets did not have a weather cap that allows long term fixtures to be plugged in while cap is closed. Recommend replacing with a weather cap cover that accommodates plug.


Recommend further evaluation/repair by qualified electrician(s).




EXTERIOR SURFACE:



EXTERIOR SURFACE:



EXTERIOR SURFACE: Inoperable.



EXTERIOR SURFACE:

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



National Property Inspections

Commercial Sample-Homewood, IL, IL

4 PARAPET WALL SYSTEM

Exterior Finish FAIR

Ponding/possible leaks above entrance and other areas. Recommend further evaluation/repair by qualified contractor(s).



PARAPET WALL SYSTEM:



PARAPET WALL SYSTEM:

Inspection Date: Inspector: Eddie Restani 11/14/2022 Inspector Phone: 312-771-1293

450.012272 Expires: 11/30/2024

Email:



National Property Inspections

Commercial Sample-Homewood, IL, IL

5 FENESTRATION SYSTEMS

POOR

Most thermal windows around the building were fogged due to loss of thermal seal. Recommend further evaluation/repair by qualified window contractor(s).



FENESTRATION SYSTEMS:



FENESTRATION SYSTEMS:



FENESTRATION SYSTEMS:



FENESTRATION SYSTEMS:

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



National Property Inspections

Commercial Sample-Homewood, IL, IL

6 ELECTRICAL 1

Service POOR

Exterior service exposed wires and cement settling.

Exposed wires interior.

Recommend further evaluation/repair by qualified electrical contractor(s).



ELECTRICAL 1:





ELECTRICAL 1:

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



National Property Inspections

Commercial Sample-Homewood, IL, IL

7 WATER HEATER 1 FAIR

Possible asbestos pipes above water heater. Recommend further evaluation/repair by qualified contractor(s).



WATER HEATER 1:

8 HEATING VI

Operation POOR

Unit inoperable.

Recommend further evaluation/repair by qualified HVAC contractor(s).



HEATING VI:

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



National Property Inspections

Commercial Sample-Homewood, IL, IL

9 HEATING VII

Operation FAIR

Rated fair due to age. Unit functional at time of inspection.



HEATING VII:

10 HVAC FAIR

Rated marginal due to age of unit. Budget for eventual replacement. A/C unit should not be tested in cool mode with temperature below 65 degrees for fear of damaging compressor. Recommend checking when ambient air is warmer. The temperature splits could not be properly tested with the low temperatures, even if it was safe to operate.

11 COOLING V FAIR

Rated fair due to age of unit. Budget for eventual replacement.

A/C unit should not be tested in cool mode with temperature below 65 degrees for fear of damaging compressor. Recommend checking when ambient air is warmer. The temperature splits could not be properly tested with the low temperatures, even if it was safe to operate.

Inspection Date: Insp 11/14/2022 Insp


Inspector: Eddie Restani Inspector Phone: 312-771-1293

Email:



National Property Inspections

Commercial Sample-Homewood, IL, IL



COOLING V:

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:




National Property Inspections

Commercial Sample-Homewood, IL, IL

12 ROOMS

Windows and sill POOR

Peeling paint, inoperable windows and moisture present. Recommend further evaluation/repair by qualified contractor(s).





ROOMS: Moisture.

F (FAIR)

Average condition for the building system evaluated, taking into consideration factors of age and design. Some short term or immediate maintenance or repairs are recommended to return the system to a good condition.

P (POOR)

Below-average condition for the building system evaluated, taking into consideration factors of age and design. Immediate repair, significant work or replacement is anticipated to return the building system to a good or fair condition.

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email: