

National Property Inspections

Sample: 3/2 Home



Monday, November 14, 2022 Inspector Eddie Restani 312-771-1293

450.012272 Expires: 11/30/2024

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



National Property Inspections

Sample: 3/2 Home

			AC	C MAR	NI	NP	RR
ROOFING			5	1 🗆			
Age: Undetermined Year(s)	Design Life: 20 Year(s)		·	•	•		
☑ Ladder at Eaves	☑Visual From Ground	☑ Walked On	✓Aspha	lt / Com	positio	on	

Comments:

There were no active leaks noted on day of inspection. Recommend monitoring for future deterioration and repair/replace as required.

Leaks not always detectable.



Roofing:



Roofing:



Roofing:



Roofing:

Inspection Date: Inspector: Eddie Restani Email:



National Property Inspections

Sample:	3/2 Home
---------	-----------------

	ACC	MAR	NI	NP	RR
CHIMNEY	V				

☑ Brick / Masonry ☑ General Deterioration

Comments:

Chimney(s) appeared in good condition with rain cap(s) present.

Flue not inspected. Annual cleaning is recommended.



Chimney:

GARAGE/CARPORT

☑ Recommend Repairs

☑1 Car	☑ Attached	☑ Cracked	☐ General Deterioration				
☑Obscured / Limited V	View						
			ACC	MAR	NI	NP	RR
FLOOR/WALLS/CEILIN	NG/ELECTRICAL		☑				
ROOF			I				
SIDING/TRIM			Ø				
LADDER							Ø

Comments:

Pull down ladder doesn't reach floor.

Recommend further evaluation/repair by qualified contractor(s).

Inspection Date: Inspector: Eddie Restani Email:



National Property Inspections

Sample: 3/2 Home



Garage/Carport: caulk/seal



Garage/Carport:



Garage/Carport: caulk/seal



Garage/Carport:

LAUNDRY FACILITIES

☑ Recommend Repairs

Location: Lower Level					
	ACC	MAR	NI	NP	RR
UTILITY HOOKUPS			V		
DRYER VENTS			Ø		
LAUNDRY TUB					Ø
DRAIN			Ø		
GFCI					Ø
WASHER/DRYER					Ø

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



National Property Inspections

Sample: 3/2 Home

Comments:

Washer/dryer unplugged.

Laundry tub doesn't drain properly, when filling one side, the other side fills up and vice-versa.

Outlet(s) in laundry area not GFCI (Ground Fault Circuit Interrupter) protected for safe use.

Recommend further evaluation/repair by qualified contractor(s).



Laundry Facilities:



Laundry Facilities: filling writher side fills other side



Laundry Facilities:

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



National Property Inspections

Sample: 3/2 Home

HEATING ☑ Monitor Condition ☑ Recommend Repairs							
Brand: Heil	Age: 21 Year(s)	Design Life: 15-20 Year(s)	SerialNo:	197022	9627		
☑Gas	☑Beyond Design Life	☑ Forced Air					
			ACC	MAR	NI	NP	RR
OPERATION				Ø			
ABOVE GROUND STORA	AGE TANKS					Ø	
HUMIDIFIER					Ø		
OPEN PUNCH OUTS							V

Comments:

Rated marginal due to age. Unit functional at time of inspection. Unit appears to be 21YO.

Open punch outs noted.

Recommend further evaluation/repair by qualified contractor(s).

Heat Exchanger - Unable to detect cracks/holes without dismantling unit.







Heating:

Inspection Date: Inspector: Eddie Restani Email:



National Property Inspections

Sample: 3/2 Home

	☑ Monitor Condition					
KITCHEN/BREAKFAST	☑ Recommend Repairs	ACC	MAR	NI	NP	RR
CEILINGS		☑				
WALL(S)		Ø				
WINDOWS/TRIM		Ø				
WINDOW SCREENS		Ø				
FLOOR/FINISH		Ø				
INTERIOR DOORS/HARDWARE		Ø				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)		Ø				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST	RECOMMENDED.)	Ø				
HEAT/AIR DISTRIBUTION		☑				
COUNTERTOPS/CABINETS		Ø				
SINK/FAUCET			Ø			
EXHAUST FAN		Ø				
STOVE TOP/OVEN		Ø				
STOVE ANTI-TIP BRACKET						Ø
WATER PRESSURE/FLOW/DRAINAGE		Ø				
DISHWASHER/CROSS FLOW PROTECTION					Ø	
REFRIGERATOR			Ø			
MICROWAVE					Ø	
GARBAGE DISPOSAL					Ø	

Comments:

No anti-tip device present. An anti-tip device is installed on the floor or wall and locks down one of the stove legs, to prevent the stove from tipping over while pushing down on open oven door.

Faucet hot/cold reversed.

Water leaks.

Recommend further evaluation/repair by qualified contractor(s).

Inspection Date: Inspector: Eddie Restani Email:



National Property Inspections

Sample: 3/2 Home



Kitchen/Breakfast:



Kitchen/Breakfast: drips



Kitchen/Breakfast: h/c rev



Kitchen/Breakfast:



Kitchen/Breakfast:



Kitchen/Breakfast: lower level

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



National Property Inspections

Sample: 3/2 Home

		ACC	MAR	NI	NP	RR
STAIRS / RAILINGS	Recommend Repairs					Ø

☑Missing Hand Rail ☑Tripping Hazard

Comments:

Current standards require handrails to terminate into the wall to prevent chance of tripping.

Handrails are required for stairs that have over 3 risers.

Light inoperative.

Recommend further evaluation/repair by qualified contractor(s).



Stairs / Railings:



Stairs / Railings:



Stairs / Railings:

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



National Property Inspections

Sample: 3/2 Home

Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

1 GARAGE/CARPORT

Ladder REPAIR/REPLACE

Pull down ladder doesn't reach floor.

Recommend further evaluation/repair by qualified contractor(s).



GARAGE/CARPORT:

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



National Property Inspections

Sample: 3/2 Home

2 LAUNDRY FACILITIES

Laundry Tub

GFCI

Washer/Dryer

REPAIR/REPLACE REPAIR/REPLACE REPAIR/REPLACE

Washer/dryer unplugged.

Laundry tub doesn't drain properly, when filling one side, the other side fills up and vice-versa.

Outlet(s) in laundry area not GFCI (Ground Fault Circuit Interrupter) protected for safe use.

Recommend further evaluation/repair by qualified contractor(s).



LAUNDRY FACILITIES:



LAUNDRY FACILITIES:



LAUNDRY FACILITIES: filling writher side fills other side

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



National Property Inspections

Sample: 3/2 Home

3 HEATING

Operation

MARGINAL

Open Punch Outs

REPAIR/REPLACE

Rated marginal due to age. Unit functional at time of inspection. Unit appears to be 21YO.

Open punch outs noted.

Recommend further evaluation/repair by qualified contractor(s).



HEATING:

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



National Property Inspections

Sample: 3/2 Home

4 KITCHEN/BREAKFAST

Sink/Faucet MARGINAL

Stove Anti-Tip Bracket REPAIR/REPLACE Refrigerator

No anti-tip device present. An anti-tip device is installed on the floor or wall and locks down one of the stove legs, to prevent the stove from tipping over while pushing down on open oven door.

Faucet hot/cold reversed.

Water leaks.

Recommend further evaluation/repair by qualified contractor(s).



KITCHEN/BREAKFAST:



KITCHEN/BREAKFAST: h/c rev



KITCHEN/BREAKFAST: drips



KITCHEN/BREAKFAST: lower level

Inspection Date: 11/14/2022

Inspector: Eddie Restani Inspector Phone: 312-771-1293 Email:

450.012272 Expires: 11/30/2024

MARGINAL



National Property Inspections

Sample: 3/2 Home

5 STAIRS / RAILINGS

REPAIR/REPLACE

Current standards require handrails to terminate into the wall to prevent chance of tripping.

Handrails are required for stairs that have over 3 risers.

Light inoperative.

Recommend further evaluation/repair by qualified contractor(s).



STAIRS / RAILINGS:



STAIRS / RAILINGS:



STAIRS / RAILINGS:

MAR (MARGINAL)

The item/system was marginally acceptable. It performed its designed function at the time of the inspection. However, due to age and/or deterioration, it will likely require early repair or replacement.

RR (REPAIR/REPLACE)

The item/system failed to operate/perform its intended function, was structurally deficient, was unsafe or was hazardous at the time of the inspection.

Inspection Date: Inspector: Eddie Restani Email: