

## **National Property Inspections**

### Sample-Townhouse



Monday, November 14, 2022 Inspector Eddie Restani 312-771-1293

450.012272 Expires: 11/30/2024

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



## **National Property Inspections**

### Sample-Townhouse

# DECKS / BALCONY ACC MAR NI NP RR DECKS / BALCONY

☑ Wood ☑ General Deterioration

#### Comments:

All exterior areas such as the deck/balcony are the responsibility of the HOA (Home Owners Association). Any areas of concern may need to be addressed with the HOA.

Limited inspection of deck due to snow cover. Visible areas appeared acceptable, with general deterioration and weather damage. Recommend further evaluation when snow has melted. Regular wood treatment maintenance should be done to preserve remaining life expectancy of construction materials.



Decks / Balcony:





Decks / Balcony:

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



## **National Property Inspections**

### Sample-Townhouse

	ACC	MAR	NI	NP	RR
FLASHING/VALLEYS	Ø				

☑ Composition / Membrane ☑ Metal ☑ General Deterioration

#### Comments:

Roof and valley flashings believed to be maintained by the HOA (Home Owners Association). Any areas of concern may need to be addressed with the HOA.

Limited visibility due to snow cover. Recommend re-inspection after snow is gone.



Flashing/Valleys:



Flashing/Valleys:



Flashing/Valleys:



Flashing/Valleys:

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



## **National Property Inspections**

### Sample-Townhouse

		ACC	MAR	NI	NP	RR
GUTTERS/DOWN SPOUTS	Recommend Repairs					Ø

✓Aluminum

☑ Missing Extension / Splash Block

#### Comments:

Missing extensions at downspouts. Recommend installing downspout extensions to divert water 4 to 6 feet away from the foundation.

Limited observation due to snow cover.



Gutters/Down Spouts:



Gutters/Down Spouts:



Gutters/Down Spouts:

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



## **National Property Inspections**

### Sample-Townhouse

### **GARAGE/CARPORT**

☑2 Cars	☑ Attached	☐ General Deterioration	☑Obscure	☑ Obscured / Limited View			
			ACC	MAR	NI	NP	RR
FLOOR/WALLS/CEILING/ELECTRICAL		Ø					
ROOF			Ø				
SIDING/TRIM			Ø				

#### Comments:

At time of inspection, the garage/carport and all related components were acceptable.



Garage/Carport:



Garage/Carport:



Garage/Carport:

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



## **National Property Inspections**

### Sample-Townhouse

### Attic / Roof

Method of Inspection 
☑ Visual from Access

#### ATTIC FRAMING/SHEATHING

ACC MAR NI NP RR

☑ Plywood / Panel Board / OSB ☑ Trusses

#### Comments:

The attic was inspected from the attic access opening only due to inadequate headroom and/or no floor. Defects may not have been visible.

#### Leaks not always detectable.



Attic Framing/Sheathing:



Attic Framing/Sheathing:



Attic Framing/Sheathing:

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



## **National Property Inspections**

### Sample-Townhouse

#### Interior Foundation

Foundation Type 

☑ Basement

#### INTERIOR FOUNDATION

ACC	MAR	NI	NP	RR
Ø				

☑ General Deterioration

☑ Limited Observation

#### Comments:

All visible interior foundation walls appeared to be in acceptable condition with no apparent major defects (settlement, cracking, bowing, movement, or moisture issues) noted at time of inspection. General deterioration of construction materials only.

Limited visibility due to insulation cover.



Interior Foundation:



Interior Foundation:



Interior Foundation:

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



## **National Property Inspections**

### Sample-Townhouse

#### **UNDER FLOOR FRAMING & SUPPORT**

☑ General Deterioration

	ACC	MAR	NI	NP	RR
BEAMS	Ø				
JOISTS	Ø				
POSTS	Ø				
PIERS			V		

#### Comments:

Where visible, framing and support was in good condition.



Under Floor Framing & Support:



Under Floor Framing & Support:



Under Floor Framing & Support:

Inspection Date: Inspector: Eddie Restani Email:



## **National Property Inspections**

### Sample-Townhouse

#### ELECTRICAL RANDOM SAMPLE

#### **SERVICE SIZE (Main Panel)** ☑ Brand: Eaton ☑ Main Disconnect Location: Lower Level ☑ 120 / 240 Volt (Nominal) **☑** 200 AMP ACC MAR NI NP RR SERVICE $\overline{\mathbf{V}}$ ENTRANCE CABLE $\overline{\mathbf{V}}$ **PANEL** $\overline{\mathbf{V}}$ SUB-PANEL $\checkmark$ BRANCH CIRCUITS $\overline{\mathbf{V}}$ BONDING/GROUNDING $\overline{\mathbf{V}}$ GFCI(IN PANEL)\* $\overline{\mathbf{A}}$ ARC FAULT $\overline{\mathbf{V}}$ SMOKE DETECTORS\* $\overline{\mathbf{V}}$ CLOSETS $\checkmark$

#### Comments:

BREAKERS

Electrical acceptable at time of inspection.

#### \*Smoke Detectors / GFCI's checked with test button only. Monthly Test Recommended.







 $\overline{\mathbf{V}}$ 

Electrical Random Sample:

Inspection Date: Inspector: Eddie Restani Email:



## **National Property Inspections**

### Sample-Townhouse

PLUMBING					
Water Service					
☑ Water Public					
Sewage Service					
☑ Sewage Public					
☐ General Deterioration					
	ACC	MAR	NI	NP	RR
SUPPLY	Ø				
DRAINS	☑				
EJECTOR PUMP	Ø				
VENTS	$\square$				

#### Comments:

No defects were found pertaining to the main plumbing system.

Main utility line, septic systems and gray water systems are excluded from this Inspection.







Plumbing:

Inspection Date: Inspector: Eddie Restani Email:



## **National Property Inspections**

#### Sample-Townhouse



Plumbing:

#### HEATING

11211110							
Brand: Carrier	Age: 3 Year(s)	Design Life: 15-20 Year(s)	SerialNo: 1619A60478				
☑Gas	☑ Forced Air						
			ACC	MAR	NI	NP	RR
OPERATION							
ABOVE GROUND STOR.	AGE TANKS					V	
HUMIDIFIER					V		

#### Comments:

Furnace was running properly at time of inspection. Heat distribution was acceptable with no problems to report. It is important that the furnace be properly maintained for efficiency and greater life span. Recommend a yearly maintenance program be set up with a local heating company to service and clean the furnace. This could greatly improve the life span of unit.


Heat Exchanger - Unable to detect cracks/holes without dismantling unit.

Inspection Date: Inspector: Eddie Restani Email:



## **National Property Inspections**

### Sample-Townhouse







Heating:

Inspection Date: Inspector: Eddie Restani

11/14/2022 Inspector Phone: 312-771-1293 450.012272 Expires: 11/30/2024

Email:



## **National Property Inspections**

### Sample-Townhouse

KITCHEN/BREAKFAST	ACC	MAR	NI	NP	RR
CEILINGS	Ø				
WALL(S)	$\overline{\mathbf{A}}$				
WINDOWS/TRIM	V				
WINDOW SCREENS	$\square$				
FLOOR/FINISH	$\square$				
INTERIOR DOORS/HARDWARE	$\square$				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST RECOMMENDED.)	Ø				
HEAT/AIR DISTRIBUTION	Ø				
COUNTERTOPS/CABINETS	Ø				
SINK/FAUCET	Ø				
EXHAUST FAN	Ø				
STOVE TOP/OVEN	Ø				
STOVE ANTI-TIP BRACKET	Ø				
WATER PRESSURE/FLOW/DRAINAGE	$\square$				
DISHWASHER/CROSS FLOW PROTECTION	Ø				
REFRIGERATOR	Ø				
MICROWAVE	$\square$				
GARBAGE DISPOSAL	Ø				

#### Comments:

All components in kitchen were acceptable at time of inspection.

Inspection Date: Inspector: Eddie Restani Email:



## **National Property Inspections**

### Sample-Townhouse



Kitchen/Breakfast:



Kitchen/Breakfast:



Kitchen/Breakfast:

Inspection Date: 11/14/2022

Inspector: Eddie Restani

Inspector Phone: 312-771-1293

Email:



## **National Property Inspections**

### Sample-Townhouse

## **Summary**

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

#### 1 GUTTERS/DOWN SPOUTS

REPAIR/REPLACE

Missing extensions at downspouts. Recommend installing downspout extensions to divert water 4 to 6 feet away from the foundation.

Limited observation due to snow cover.



**GUTTERS/DOWN SPOUTS:** 



**GUTTERS/DOWN SPOUTS:** 

MAR (MARGINAL)

The item/system was marginally acceptable. It performed its designed function at the time of the inspection. However, due to age and/or deterioration, it will likely require early repair or replacement.

RR (REPAIR/REPLACE)

The item/system failed to operate/perform its intended function, was structurally deficient, was unsafe or was hazardous at the time of the inspection.

Inspection Date: Inspector: Eddie Restani Email: