

National Property Inspections

Pressgrove Sample Report, 987 Main St, Anywhere, ar, 12345





Friday, May 5, 2023
Inspector
Ronald Jeremy Pressgrove
501-733-3981
jeremy.pressgrove@npiinspect.com

Inspection Date: 05/05/2023

Inspector: Ronald Jeremy Pressgrove Inspector Phone: 501-733-3981



National Property Inspections

Pressgrove Sample Report, 987 Main St, Anywhere, ar, 12345

GENERAL INFORMATION

GENERAL CONDITIONS AT TIME OF INSPECTION:

Property Occupied:	Yes	Temperature: 60 Weather:	F	
Estimated Age Of Property: Property Faces: □ North	40 Year(s) \square South \square East \square West	☑ Overcast	☑ Rain	
Type of Property: ☑ Single-Family		Soil Conditions : ☑ Damp/Wet		
Primary Construction:		Persons Present :		
☑ Brick ☑	J Wood			

DEFINITIONS:

Below are listed the definitions used throughout the report to describe each feature of the property.

ACC (ACCEPTABLE) The item/system was performing its intended function at the time of the inspection.

MAR (MARGINAL) The item/system was marginally acceptable. It performed its designed function at the time of the

inspection. However, due to age and/or deterioration, it will likely require early repair or replacement.

NI (NOT INSPECTED) The item/system was not inspected due to safety concerns, inaccessibility and/or concealment or seasonal

conditions and no representations of whether or not it was functioning as intended were made.

NP (NOT PRESENT) The item/system does not exist or was visually concealed at the time of the inspection.

DEF (DEFICIENT)The item/system failed to operate/perform its intended function, was structurally deficient, was unsafe or

was hazardous at the time of the inspection.

SCOPE OF THE INSPECTION:

We wish to remind you that every property requires a certain amount of ongoing maintenance: drains sometimes clog, gutters, downspouts and the grading around the property must be properly maintained to help prevent water intrusion in to the basement or crawlspace; roofs, furnaces, air conditioners and other components require regular maintenance and inspection. This property will be no exception and we strongly suggest that you both expect and budget for regular maintenance/repairs.

The following report is based on visual inspection of the readily accessible areas of this property and on a random sampling of like items, <u>not every item was or could be inspected</u>. Please read the entire report carefully, ask your inspector any questions you might have <u>and obtain estimates or discuss noted items with a contractor before</u> closing.

Inspection Date: Inspector: Ronald Jeremy Pressgrove Email: jeremy.pressgrove@npiinspect.com

05/05/2023 Inspector Phone: 501-733-3981



National Property Inspections

Pressgrove Sample Report, 987 Main St, Anywhere, ar, 12345

PORCHES / STOOPS DEFICIENT

Observed no screen on door to screened porch area

Damage to screen porch in two places. Recommend repair by handyman or contractor



PORCHES / STOOPS:

PATIO MARGINAL

Roof covering over deck leaked at seams and appears to be negatively sloped towards the home. The home owner also reported leaking and negative slope. Recommend repair by qualified professional

Patio has some minor cracking present throughout (less than 1/4 inch). Recommend filling the cracks with an approved concrete sealant to prevent any future water damage/deterioration.



PATIO: Roof covering leaks at seams and slopes towards home

Inspection Date: 05/05/2023

Inspector: Ronald Jeremy Pressgrove Inspector Phone: 501-733-3981



National Property Inspections

Pressgrove Sample Report, 987 Main St, Anywhere, ar, 12345

GARAGE/CARPORT

Floor/Walls/Ceiling/Electrical

MARGINAL

After testing electric receptacle(s) with a tester and pushing the test button(s), it was determined that the wall receptacle(s) were not GFCI protected. Receptacles in a carport/garage have been required to be GFCI protected since 1978.

GARAGE PEDESTRIAN DOOR INTO HOUSE

MARGINAL

Observed a hollow core (interior door) between garage and home. Door from garage into house should be metal or solid core fire rated door. Recommend upgrading door with installation from qualified contractor or handyman.

ELECTRICAL

Panel

MARGINAL

GFCI(in panel)*

DEFICIENT

Recommend complete labeling of panel and all circuits by licensed electrician

GFCI not present, it is recommended in exterior, garage, kitchen. GFCI (Ground Fault Circuit Interrupter) outlets help reduce the risk of electrical shock. GFCIs detect a change in current between the "hot" and "neutral" wires and trip the circuit, shutting off power to the circuit.



ELECTRICAL:

Inspection Date: 05/05/2023

Inspector: Ronald Jeremy Pressgrove Inspector Phone: 501-733-3981



National Property Inspections

Pressgrove Sample Report, 987 Main St, Anywhere, ar, 12345

	ACC	MAR	NI	NP	DEF
ATTIC FRAMING/SHEATHING	Ø				

☑ Rafters ☑ Trusses

Comments:

The attic interior was visually examined for leaks and/or water stains. All the framing and sheathing that was visible from the attic was acceptable at time of inspection. No cracked trusses or rafters, stains, or leaks were observed at time of inspection.

Leaks not always detectable.



Attic Framing/Sheathing:



Attic Framing/Sheathing:



Attic Framing/Sheathing:



Attic Framing/Sheathing:



National Property Inspections

Pressgrove Sample Report, 987 Main St, Anywhere, ar, 12345



Attic Framing/Sheathing:



Attic Framing/Sheathing:



Attic Framing/Sheathing:

ATTIC VENTILATION

ACC	MAR	NI	NP	DEF
\square				

Comments:

At time of inspection ventilation was acceptable.



National Property Inspections

Pressgrove Sample Report, 987 Main St, Anywhere, ar, 12345



Attic Ventilation:



ACC MAR

 $\overline{\mathbf{V}}$

DEF

NP

Attic Ventilation:

ATTIC INSULATION

☑Blanket

Comments:

Blanket insulation was observed in attic and appears to be an adequate depth at the time of the inspection



Attic Insulation:

Inspection Date: 05/05/2023

Inspector: Ronald Jeremy Pressgrove Inspector Phone: 501-733-3981



FLOOR/SLAB

Pressgrove Property Inspection DBA

National Property Inspections

Pressgrove Sample Report, 987 Main St, Anywhere, ar, 12345

☑ Concrete						
Comments: Foundation construction included a slab-on-grad that typically, most of the foundation and slab are that portion of the foundation visible at the home was inspected.	e hidden underground or by interior floor co	verings	s. Wh	ere p	ossib	ole,
ELECTRICAL	✓ Monitor Condition✓ Recommend Repairs					
SERVICE SIZE (Main Panel)						
☑ Main Disconnect Location: Garage	☑ 120 / 240 Volt (Nominal)					
		ACC	MAR	NI	NP	DEF
SERVICE		Ø				
ENTRANCE CABLE		4				
PANEL			Ø			
SUB-PANEL					Ø	
BRANCH CIRCUITS		Ø				
BONDING/GROUNDING						
GFCI(IN PANEL)*						Ø
ARC FAULT					V	
SMOKE DETECTORS*						

Comments:

AFCI (Arc Fault Circuit Interrupter) breaker outlets and breakers were not present. AFCI outlets were not a requirement when the home was constructed, however, the installation of AFCI outlets/breakers is recommended. Recommend complete labeling of panel and all circuits by licensed electrician

GFCI not present, it is recommended in exterior, garage, kitchen. GFCI (Ground Fault Circuit Interrupter) outlets help reduce the risk of electrical shock. GFCIs detect a change in current between the "hot" and "neutral" wires and trip the circuit, shutting off power to the circuit.

*Smoke Detectors / GFCI's checked with test button only. Monthly Test Recommended.

Inspection Date: Inspector: Ronald Jeremy Pressgrove Email: jeremy.pressgrove@npiinspect.com

05/05/2023 Inspector Phone: 501-733-3981

ACC MAR

 $\overline{\Box}$

NI

NP DEF



National Property Inspections

Pressgrove Sample Report, 987 Main St, Anywhere, ar, 12345



Electrical:



Electrical:



Electrical:



Electrical:



Electrical:



Electrical:

Inspection Date: 05/05/2023

Inspector: Ronald Jeremy Pressgrove Inspector Phone: 501-733-3981



National Property Inspections

Pressgrove Sample Report, 987 Main St, Anywhere, ar, 12345

PLUMBING	☑ Monitor Condition					
Water Service						
☑ Water Public	☑ Shut Off Location: exterior front					
Sewage Service						
☑ Sewage Public						
		ACC	MAR	NI	NP	DEF
SUPPLY		Ø				
DRAINS			Ø			
EJECTOR PUMP					Ø	
VENTS PVC		Ø				

Comments:

Observed a clean out with a broken cap. Recommend replacement or repair of cap to prevent debris from entering sewage line from the yard

Main utility line, septic systems and gray water systems are excluded from this Inspection.



Plumbing:



Plumbing: broken cap, replacement or repair



National Property Inspections

Pressgrove Sample Report, 987 Main St, Anywhere, ar, 12345



Plumbing: main disconnect

WATER HEATER

Brand: AO Smith

☑ Electric

Comments:

The operation and installation of the water heater appeared to be satisfactory at time of inspection. Routine maintenance such as draining the water heater could prolong its lifespan. Always refer to manufacturer's specifications before doing any maintenance on your water heater.



Water Heater:



ACC MAR

 $\overline{\mathbf{V}}$

NI

NP DEF

Water Heater:

Inspection Date: 05/05/2023

Inspector: Ronald Jeremy Pressgrove Inspector Phone: 501-733-3981



National Property Inspections

Pressgrove Sample Report, 987 Main St, Anywhere, ar, 12345



Water Heater:



Water Heater:

LAUNDRY FACILITIES

Location: Laundry room

	ACC	MAR	NI	NP	DEF
UTILITY HOOKUPS	Ø				
DRYER VENTS	Ø				
LAUNDRY TUB	Ø				
DRAIN	Ø				

Comments:

All components in laundry room were acceptable at time of inspection.



Laundry Facilities:

Inspection Date: 05/05/2023

Inspector: Ronald Jeremy Pressgrove Inspector Phone: 501-733-3981



National Property Inspections

Pressgrove Sample Report, 987 Main St, Anywhere, ar, 12345

HEATING DISTRIBUTION ☑ Ductwork ACC MAR DEF DISTRIBUTION $\overline{\mathbf{V}}$ **BLOWER** $\overline{\mathbf{Q}}$ CONTROLS/THERMOSTAT (CALIBRATIONS/TIMED FUNCTIONS NOT CHECKED.) $\overline{\mathbf{V}}$ CIRCULATOR PUMP $\sqrt{}$ Comments:

COOLING

Brand: Trane Age: < 5 Year(s)

Comments:

The air conditioning system responded to the controls and appeared to operate in a satisfactory manner.







ACC MAR

 $\sqrt{}$

NP

DEF

Cooling:

Inspection Date: 05/05/2023

Inspector: Ronald Jeremy Pressgrove Inspector Phone: 501-733-3981



National Property Inspections

Pressgrove Sample Report, 987 Main St, Anywhere, ar, 12345





Cooling

KITCHEN	☑ Recommend Repairs A	ACC	MAR	NI	NP	DEF
CEILINGS		Ø				
WALL(S)		☑				
WINDOWS/TRIM		☑				
WINDOW SCREENS		Ø				
FLOOR/FINISH		☑				
INTERIOR DOORS/HARDWARE		☑				
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)		☑				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST	RECOMMENDED.)					Ø
HEAT/AIR DISTRIBUTION		☑				
COUNTERTOPS/CABINETS		☑				
SINK/FAUCET		☑				
EXHAUST FAN		Ø				
STOVE TOP/OVEN		☑				
STOVE ANTI-TIP BRACKET		☑				
WATER PRESSURE/FLOW/DRAINAGE		☑				
DISHWASHER/CROSS FLOW PROTECTION		☑				
REFRIGERATOR		☑				
MICROWAVE		Ø				
GARBAGE DISPOSAL		☑				

Inspection Date: 05/05/2023

Inspector: Ronald Jeremy Pressgrove Inspector Phone: 501-733-3981