

## **National Property Inspections**

### **Sample Report**



Tuesday, June 6, 2023
Inspector
JC Manalo
909-728-3556
julius.manalo@npiinspect.com



## **National Property Inspections**

### Sample Report

#### **GENERAL INFORMATION**

#### GENERAL CONDITIONS AT TIME OF INSPECTION:

Property Occupied :	Yes	Temperature: 75 F Weather:
<b>Estimated Age Of Property:</b>	Year(s)	Treatment :
<b>Property Faces:</b> ☑ North	□ South □ East □ West	
Type of Property:		Soil Conditions :
☑ Single-Family		☑ Dry
Primary Construction :		Persons Present :
☑ Wood		☑ Buyer

#### **DEFINITIONS:**

Below are listed the definitions used throughout the report to describe each feature of the property.

ACC (ACCEPTABLE) The item/system was performing its intended function at the time of the inspection.

MAR (MARGINAL) The item/system was marginally acceptable. It performed its designed function at the time of the

inspection. However, due to age and/or deterioration, it will likely require early repair or replacement.

NI (NOT INSPECTED) The item/system was not inspected due to safety concerns, inaccessibility and/or concealment or seasonal

conditions and no representations of whether or not it was functioning as intended were made.

**NP (NOT PRESENT)** The item/system does not exist or was visually concealed at the time of the inspection.

**DEF (DEFICIENT)**The item/system failed to operate/perform its intended function, was structurally deficient, was unsafe or

was hazardous at the time of the inspection.

### **SCOPE OF THE INSPECTION:**

We wish to remind you that every property requires a certain amount of ongoing maintenance: drains sometimes clog, gutters, downspouts and the grading around the property must be properly maintained to help prevent water intrusion in to the basement or crawlspace; roofs, furnaces, air conditioners and other components require regular maintenance and inspection. This property will be no exception and we <a href="strongly suggest that you both expect and budget for regular maintenance/repairs.">strongly suggest that you both expect and budget for regular maintenance/repairs.</a>

The following report is based on visual inspection of the readily accessible areas of this property and on a random sampling of like items, <u>not every item was or could be inspected</u>. Please read the entire report carefully, ask your inspector any questions you might have <u>and obtain estimates or discuss noted items with a contractor before closing</u>.

Inspection Date: Inspector: JC Manalo Email: julius.manalo@npiinspect.com

06/06/2023 Inspector Phone: 909-728-3556



## **National Property Inspections**

### Sample Report

### **Summary**

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

**FENCES / GATES** MARGINAL

Several areas of wood rot observed on the wood fence. Correct as necessary.

FLASHING/VALLEYS MARGINAL

Minor debris accumulation in one or more valleys. Debris should be cleared to allow for proper runoff. Plumbing boot on vent has deteriorated and may allow for water intrusion. Repair or Replace as necessary.

**COOLING** MARGINAL

Due to the age of unit, be aware that it could need repairs or replacing at any time.

MAR (MARGINAL)

The item/system was marginally acceptable. It performed its designed function at the time of the inspection. However, due to age and/or deterioration, it will likely require early repair or replacement.

**DEF (DEFICIENT)** 

The item/system failed to operate/perform its intended function, was structurally deficient, was unsafe or was hazardous at the time of the inspection.

Inspector: JC Manalo Inspection Date: Email: julius.manalo@npiinspect.com Inspector Phone: 909-728-3556

06/06/2023



## **National Property Inspections**

### **Sample Report**

# GRADING / DRAINAGE ACC MAR NI NP DEF OF COMMAR NI NP DEF

☑ Positive Slope

#### Comments:

Appeared to be a positive slope around all sides of the home.



Grading / Drainage:



Grading / Drainage:



Grading / Drainage:



Grading / Drainage:

Inspection Date: 06/06/2023

Inspector: JC Manalo

Inspector Phone: 909-728-3556



## **National Property Inspections**

### **Sample Report**

		ACC	MAR	NI	NP	DEF
FENCES / GATES	☑ Monitor Condition		Ø			

☑ Wood ☑ Wrought Iron ☑ Rotting

#### Comments:

Several areas of wood rot observed on the wood fence. Correct as necessary.



Fences / Gates:



Fences / Gates:



Fences / Gates: Area of wood rot to fence slat.



Fences / Gates:

Inspection Date: 06/06/2023

Inspector: JC Manalo

Inspector Phone: 909-728-3556



## **National Property Inspections**

### **Sample Report**



Fences / Gates:



Fences / Gates:

ROOFING

ACC MAR NI NP DEF

Monitor Condition

Age: 22 Year(s) Design Life: 40-50 Year(s) Layers: 1 80% Visible

#### Comments:

Overall the roof was in acceptable condition with no active leaks noted on day of inspection. Recommend monitoring for future deterioration and repair/replace as required. Solar panels were present on roof, but are not within the scope of the inspection and were not inspected.

#### Leaks not always detectable.



Roofing:



Roofing:

Inspection Date: Inspector: JC Manalo

06/06/2023 Inspector Phone: 909-728-3556



## **National Property Inspections**

### **Sample Report**



Roofing:



Roofing:



Roofing:



Roofing:



Roofing:



Roofing:

Inspection Date: 06/06/2023

Inspector: JC Manalo

Inspector Phone: 909-728-3556



## **National Property Inspections**

### **Sample Report**

		ACC	MAR	NI	NP	DEF
FLASHING/VALLEYS	☑ Monitor Condition					

☑ Filled with Debris ☑ General Deterioration

#### Comments:

Minor debris accumulation in one or more valleys. Debris should be cleared to allow for proper runoff. Plumbing boot on vent has deteriorated and may allow for water intrusion. Repair or Replace as necessary.



Flashing/Valleys:



Flashing/Valleys:

Inspection Date: Inspector: JC Manalo Inspector Phone: 909-728-3556

©1996-2023



## **National Property Inspections**

Sample Report					
	ACC	MAR	NI	NP	DEF
FLOOR/SLAB	$\square$				
☑ Concrete ☑ Obscured / Covered					
Comments: All visible concrete flooring was in good condition at time of inspection with no r Slab on grade. Limited visibility. The concrete floors of the home were covered Where possible, that portion of the foundation between grade and exterior wall	by carpet, tiles and	or flo	or co	overin	ıgs.
ELECTRICAL					
SERVICE SIZE (Main Panel)	<b>-</b>				
☑ Brand: Cutler Hammer ☑ Main Disconnect Location: Exterior Wall	<b>☑</b> 120 / 24	0 Volt	(Non	inal)	
☑ 100 AMP					1
GENTION D		MAR	NI	NP	DEF
SERVICE Underground	☑				
ENTRANCE CABLE  Aluminum					
PANEL Breaker(s) Exterior Wall	V				
SUB-PANEL				Ø	
BRANCH CIRCUITS    ☐ Copper	$\square$				
BONDING/GROUNDING	$\square$				
GFCI(IN PANEL)*	$\square$				
ARC FAULT				V	
SMOKE DETECTORS*	☑				

#### Comments:

Overall, the electrical system was in good condition.

Front cover on panel not clearly labeled to identify what breakers supply what circuits. For additional safety, recommend identification and labeling of all specific breaker functions.

\*Smoke Detectors / GFCI's checked with test button only. Monthly Test Recommended.

Inspection Date: Inspector: JC Manalo Email: julius.manalo@npiinspect.com

06/06/2023 Inspector Phone: 909-728-3556



## **National Property Inspections**

### **Sample Report**



Electrical: Main Panel



Electrical: Main breaker 100 amp



Electrical:



Electrical:



Electrical:



Electrical:

Inspection Date: 06/06/2023

Inspector: JC Manalo

Inspector Phone: 909-728-3556



## **National Property Inspections**

### **Sample Report**

			ACC	MAR	NI	NP	DEF
		Monitor Condition		☑			
Model: CA9048VKD2	Size: 4.0		Age: 24 Y	ear(s)			
	Model: CA9048VKD2 SerialNo: I 9932 25897	Model: CA9048VKD2 Size: 4.0		Model: CA9048VKD2 Size: 4.0 Monitor Condition ☐  Model: CA9048VKD2 Size: 4.0 Age: 24 Yes	Model: CA9048VKD2 Size: 4.0 Monitor Condition □ ☑  Model: CA9048VKD2 Size: 4.0 Age: 24 Year(s)	Model: CA9048VKD2 Size: 4.0 Age: 24 Year(s) □ □ □ □	Model: CA9048VKD2 Size: 4.0 Age: 24 Year(s) □ □ □ □

☑ Electric ☑ Central Air

### Comments:

The air conditioning system responded to the controls and appeared to operate in a satisfactory manner.

Due to the age of unit, be aware that it could need repairs or replacing at any time.



Cooling:



Cooling:

KITCHEN	ACC	MAR	NI	NP	DEF
CEILINGS	Ø				
WALL(S)	Ø				
WINDOWS/TRIM	☑				
WINDOW SCREENS	Ø				
FLOOR/FINISH	Ø				
INTERIOR DOORS/HARDWARE				V	
ELECTRICAL (RANDOM SAMPLING OF OUTLETS, SWITCHES, FIXTURES.)	Ø				
GFCI PROTECTION (CHECKED WITH TEST BUTTON ONLY. MONTHLY TEST RECOMMENDED.)	V				
HEAT/AIR DISTRIBUTION	Ø				
COUNTERTOPS/CABINETS	V				

Inspection Date: Inspector: JC Manalo Email: julius.manalo@npiinspect.com

06/06/2023 Inspector Phone: 909-728-3556



## **National Property Inspections**

#### **Sample Report** SINK/FAUCET $\overline{\mathbf{V}}$ **EXHAUST FAN** $\overline{\mathbf{V}}$ **✓** Gas STOVE TOP/OVEN $\checkmark$ STOVE ANTI-TIP BRACKET $\checkmark$ WATER PRESSURE/FLOW/DRAINAGE $\checkmark$ DISHWASHER/CROSS FLOW PROTECTION $\checkmark$ REFRIGERATOR $\checkmark$ MICROWAVE $\sqrt{}$ GARBAGE DISPOSAL $\checkmark$

#### Comments:

All components in kitchen were acceptable at time of inspection.







Kitchen:

Inspection Date: Inspector: JC Manalo Email: julius.manalo@npiinspect.com
06/06/2023 Inspector Phone: 909-728-3556